



C007678

Date Inspection Started 23 07 25 DAY MO. YR.	Station Number A12345	Station Name The Green Team & Team	City 255	
Date Inspection Completed 23 07 25 DAY MO. YR.	Mechanic Number 107402	Mechanic Signature [Signature]		
Station Phone Number [Blank]				
Date Inspection Expiry 21 07 26 DAY MO. YR.	Vehicle Owner Kenny Sore Thomas 2-2			
Address [Blank]				
City [Blank]		Province [Blank]	Postal Code [Blank]	Phone [Blank]

☐ Pass/Safe Vehicle ☐ Fail/Unsafe Vehicle ☐ Fail/Hazardous	Licence Number CFK6441	Prov. NL	NSC # M011126	Odometer Reading 154155	Odom. Type ☒ km ☐ mi
Vehicle Identification Number 2AKT1156289171276					
Make LH					
Model 1000		Year 2009		Unit # 1002	
☐ Confirmed legible Vehicle Identification Number on vehicle					

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

_____ Truck GVWR _____ KGS ✓ _____ Truck Tractor _____ Trailer _____ Semi-Trailer _____ Bus _____ School Bus _____ Coach Bu

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																																						
X		Section 1 - Power Train: Defects (if any)																																																																																						
X		Section 2 Suspension: Defects (if any)																																																																																						
X	X	Section 3 - Brake Systems: 3H 3A								Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																														
		Defects (if any)								Circle Brake Type																																																																														
		15-60 2H 11 11 11 11 11 11 11 11								<table border="1"> <thead> <tr> <th></th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>Axle</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>ER</td> <td>ER</td> <td>11526</td> <td>11526</td> <td>115</td> <td>115</td> </tr> <tr> <td>2</td> <td>11526</td> <td>11526</td> <td>11526</td> <td>11526</td> <td>115</td> <td>115</td> </tr> <tr> <td>3</td> <td>11526</td> <td>11526</td> <td>11526</td> <td>11526</td> <td>115</td> <td>115</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>									Lining		Drum/Rotor		Stroke		Axle	L	R	L	R	L	R	1	ER	ER	11526	11526	115	115	2	11526	11526	11526	11526	115	115	3	11526	11526	11526	11526	115	115	4							5							Final Measurement																					
	Lining		Drum/Rotor		Stroke																																																																																			
Axle	L	R	L	R	L	R																																																																																		
1	ER	ER	11526	11526	115	115																																																																																		
2	11526	11526	11526	11526	115	115																																																																																		
3	11526	11526	11526	11526	115	115																																																																																		
4																																																																																								
5																																																																																								
Final Measurement																																																																																								
X		Section 4 - Steering: Defects (if any)																																																																																						
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																																						
X		Section 6 - Lamps: Defects (if any)																																																																																						
X		Section 7 - Electrical System: Defects (if any)																																																																																						
X		Section 8 - Body: Defects (if any)																																																																																						
X		Section 9 - Tire & Wheel: Defects (if any)																																																																																						
X		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th></th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>12</td> <td>10</td> <td></td> <td></td> <td>100</td> <td>100</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>11</td> <td>12</td> <td>14</td> <td></td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td>12</td> <td>12</td> <td>20</td> <td>20</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>																Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	12	10			100	100			2	11	12	14		100	100	100	100	3	12	12	20	20	100	100	100	100	4									5								
Axle	Tread Depth				Air Pressure																																																																																			
	Initial		Corrected		Initial		Corrected																																																																																	
	L	R	L	R	L	R	L	R																																																																																
1	12	10			100	100																																																																																		
2	11	12	14		100	100	100	100																																																																																
3	12	12	20	20	100	100	100	100																																																																																
4																																																																																								
5																																																																																								
X		Section 10 - Coupling Devices: Defects (if any)																																																																																						

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not