



HOUSTON TX BRANCH
7045 North Loop East
HOUSTON, TX 77028-
(713)679-2220

Payment terms are 30 days from invoice date unless
otherwise agreed upon in writing. Remit to:
Cummins Southern Plains LLC
PO BOX 772642
Detroit, MI 48277-2642



INVOICE NO

85-250733656

TO PAY ONLINE LOGON TO
customerpayment.cummins.com

BILL TO

PAGE 1 OF 3

*** CHARGE ***

DATE	CUSTOMER ORDER NO.	DATE IN SERVICE	ENGINE MODEL	PUMP NO.	EQUIPMENT MAKE
25-JUL-2025	195730	04-MAY-2013	ISX15 CM2250		KENWORTH
CUSTOMER NO.	SHIP VIA	FAIL DATE	ENGINE SERIAL NO.	CPL NO.	EQUIPMENT MODEL
		15-JUL-2025	79591568	3606	T800
REF. NO.	SALES PERSON	PARTS DISP.	MILEAGE/HOURS	PUMP CODE	UNIT NO.
408200	QP412		461900		

QUANTITY ORDERED	BACK ORDERED	QUANTITY SHIPPED	PART NUMBER	DESCRIPTION	PRODUCT CODE	UNIT PRICE	AMOUNT
------------------	--------------	------------------	-------------	-------------	--------------	------------	--------

OSN/MSN/VIN

1XKDP4EX5DJ358001

**COMPLAINT
CAUSE**

CHECK ENGINE LIGHT AND CUSTOMER STATES IT IS SMOKING
ROOT CAUSE TBD
CSS# 01452220
CONNECTED AND FOUND A AFTERTREATMENT FAULT CODE
SENT CODE TO GUIDANZ
IT HAD ME DO A INJECTOR PERFORMANCE TEST
TEST DID NOT PASS DUE TO THE FUEL SYSTEM NOT BEING STABLE
FOUND THE INJECTOR PERFORMANCE TEST FAIL SOLUTION
STARTED TO TROUBLESHOOT
FOUND THAT 4 INJECTORS ARE BAD 1,2,3,4
BUT I RECOMMEND GOING AHEAD AND REPLACING ALL 6

RESULTS OF RETURN FLOW TEST
RETURN SPECS ARE 420ML
RETURN - 420ML
1 - 300ML
2 - 365ML
3 - 270ML
4 - 312ML
5 - 410ML
6 - 410M

CORRECTION

ADMINISTRATIVE TIME
TECHNICIAN ADMINISTRATIVE TIME - NON-FIELD ACTION SERVICE EVENT
JOB SAFETY ASSESSMENT
ELECTRONIC SERVICE TOOL - OPERATE SIGNATURE ENGINES
TROUBLESHOOTING
COURTESY VISUAL INSPECTION
THANK YOU FOR YOUR BUSINESS
ADMINISTRATIVE TIME
TECHNICIAN ADMINISTRATIVE TIME - NON-FIELD ACTION SERVICE EVENT
JOB SAFETY ASSESSMENT
ELECTRONIC SERVICE TOOL - OPERATE SIGNATURE ENGINES
TROUBLESHOOTING
STEAM CLEAN - SINGLE COMPONENT REPAIR

Billing Inquiries? Call (877)480-6970

APPENDIX A IS ATTACHED AND INCORPORATED HEREIN. IN APPENDIX A THERE ARE
ADDITIONAL CONTRACT TERMS AND CONDITIONS, INCLUDING LIMITATION ON
WARRANTIES AND LIABILITIES WHICH ARE EXPRESSIVELY INCORPORATED HEREIN AND
WHICH PURCHASER ACKNOWLEDGES HAVE BEEN READ, FULLY UNDERSTOOD AND
ACCEPTED.

AUTHORIZED BY (print name) _____ SIGNATURE _____ DATE _____



Sales and Service

HOUSTON TX BRANCH
7045 North Loop East
HOUSTON, TX 77028-
(713)679-2220

Payment terms are 30 days from invoice date unless otherwise agreed upon in writing. Remit to:
Cummins Southern Plains LLC
PO BOX 772642
Detroit, MI 48277-2642



INVOICE NO

85-250733656

TO PAY ONLINE LOGON TO
customerpayment.cummins.com

BILL TO

PAGE 2 OF 3

*** CHARGE ***

DATE	CUSTOMER ORDER NO.	DATE IN SERVICE	ENGINE MODEL	PUMP NO.	EQUIPMENT MAKE
25-JUL-2025		04-MAY-2013	ISX15 CM2250		KENWORTH
CUSTOMER NO.	SHIP VIA	FAIL DATE	ENGINE SERIAL NO.	CPL NO.	EQUIPMENT MODEL
		15-JUL-2025	79591568	3606	T800
REF. NO.	SALES PERSON	PARTS DISP.	MILEAGE/HOURS	PUMP CODE	UNIT NO.
408200	QP412		461900		4.113

QUANTITY ORDERED	BACK ORDERED	QUANTITY SHIPPED	PART NUMBER	DESCRIPTION	PRODUCT CODE	UNIT PRICE	AMOUNT
------------------	--------------	------------------	-------------	-------------	--------------	------------	--------

OSN/MSN/VIN

1XKDP4EX5DJ358001

AIR CLEANER ASSEMBLY R / R - (PACCAR, 041-001) - KENWORTH T800
FUEL INJECTOR PERFORMANCE TEST ENGINE - RUN FUEL INJECTOR PERFORMANCE TEST
INJECTOR - ISOLATION TEST, ALL
INJECTORS - REMOVE AND INSTALL, ALL (COMMON RAIL FUEL SYSTEM)
EGR CROSSOVER TUBE - REMOVE AND INSTALL
AFTERTREATMENT STATIONARY REGENERATION
COURTESY VISUAL INSPECTION
THANK YOU FOR YOUR BUSINESS

COVERAGE

REMARK

CUSTOMER BILLABLE
TROUBLESHOOTING

1	COURTESY INSPECTION	COURTESY INSPECTION				0.00
2	2 3687051	CARRIER,SEAL	CECO	32.41	64.82	
6	6 5579417PX	KIT,INJECTOR	DRC	1,825.64	10,953.84	
6	6 2872161D	INJECTOR, MONARCH RED	CLEAN	337.50	2,025.00	
-6	-6 2872161D	INJECTOR, MONARCH RED	DIRTY	337.50	-2,025.00	
1	1 3104392	GASKET,VALVE COVER	CECO	84.21	84.21	

PARTS:	11,102.87
PARTS COVERAGE CREDIT:	0.00 CR
TOTAL PARTS:	11,102.87
SURCHARGE TOTAL:	0.00
LABOR:	2,541.00
LABOR COVERAGE CREDIT:	0.00 CR
TOTAL LABOR:	2,541.00
MISC.:	0.00
MISC. COVERAGE CREDIT:	0.00 CR

Billing Inquiries? Call (877)480-6970

APPENDIX A IS ATTACHED AND INCORPORATED HEREIN. IN APPENDIX A THERE ARE ADDITIONAL CONTRACT TERMS AND CONDITIONS, INCLUDING LIMITATION ON WARRANTIES AND LIABILITIES WHICH ARE EXPRESSIVELY INCORPORATED HEREIN AND WHICH PURCHASER ACKNOWLEDGES HAVE BEEN READ, FULLY UNDERSTOOD AND ACCEPTED.

AUTHORIZED BY (print name) _____ SIGNATURE _____ DATE _____



Sales and Service

HOUSTON TX BRANCH
7045 North Loop East
HOUSTON, TX 77028-
(713)679-2220

Payment terms are 30 days from invoice date unless
otherwise agreed upon in writing. Remit to:
Cummins Southern Plains LLC
PO BOX 772842
Detroit, MI 48277-2842



INVOICE NO

85-250733656

TO PAY ONLINE LOGON TO
customerpayment.cummins.com

BILL TO

PAGE 3 OF 3

*** CHARGE ***

DATE	CUSTOMER ORDER NO.	DATE IN SERVICE	ENGINE MODEL	PUMP NO.	EQUIPMENT MAKE
25-JUL-2025		04-MAY-2013	ISX15 CM2250		KENWORTH
CUSTOMER NO.	SHIP VIA	FAIL DATE	ENGINE SERIAL NO.	CPL NO.	EQUIPMENT MODEL
		15-JUL-2025	79591566	3606	T800
REF. NO.	SALES PERSON	PARTS DISP.	MILEAGE/HOURS	PUMP CODE	UNIT NO.
408200	QP412		461900		

QUANTITY ORDERED	BACK ORDERED	QUANTITY SHIPPED	PART NUMBER	DESCRIPTION	PRODUCT CODE	UNIT PRICE	AMOUNT
------------------	--------------	------------------	-------------	-------------	--------------	------------	--------

OSN/MSN/VIN

1XKDP4EX5DJ358001

TOTAL MISC.:

0.00

CITY	111.03
LOCAL	111.03
STATE	693.93

Billing Inquiries? Call (877)480-6970

APPENDIX A IS ATTACHED AND INCORPORATED HEREIN. IN APPENDIX A THERE ARE
ADDITIONAL CONTRACT TERMS AND CONDITIONS, INCLUDING LIMITATION ON
WARRANTIES AND LIABILITIES WHICH ARE EXPRESSLY INCORPORATED HEREIN
AND WHICH PURCHASER ACKNOWLEDGES HAVE BEEN READ, FULLY UNDERSTOOD
AND ACCEPTED.

SUB TOTAL: 13,643.87

TOTAL TAX: 915.99

TOTAL AMOUNT: US \$ 14,559.86

AUTHORIZED BY (print name) _____ SIGNATURE _____ DATE _____