

03976763

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Ins.
Box 45064, Regina, S4S 0G7
Winnipeg, MB, R2C 5C7
1-204-985-0920Manitoba
A996601

Date Inspection Started: DAY 07 MO. 07 YR. 25
Date Inspection Completed: DAY 10 MO. 07 YR. 25
Inspection Expiry Date: DAY 31 MO. 07 YR. 26

Station Number: A101111 Station Name: _____ City: _____
Mechanic Number: M87749 Mechanic Signature: _____ Station Phone Number: 825-2121

Vehicle Owner: Circle L Feedlot Cleaners Ltd.
Address: _____ City: _____ Province: _____ Postal Code: _____ Phone: _____

☒ Pass/Safe Vehicle ☐ Licence Number: C1X1860 Prov. MB NSC #: M86083398 Odometer Reading: 1442872 Odom. Type: ☒ km ☐ mi
☒ Fail/Unsafe Vehicle ☐ Vehicle Identification Number: 1FUDJA1G1CN187419S77714 Make: Ford Model: F-Series Year: 07 Unit #: _____
☒ Fail/Hazardous ☐ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

☒ Truck ☒ GWRV KGS ☐ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

P	R	Section	Defects (if any)	Circle Brake Type	Brake Inspection Type: A B C D E	Lining	Drum/Rotor	Stroke																																																																								
						L	R	L	R																																																																							
X	X	Section 1 - Power Train: Defects (if any)	Sec 1-2 Major fuel leak																																																																													
X	X	Section 2 Suspension: Defects (if any)	Sec 2-40 + 1 front spring broken on L side																																																																													
X	X	Section 3 - Brake Systems: Defects (if any)	Sec 3A-196 Rear right wheel speed sensor is by	3H 3A																																																																												
X	X	Section 4 - Steering: Defects (if any)	Sec 4-40 Front end																																																																													
X	X	Section 5 - Instruments & Auxiliary Equipment: Defects (if any)	Sec 5-70 Ignition key not work																																																																													
X	X	Section 6 - Lamps: Defects (if any)	Sec 6-14 No side marker light on box																																																																													
X	X	Section 7 - Electrical System: Defects (if any)																																																																														
X	X	Section 8 - Body: Defects (if any)	Sec 8-138 Diversion windshield cracked Sec 8-139 Right side convex mirror missing on head + on side of door Sec 8-21 front right head / loose																																																																													
X	X	Section 9 - Tire & Wheel: Defects (if any)	Sec 9-41A 2 + ms flat																																																																													
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth mm</th> <th colspan="4">Air Pressure PSI</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th></th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>10</td> <td>11</td> <td></td> <td></td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>2</td> <td>15</td> <td>16</td> <td>17</td> <td>16</td> <td>100</td> <td>90</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td>21</td> <td>17</td> <td>15</td> <td>27</td> <td>90</td> <td>20</td> <td>90</td> <td>100</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>								Axle	Tread Depth mm				Air Pressure PSI				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	10	11			100	100	100	100	2	15	16	17	16	100	90	100	100	3	21	17	15	27	90	20	90	100	4									5								
Axle	Tread Depth mm				Air Pressure PSI																																																																											
	Initial		Corrected		Initial		Corrected																																																																									
	L	R	L	R	L	R	L	R																																																																								
1	10	11			100	100	100	100																																																																								
2	15	16	17	16	100	90	100	100																																																																								
3	21	17	15	27	90	20	90	100																																																																								
4																																																																																
5																																																																																
X	X	Section 10 - Coupling Devices: Defects (if any)																																																																														

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date:

FVS0022-01-(R-09/15)

Ce document peut être obtenu en français sur demande.

SELLER'S COPY - NOT FOR REGISTRATION