

04078805

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

E05-12

Vehicle Safety
Box 45054 Regent Postal Cntr
Winnipeg, MB, R2C 9C7
1-204-985-0920Manitoba
C070375

Date Inspection Started
DAY 05 MO. 03 YR. 216

Date Inspection Completed
DAY 05 MO. 03 YR. 216

Inspection Expiry Date
DAY 31 MO. 03 YR. 217

Station Number A163119 Station Name Winnipeg Central Fleet Co
Mechanic Number M1016122 Mechanic Signature [Signature] City 204-999-8893
Vehicle Owner DE LAKE LANDEN FINANCIAL SERVICES CANADA INC
Address _____ City _____ Province _____ Postal Code _____ Phone _____

☒ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number TF161163 Prov. MB NSC # _____ Odometer Reading _____ Odom. Type km ☐ mi ☐

Vehicle Identification Number 11WYV5R2537J6312444 Make H/H Model Reta Year 18 Unit # R226
☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR _____ KGS _____ Truck Tractor _____ Trailer ☒ Semi-Trailer _____ Bus _____ School Bus _____ Coach Bus _____

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		Section 1 - Power Train: Defects (if any)
X		Section 2 Suspension: Defects (if any)
X	X	Section 3 - Brake Systems: 3H (3A) Defects (if any) Circle Brake Type 416' Air Tank Loose 1310: Caliper hand rock Loose 15 (b) 6: Brake shoe crack 1610: ALL Brake Adjust
X		Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X		Section 6 - Lamps: Defects (if any)
X		Section 7 - Electrical System: Defects (if any)
X	X	Section 8 - Body: Defects (if any) 6 (C) Middle P corner Member left loose
X		Section 9 - Tire & Wheel: Defects (if any)
X		Section 10 - Coupling Devices: Defects (if any)

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	5	5	10	5	100	100	100	100
2	11	16	14	11	100	100	100	100
3								
4								
5								

Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	5/8	5/8			1 1/2	1 1/2
2	5/8	3/4			1 1/2	1 1/2
3						
4						
5						
Final Measurement						

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date: