

04058958

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba



E05-15

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba



C052099

Date Inspection Started DAY: 02 MO: 01 YR: 26	Station Number A6 491	Station Name MID CANADA FRUIT LTD.	City
Date Inspection Completed DAY: 02 MO: 01 YR: 26	Mechanic Number 107748	Mechanic Signature Jatinder Kumar	Station Phone Number
Inspection Expiry Date DAY: 31 MO: 01 YR: 27	Vehicle Owner GMR TRANSPORT INC.		
Address		City	Province
Postal Code		Phone	
☒ Pass/Safe Vehicle ☒ Fail/Unsafe Vehicle ☐ Fail/Hazardous	Licence Number CKX734	Prov. MB	NSC # MB1510126
	Vehicle Identification Number 3AKJHHDR8LSKV5323	Make FRUIT	Model CAS
	Odometer Reading 1701725		Odom. Type ☒ km ☐ mi
	Year 2020		Unit # 101
☐ Confirmed legible Vehicle Identification Number on vehicle			

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS ☒ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		Section 1 - Power Train: Defects (if any)
X		Section 2 Suspension: Defects (if any)
X		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type
X		Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X		Section 6 - Lamps: Defects (if any)
X		Section 7 - Electrical System: Defects (if any)
X		Section 8 - Body: Defects (if any)
X		Section 9 - Tire & Wheel: Defects (if any)
X		Section 10 - Coupling Devices: Defects (if any)

Tread Depth				Air Pressure											
Initial				Corrected				Initial				Corrected			
Axle	L	R		L	R	L	R	L	R	L	R	L	R		
1	14	14				105	105								
2	7	7	10	9		100	100	100	100						
3	14	13	7	9		100	100	100	100						
4															
5															

Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	7/8	11/16	16.520	16.525		
2	7/8	7/8	16.518	16.521		
3	7/8	11/16	16.523	16.528		
4						
5						
Final Measurement						

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date: