

04030287

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba



E 05-17

Vehicle Standards and Inspection
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba



C048785

Date Inspection Started DAY: 16 MO: 10 YR: 25	Station Number AS341	Station Name S496633 Manitoba	City Winnipeg
Date Inspection Completed DAY: 17 MO: 10 YR: 25	Mechanic Number M77772	Mechanic Signature [Signature]	Station Phone Number 204-999-3179
Inspection Expiry Date DAY: 31 MO: 10 YR: 26	Vehicle Owner Coach Transport Ltd.		
Address 3 Magalas Ave West St Paul MB R4A 0B5			
City St Paul Province MB Postal Code R4A 0B5 Phone [Blank]			

☒ Pass/Safe Vehicle	Licence Number CRL328	Prov. MB	NSC # MB1510126	Odometer Reading 1966086	Odom. Type ☒ km ☐ mi
☐ Fail/Unsafe Vehicle	Vehicle Identification Number 3AKJHADR1J5SKA2231	Make FRH	Model Cascadia	Year 2018	Unit # 107
☐ Fail/Hazardous	☒ Confirmed legible Vehicle Identification Number on vehicle				

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS ☒ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		Section 1 - Power Train: Defects (if any)
X		Section 2 Suspension: Defects (if any)
X	X	Section 3 - Brake Systems: 3H 3A Defects (if any) 13(A) Gladhand Seals Broken Circle Brake Type
X		Section 4 - Steering: Defects (if any)
X	X	Section 5 - Instruments & Auxiliary Equipment: Defects (if any) 1(B) Fire Extinguisher Empty
X	X	Section 6 - Lamps: Defects (if any) 1(D) Right Side Headlight not working 1(E) Right Side Marker and Turn Signal not working
X	X	Section 7 - Electrical System: Defects (if any) 2(A) All Battery cables and posts Corrosion
X	X	Section 8 - Body: Defects (if any) 12(A) Front Bumper Loose
X	X	Section 9 - Tire & Wheel: Defects (if any) 4(D) All Tire Air Pressure Low
X	X	Section 10 - Coupling Devices: Defects (if any) 7(D) Adjust 5th wheel Loose

Axle	Tread Depth				Air Pressure			
	Initial PSI		Corrected		Initial PSI		Corrected PSI	
	L	R	L	R	L	R	L	R
1	7	7			90	90	100	100
2	11	10	11	12	85	90	90	85
3	11	11	10	11	90	90	90	90
4	1	1	1	1	1	1	1	1
5	1	1	1	1	1	1	1	1

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature Date: