

04057837

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

E05-18

Vehicle Safety
Box 45064 Regent Plaza
Winnipeg, MB, R2C 5C7
1-204-985-0920Manitoba
C050717

Date Inspection Started	03	12	25
	DAY	MO.	YR.
Date Inspection Completed	04	12	25
	DAY	MO.	YR.
Inspection Expiry Date	31	12	26
	DAY	MO.	YR.

Station Number	A1513411	Station Name	S496633/Monitoba	City	204999-3179
Mechanic Number	M171712	Mechanic Signature		Station Phone Number	
Vehicle Owner	GMR Transport Ltd.	Address	296 Wheatfield Rd	City	Centerport MB R4B 0A3
		Province		Postal Code	
				Phone	

☒ Pass/Safe Vehicle	Licence Number	T111411616	Prov.	MB	NSC #		Odometer Reading		Odom. Type	km	mi
☒ Fail/Unsafe Vehicle	Vehicle Identification Number	11U1YMS12532H21178855	Make	Utili	Model	Reflex	Year	2017	Unit #	GR2910	
☐ Fail/Hazardous	☒ Confirmed legible Vehicle Identification Number on vehicle										

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P R Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

Section 1 - Power Train: Defects (if any)

Section 2 Suspension: Defects (if any)

Section 3 - Brake Systems: 3H 3A

Defects (if any) Circle Brake Type

13(A) Both Gladhand seals Broken

15(E) Front Axle Both Brake Shoe

Lining 2/16"

15(E) Front Axle Both Brake Drum

16635"

Section 4 - Steering: Defects (if any)

Section 5 - Instruments & Auxiliary Equipment: Defects (if any)

Section 6 - Lamps: Defects (if any) 1(D) Left Stop light not working

1(E) Right Side Middle Turn Signal not working

Section 7 - Electrical System: Defects (if any)

Section 8 - Body: Defects (if any)

Section 9 - Tire & Wheel: Defects (if any) 4(A) All Tire Air pressure Lower than Recommended

Tread Depth

Air Pressure

Initial Corrected Initial Corrected

Axle L R L R L R L R

1 10 10 10 10 90 90 90 90 100 100 100 100

2 8 8 8 8 85 90 90 90 100 100 100 100

3 1 1 1 1 1 1 1 1 1 1 1

4 1 1 1 1 1 1 1 1 1 1 1

5 1 1 1 1 1 1 1 1 1 1 1

Section 10 - Coupling Devices: Defects (if any)

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not

guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: All Repair Done by All Trucks and Trailers Repair

Ltd.

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and

an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a

Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature

Date: 03/12/25

COPY IN CAB - PLEASE ENSURE CERTIFICATE IS SIGNED - NOT FOR REGISTRATION

Ce document peut être obtenu en français sur demande.

