

03941404

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba



E06-1

Vehicle Standards and Inspections
Box 45064 Regent Postal C
Winnipeg, MB, R2C 5C7
1-204-955-0920

Manitoba



A981716

Date Inspection Started: 07 DAY, 08 MO., 25 YR.

Date Inspection Completed: 07 DAY, 08 MO., 25 YR.

Inspection Expiry Date: 31 DAY, 08 MO., 26 YR.

Station Number: A100613 Station Name: GREWINSKI TRUCKING LTD. City: 204-345-2207

Mechanic Number: M716110 Mechanic Signature: [Signature] Station Phone Number: 204-345-2207

Vehicle Owner: Stephen Folks

Address: 1014 Bay Rd City: Stanley Province: MB Postal Code: R1A3L1 Phone: 204-230-6555

☒ Pass/Safe Vehicle ☐ Fail/Unsafe Vehicle ☐ Fail/Hazardous

License Number: [Blank] Prov. MB NSC # [Blank] Odometer Reading: 1327.3 Odom. Type: [Blank] km [Blank] mi

Vehicle Identification Number: 1FV6HFAA8TL678029 Mark: FAIRCHILD Model: [Blank] Year: 1996 Unit #: [Blank]

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck 14833 KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		Section 1 - Power Train: Defects (if any)
X		Section 2 Suspension: Defects (if any)
X		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type
X		Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X		Section 6 - Lamps: Defects (if any)
X		Section 7 - Electrical System: Defects (if any)
X		Section 8 - Body: Defects (if any)
X		Section 9 - Tire & Wheel: Defects (if any)
X		Section 10 - Coupling Devices: Defects (if any)

Brake Inspection Type: (A) B C D E Circle appropriate letter for Internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	NEW	NEW	NEW	NEW	1.5	1.5
2	NEW	NEW	16.558	16.563	1.25	1.25
3						
4						
5						
Final Measurement						

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	11	10			100	100		
2	23	23	23	23	100	100	100	100
3								
4								
5								

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.