Service History Customer Report
Equipment No. EXC14

Description: Komatsu PC138US-11 Excavator

Make: Komatsu

Model: PC138US-11

Serial No.: KMTPC189CGA033679

Registration: 35417C

Registration Expiry: 30/04/2027

Date	Job Number	Eng. Hours	Job Description
18/05/2024	531	6750.00	Fire Suppression Fault
			Comment: Investigated fire suppression fault - Found to be low pressure. Charged system with nitrogen and checked for leaks - Tested ok.
18/05/2024	544	6774.00	Hydraulic Oil Leak
			Comment: 19.05.24 Investigated hydraulic oil leak - Found to be hose on tilt bucket. Replaced o-ring on hose and tested ok.
09/06/2024	730	6791.00	DEFECT REPAIRS/FULL WASH AND DETAIL/PRE HIRE INSPECTION
			Comment: COMPLETED OFF HIRE INSPECTION. WASHED, DETAILED AND GREASED MACHINE. COMPLETED ON HIRE INSPECTION.
29/09/2024	795	6791.00	Scheduled Service Job. COMPLIANCE FIRE SUPPRESSION6M AND FIRE EXTINGUISHE
			Comment: DMS FIRE TECHNICIAN COMPLETED 6 MONTLY FIRE SUPPRESSION AND FIRE EXTINGUISHER SERVICES
19/06/2024	865	6791.00	Adani Spec Machine
			Comment: 22.06.24 Completed Adani spec repairs - Installed seatbelt alarm. Washed, detailed and greased machine.
22/07/2024	2201	6774.00	Full Wash and Detail/Pre Hire Inspection
			Comment: 01.07.24 6774HRS - Completed full wash and detail on machine and completed on hire inspection.
25/07/2024	2313	6791.00	REPLACE BROKEN LH LOWER REAR VIEW MIRROR
			Comment: REPLACED BROKEN LEFT HAND LOWER REAR VIEW MIRROR.
16/10/2024	3384	6817.00	DEFECT REPAIRS FROM OFF HIRE INSPECTION 14.10.24
			Comment: COMPLETED OFF HIRE INSPECTION. TOPPED UP LOW COOLANT LEVEL. TOPPED UP LOW ENGINE OIL LEVEL. REPAIRED WORK LIGHT ON BOOM NOT WORKING. TOPPED UP WASHER BOTTLE. REPLACED LHS MIRROR NEAR DOOR (PARTS ORDERED ON SERV JOB 2313). DRAINED HYDRAULIC TANK, REMOVED AND REPLACED HYDRAULIC HOSE AND TOPPED UP OIL. DRAINED AND REFILLED SLEW BOX. REMOVED BUCKET, FIT AUGER AND REPLACED HOSES AND TESTED

Service History Customer Report
Equipment No. EXC14

Description: Komatsu PC138US-11 Excavator

Make: Komatsu

Model: PC138US-11

Serial No.: KMTPC189CGA033679

Registration: 35417C

Registration Expiry: 30/04/2027

			OPERATION - ALL OK. WASHED, DETAILED AND GREASED MACHINE. COMPLETED ON HIRE INSPECTION.
13/11/2024	3711	6832.00	DEFECT REPAIRS FROM OFF HIRE INSPECTION 13/11/24
			Comment: COMPLETED OFF HIRE INSPECTION. TOPPED UP LOW ENGINE OIL. CHECKED AND ADJUSTED HYDRAULIC OIL LEVEL. WASHED, DETAILED AND GREASED MACHINE. COMPLETED ON HIRE INSPECTION
15/11/2024	3770	6832.00	Scheduled Service Job. COMPLIANCEFIRESUPPRESSION 12M AND FIRE EXTINGUISHE
			Comment: DMS COMPLETED 12 MONTHLY FIRE SUPPRESSION AND FIRE EXTINGUISHER SERVICES.
19/11/2024	3814	6839.00	Off hire/On hire 19.11.24
			Comment: COMPLETED OFF HIRE INSPECTION. WASHED, DETAILED AND GREASED MACHINE. COMPLETED ON HIRE INSPECTION.
18/12/2024	4243	6839.00	DEFECT REPAIRS FROM OFF HIRE INSPECTION 18.12.24
			Comment: COMPLETED OFF HIRE INSPECTION. FIRE SUPPRESSION SYSTEM LOW PRESSURE CLEANED DIRTY AIR CLEANER. TOPPED UP WASHER BOTTLE. REPLACED MISSING KEY. RECTIFIED HYDRAULIC LEAK AROUND RH QUICK CONNECT COUPLING. RESEALED A/C VENT IN ROOF LEAKING WATER. DOOR HARD TO SLIDE - REPLACED ROLLER ASSEMBLY. INVESTIGATED AND REPAIRED TILT BUCKET NOT OPERATING PROPERLY. WASHED, DETAILED AND GREASED MACHINE. COMPLETED ON HIRE INSPECTION.
29/01/2025	4564	6896.00	DEFECTS FROM OFF HIRE INSPECTION 24/01/25
			Comment: COMPLETED OFF HIRE INSPECTION. REPLACED SEAT BELT BUZZER. REFIT LH ARM REST CABLE. REMOVED AND REPLACED FRONT WIPER BLADE. WASHED, DETAILED AND GREASED MACHINE. COMPLETED ON HIRE INSPECTION.
18/02/2025	4799	6921.00	DEFECTS FROM OFF HIRE INSPECTION 18/02/25

Service History Customer Report
Equipment No. EXC14

Description: Komatsu PC138US-11 Excavator

Make: Komatsu

Model: PC138US-11

Serial No.: KMTPC189CGA033679

Registration: 35417C

Registration Expiry: 30/04/2027

			Comment: COMPLETED OFF HIRE INSPECTION. TOPPED UP ENGINE OIL. REMOVED AND REPLACED LH JOYSTICK . WASHED, DETAILED AND GREASED MACHINE. COMPLETED ON HIRE INSPECTION. INSPECTED DOOR SEAL LEAKING. REMOVED DOOR, REPLACED SEAL, REFIT DOOR. SEALED ADDITIONAL AIR LEAKING SPOTS.
19/02/2025	4815	6921.00	MACHINE IS DUE FOR A 1000HR SERVICE
			Comment: CARRIED OUT 1000 HOUR SERVICE.
24/02/2025	4832	6921.00	LH JOYSTICK BROKEN
			Comment: REMOVE PLASTIC TRIMS ON LH ARM REST, REMOVE BROKEN LH JOYSTICK AND REPLACE WITH NEW JOYSTICK. ASSEMBLE PLASTIC TRIM AND TEST OPERATIONS. (NOTE: BROKEN PIECES ON JOYSTICK ARE NOT SOLD SEPERATELY, CAN ONLY SOURCE COMPLETE JOYSTICK ASSEMBLY)
27/02/2025	4855	6921.00	Scheduled Service Job. COMPLIANCE FIRE SUPPRESSION6M AND FIRE EXTINGUISHER
			Comment: DMS FIRE TECHNICIAN COMPLETED 6 MONTHLY FIRE SUPPRESSION AND FIRE EXTINGUISHER SERVICES.
10/04/2025	5291	6929.00	DEFECTS FROM OFF HIRE INSPECTION 09/04/25
			Comment: COMPLETED OFF HIRE INSPECTION. FIT BOLT TO LIFTING EYE ON HITCH. SECURED WINDOW HAMMER. TURNED BLADE EDGE. REMOVED AND REPLACED BROKEN BOLT IN FIRE EXTINGUISHER BRACKET. WASHED, DETAILED AND GREASED MACHINE. COMPLETED ON HIRE INSPECTION. REMOVED AND REPLACED COUPLING. INVESTIGATED AND RECTIFIED OIL LEAK. REMOVED WASTE FROM A/C FAN.
06/05/2025	5484	6994.00	DEFECTS IDENTIFIED FROM OFF HIRE INSPECTION 06.05.25
			Comment: COMPLETED OFF HIRE INSPECTION. REPLACED FIRST AID KIT. REMOVED AND REPLACED SEAT BELT. REMOVED AND REPLACED WIPER ARM. REPLACED HYDRAULIC FITTINGS TO TILT BUCKET. REPLACED STICKERS. WASHED, DETAILED AND GREASED MACHINE. COMPLETED ON HIRE INSPECTION.

Service History Customer Report
Equipment No. EXC14

Description: Komatsu PC138US-11 Excavator

Make: Komatsu

Model: PC138US-11

Serial No.: KMTPC189CGA033679

Registration: 35417C

Registration Expiry: 30/04/2027

20/05/2025	5660	6994.00	WATER PUMP FAILURE
			Comment: WATER PUMP & FAN REPLACED
02/06/2025	5937	6997.00	Scheduled Service Job. COMPLIANCEBRAKE 6MONTHLY
			Comment: CENTRAL QLD COMPLIANCING COMPLETED BMA 6 MONTHLY BRAKE TEST.
03/06/2025	5954	7005.00	MAY ON SITE REPAIRS AT PEAK DOWNS MINE
03/06/2025	5955	7005.00	JUNE ON SITE REPAIRS AT PEAK DOWNS MINE
			Comment: ARA FIRE TECHNICIAN COMPLETED LEVEL 5 REFILL AND RECHARGE SERVICE DUE TO SYSTEM DISCHARGED (CALL OUT).
30/06/2025	6333	7033.00	JULY ON SITE REPAIRS AT PEAK DOWNS MINE
28/07/2025	6679	7067.00	DEFECT REPAIRS FROM OFF HIRE 28.7.25
			Comment: COMPLETED OFF HIRE INSPECTION TOPPED UP LOW COOLANT LEVEL REPAIRED CRACKED HANDRAIL FILLED UP WASHER BOTTLE ADJUSTED TRACKS TENSION TO OEM SPEC WASHED, DETAILED AND GREASED MACHINE COMPLETED ON HIRE INSPECTION
21/08/2025	7022	7067.00	DEFECT REPAIRS IDENTIFIED ON OFF HIRE 21.8.25
			Comment: COMPLETED OFF HIRE INSPECTION WASHED, DETAILED AND GREASED MACHINE COMPLETED ON HIRE INSPECTION NO STICK TO QUICK HITCH ORINGS. REQUIRES SHIMS - WILL NEED TO FABRICATE. RADIATOR FLY SCREENS ARENT IN CORRECTLY LOW HYDRAULIC OIL – TOPPED UP TO CORRECT LEVEL
02/09/2025	7361	7113.00	DEFECTS REPAIRS FROM OFF HIRE INPSECTION 02.09.25
			Comment: COMPLETED OFF HIRE INSPECTION SLEW OIL - TOPPED UP. COOLANT OIL - TOPPED UP. RUST AROUND WINDSCREEN FRAME TREATED. WASHED, DETAILED & GREASED MACHINE COMPLETED ON HIRE INSPECTION REPLACED BUCKET TEETH
15/09/2025	7717	7113.00	Scheduled Service Job. COMPLIANCEFIRESUPPRESSION 12M AND FIRE EXTINGUISHER

Service History Customer Report
Equipment No. EXC14

Description: Komatsu PC138US-11 Excavator

Make: Komatsu

Model: PC138US-11

Serial No.: KMTPC189CGA033679

Registration: 35417C

Registration Expiry: 30/04/2027

			Comment: DMS FIRE TECHNICIAN COMPLETED 12 MONTHLY FIRE SUPPRESSION AND FIRE EXTINGUISHER SERVICES
22/09/2025	7859	7113.00	AIRCON FAULT
			Comment: ACES CALLED TO INVESTIGATE & REPAIR
07/10/2025	8050	7113.00	A/C SYSTEM BLOWING HOT AIR
			Comment: ACES / INV80587 - DAN 30.09 - SERVICE CALL TO SITE AND INSPECTED AIRCON FAULT. SOURCED PARTS TO REPAIR. 2.10 - SERVICE CALL TO SITE TO CARRY OUT AIRCON REPAIRS. DEGASSED SYSTEM, REMOVED SEAT AND ALL CAB COMPONENTS TO ACCESS EVAPORATOR BOX. REMOVED AND REPLACED EVAPORATOR. REASSEMBLED EVAPORATOR BOX. REMOVE AND REPLACE COMPRESSOR, CONDENSER AND TX VALVE. FLUSHED SYSTEM, VACUUMED DOWN AND REGAS.
10/10/2025	8098	7157.00	DEFECT, REPAIRS FROM OFF HIRE INSPECTIOIN 10.09.25
			Comment: COMPLETED OFF HIRE INSPECTION REMOVED & REPLACED BROKEN TRACK PAD RH TRACK REPLACED BOOM LIGHT WASHED, DETAILED & GREASED MACHINE COMPLETED ON HIRE INSPECTION
10/12/2025	9039	7193.00	DEFECT, REPAIRS FROM OFF HIRE INSPECTION 10.12.25
			Comment: COMPLETED OFF HIRE INSPECTION TRACK PLATE REPLACED RHS X1 REAR MID RAIL CRACKED - REPAIRED SLEW LEVEL TOPPED UP DOOR ALARM REPAIRED WASHED, DETAILED & GREASED MACHINE COMPLETED ON HIRE INSPECTION
03/02/2026	9603	7280.00	DEFECT REPAIRS FROM OFF HIRE INSPECTION 02.02.26
			Comment: COMPLETED OFF HIRE INSPECTION BUCKET CYLINDER HOSE FITTING REPLACED TOPPED UP ENGINE OIL WASHED, DETAILED & GREASED MACHINE COMPLETED ON HIRE INSPECTION
06/03/2026	10054	7305.00	DEFECT, REPAIRS FROM OFF HIRE INSPECTION 6.03.26

Service History Customer Report
Equipment No. EXC14

Description: Komatsu PC138US-11 Excavator

Make: Komatsu

Model: PC138US-11

Serial No.: KMTPC189CGA033679

Registration: 35417C

Registration Expiry: 30/04/2027

			Comment: COMPLETED OFF HIRE INSPECTION REPLACED BENT WIPER BLADE. FIRE EXTINGUSHER SWAPPED OUT FIRE SUPPRESSION DUE FOR 6MONTHLY AUDIT - COMPLETED WASHER BOTTLE FILLED CABIN FILTERS BLOWN OUT FITTINGS TIGHTENED ON HITCH (BUCKET TILT) BLEW OUT AIR CLEANER WASHED, DETAILED & GREASED MACHINE COMPLETED ON HIRE INSPECTION REMOVED & REPLACED TILT HOSES ON BUCKET
10/03/2026	10076	7305.00	Scheduled Service Job. COMPLIANCE FIRE SUPPRESSION6M AND FIRE EXTINGUISHER
			Comment: DMS FIRE SERVICES COMPLETED 6 MONTHLY FIRE SUPPRESSION & FIRE EXTINGUSHER SERVICE.
26/03/2026	10263	7305.00	REPLACE DAMAGED QUICK COUPLER ADAPTOR
			Comment: EXC14 - DAMAGED HYD HOSE QUICK CONNECT FITTINGS TRAVEL TO SITE, LOCATE MACHINE, REMOVED AND REPLACED BROKEN QUICK CONNECT FITTINGS
27/03/2026	10277	7305.00	BATTERY CHARGE LIGHT ON DASH
			Comment: FITTER ATTENDED SITE INVESTIGATED THE FAULT / IDENTIFIED ALTERNATOR UNSERVICEABLE/ REMOVED & REPLACED ALTERNATOR - TESTED OK - 26.1V @ IDLE.
02/04/2026	10418	7360.00	DEFECT REPAIRS FROM OFF HIRE INSPCTION 01.04.26
			Comment: COMPLETED OFF HIRE INSPECTION COOLANT TOPPED UP. AIR CLEANER BLEW OUT COOLANT LEAK @ THERMOSTAT HOUSING - REPAIRED OIL LEAK ON TIMING COVER - REPAIRED WASHED, DETAILED & GREASED MACHINE COMPLETED ON HIRE INSPECTION DMS FIRE TECHICIAN LOCATED AND RECTIFIED LEAKING FITTING RECHARGED FIRE SUPPRESSION SYSTEM.
30/04/2026	10779	7452.00	MAY DEFECT REPAIRS ON SITE @ PEAKDOWNS

Service History Customer Report
Equipment No. EXC14

Description: Komatsu PC138US-11 Excavator

Make: Komatsu

Model: PC138US-11

Serial No.: KMTPC189CGA033679

Registration: 35417C

Registration Expiry: 30/04/2027

			Comment: DEFECT REPAIRS CARRIED OUT DURING MAY : - REPAIRED HYDRAULIC OIL LEAK @ TILT BUCKET.
11/05/2026	10952	7532.00	500Hr Service @ 7500Hrs
			Comment: 500HR SERVICE & INSPECTION COMPLETED 3.06.26
20/04/2026	10981	7452.00	Scheduled Service Job. COMPLIANCE BMA INSPECTION AND BRAKE TEST
			Comment: CQ COMPLIANCING COMPLETED 12 MONTHLY BMA COMPLIANCE & BRAKE TEST
29/05/2026	11178	7495.90	JUNE - ON SITE REPAIRS AT PEAK DOWNS MINE
			Comment: DEFECT REPAIRS CARRIED OUT DURING JUNE INCLUDED: - REPLACED LH FRONT TRACK ROLLER. - REPLACED 5x TRACK WEAR PLATES. - CHECKED OVER MACHINE.
30/06/2026	11711	7592.00	AUGUST - OFF HIRE INSPECTION
			Comment: WORKS CARRIED OUT DURING AUGUST - COMPLETED OFF HIRE INSPECTION. - FITTED NEW GREASE NIPPLES & DOOR LATCH. - REPAIRED & PAINTED PANEL. - WASHED, POLISHED, DETAILED & GREASED MACHINE. - REPLACED BROKEN BOLTS. - UNBLOCKED GREASE LINES - ADJUSTED TRACKS. - COMPLETED ON HIRE INSPECTION.
31/08/2026	12611	7592.00	SEPTEMBER - REPAIRS & MAINT
			Comment: MACHINE GREASED & LOADED ONTO FLOAT WITH ALL ATTACHMENTS
19/10/2026	13240	7592.00	PREPARE MACHINE TO SEND TO AUCTION

Service History Customer Report
Equipment No. EXC14

Description: Komatsu PC138US-11 Excavator

Make: Komatsu

Model: PC138US-11

Serial No.: KMTPC189CGA033679

Registration: 35417C

Registration Expiry: 30/04/2027

Date/Time Printed:05/11/2026 2:21 PM