03937135

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Inspection Unit
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba

A916963

Date Inspection Started	02 DAY	06 MO.	25 YR.	Station Number	C01141	Station Name: Strilkiwski Contracting LTD	City
Date Inspection Completed	02 DAY	06 MO.	25 YR.	Mechanic Number	MB837	Mechanic Signature	Station Phone Number: 638-9304
Inspection Expiry Date	30 DAY	06 MO.	26 YR.				

Vehicle Owner: Strilkiwski Contracting LTD

Address: Box 578 | City: Dauphin | Province: MB | Postal Code: R7N-2V4 | Phone: 638-9304

☒ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number: TFB156B | Prov.: MB | NSC #: | Odometer Reading: | Odom. Type ☐ km ☐ mi

Vehicle Identification Number: 2MFB2R5D19R101591 6 | Make: mid land | Model: side dump | Year: 09 | Unit #: SD-9

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

____Truck GVWR ____ KGS ____Truck Tractor ____Trailer X Semi-Trailer ____Bus ____School Bus ____Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		**Section 1 - Power Train:** Defects (if any)
X	X	**Section 2 Suspension:** Defects (if any) 2-5B axl Left air spring Leaking.
X	X	**Section 3 - Brake Systems:** 3H (3A)

Defects (if any) / Circle Brake Type

3A-15K drum diameter worn past 16.620.
3A-15C shoes worn past 5/16

Brake Inspection Type: (A) B C D E — Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining L	Lining R	Drum/Rotor L	Drum/Rotor R	Stroke L	Stroke R
1	9/16	9/16	NEW	16.607	1 1/2	1 3/16
2	7/16	NEW	NEW	NEW	1 1/2	1 9/16
3	5/8	5/8	16.576	16.590	1 3/8	1 5/16
4						
5						
	Final Measurement					

X		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X		**Section 6 - Lamps:** Defects (if any)
X		**Section 7 - Electrical System:** Defects (if any)
X		**Section 8 - Body:** Defects (if any)
X		**Section 9 - Tire & Wheel:** Defects (if any)

	Tread Depth Initial L		Tread Depth Initial R		Tread Depth Corrected L		Tread Depth Corrected R		Air Pressure Initial L		Air Pressure Initial R		Air Pressure Corrected L		Air Pressure Corrected R	
Axle																
1	10	12	10	10					100	100	100	100				
2	19	19	16	17					100	100	100	100				
3	9	11	8	8					100	100	100	100				
4																
5																

X		**Section 10 - Coupling Devices:** Defects (if any)

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

FVS0022-01-(R-09/15)

Ce document peut être obtenu en français sur demande.

COPY IN CAB - PLEASE ENSURE CERTIFICATE IS SIGNED - NOT FOR REGISTRATION