04103071 **PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE** Manitoba F03-1

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba
C091878

Date Inspection Started	08 (DAY)	05 (MO.)	26 (YR.)
Date Inspection Completed	08 (DAY)	05 (MO.)	26 (YR.)
Inspection Expiry Date	31 (DAY)	05 (MO.)	27 (YR.)

Station Number: A5293 — Station Name: JAZ MECHANICAL LTD — City: WPG

Mechanic Number: M3977P — Mechanic Signature: [signature] — Station Phone Number: 204 9976075

Vehicle Owner: RICK PALMER TRUCKING LTD.

Address: — City: — Province: — Postal Code: — Phone:

- [X] Pass/Safe Vehicle
- [X] Fail/Unsafe Vehicle
- [ ] Fail/Hazardous

Licence Number: TG8134 — Prov.: MB — NSC #: — Odometer Reading: — Odom. Type: [ ] km [ ] mi

Vehicle Identification Number: 2D9CD3823W1012159 — Make: LOAD LINE — Model: BELLY DUMP — Year: 1998 — Unit #: B098

[X] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

___Truck GVWR ___ KGS ___Truck Tractor ___Trailer X Semi-Trailer ___Bus ___School Bus ___Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		Section 1 - Power Train: Defects (if any)
X		Section 2 Suspension: Defects (if any)
X		Section 3 - Brake Systems: 3H 3A (Circle Brake Type) Defects (if any)
X		Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X	X	Section 6 - Lamps: Defects (if any) [illegible]
X		Section 7 - Electrical System: Defects (if any)
X		Section 8 - Body: Defects (if any)
X		Section 9 - Tire & Wheel: Defects (if any)
X		Section 10 - Coupling Devices: Defects (if any)

Brake Inspection Type: A B C D E — Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining L	Lining R	Drum/Rotor L	Drum/Rotor R	Stroke L	Stroke R
1	1/2	9/16	16537	16543	1 1/2	1 1/2
2	7/16	1/2	16543	16552	1 1/2	1 1/2
3	1/2	9/16	16555	16547	1 1/2	1 1/2
4						
5						
	Final Measurement					

Axle	Tread Depth Initial L		Tread Depth Initial R		Tread Depth Corrected L		Tread Depth Corrected R		Air Pressure Initial L		Air Pressure Initial R		Air Pressure Corrected L		Air Pressure Corrected R	
1	8	4	5	4					100	100	100	100				
2	12	7	10	14					100	100	100	100				
3	7	4	4	13					100	100	100	100				
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Date:

Vehicle received without repairs by:

Ce document peut être obtenu en français sur demande