



DIESEL VEHICLE INSPECTION REPORT


VEHICLE OWNER INFORMATION			Date of Test 04/27/2026
Name PAR SOLUTIONS			
Address 1570 S COUNTY RD 129			
City BENNETT	State CO	Zip Code 80102	

EMISSIONS TEST FACILITY INFORMATION		
Station Number 21242	Station Name Windways Express	Serial # 2124211454
Inspection Cost \$ 100	Station Address 4940 Oneida St	
Commerce City, CO 80022		

VEHICLE INFORMATION			
Vehicle Identification Number 3ALACXFC4KDKU9132			
Model Year 2019	Vehicle Make FRHT	Vehicle License Plate ENBP98	
GVWR 33000	Vehicle Class HD	Non CO. License Plate NO	
# of Cylinders 6	Engine Make CUMM	Engine Type TURBO	Odometer 201338
Transmission Type AUTO	Vehicle smoke repairs last 60 days? NO	DR2365 NO	

FIRST TEST	Inspector Number 21248	AFTER REPAIRS TEST	Inspector Number
Heavy duty vehicle dynamometer lug down test		Heavy duty vehicle dynamometer lug down test	
Snap 0% OPACITY		Snap	
Zero Shift 0% OPACITY		Zero Shift	
Engine Rate 0% OPACITY		Engine Rate	
90% 0% OPACITY		90%	
80% 0% OPACITY		80%	
70% 0% OPACITY		70%	
Zero Shift 0% OPACITY		Zero Shift	
Results PASS		Results	

EMISSIONS CONTROL SYSTEMS	FIRST	FINAL	REPAIR INFORMATION
Pump Seals Air Fuel Adjustment	NA		Fail Repair Cost \$ 0.00
Boost Compensation / Aneroid	NA		Re-insp. Cost \$
Electronic Engine Controls	PASS		Date of Retest
Trap / Catalytic Converter	PASS		
Positive Crankcase Ventilation System	PASS		
Exhaust Gas Recirculation System	PASS		

OVERALL RESULTS	CERTIFICATE OF EMISSIONS COMPLIANCE	
Initial Test PASS	Date Of Test 04/27/2026	Test Results PASS
Retest	VIN 3ALACXFC4KDKU9132	GVWR 33000
Waiver	Verification # 2124541018	 COLORADO Department of Revenue