

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 12/4/2023

Serial: 7722

Make: Ford

location: R/c

Model: F-350

Hours/Mileage: 63,000

Work performrd (print)

Had left rear inside tire repaired

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Jared Willingham

Total Hours spent on Repair: 1

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 11/9/2023

Serial: 7722

Make: Ford

location: R/C

Model: f-350

Hours/Mileage: 62,037

Work performrd (print)

Did 5,000 hour service

Parts/supplies used (print)

A: 1-WA10679 air filter

B: 1-57151 oil filter

C: 1-WP10266 cab-n-air filter

D: 3- 1 gallon rotella 4-t engine oil

E:

F:

Repaired Completed By (Mechanic-Print)

Jared Willingham

Total Hours spent on Repair: 1

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 8/9/2023

Serial: 7722

Make: Ford

location: Royal city

Model: f-350

Hours/Mileage: 58,480

Work performrd (print)
replaced broken valve and
solenoid's on mobil crane

Parts/supplies used (print)

A: 1-44027 valve

B: 2-44028 solenoid's

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Jared Willingham

Total Hours spent on Repair: 2

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 7/21/2023

Make: ford

Model: f-350

Serial: 7722

location: R/C

Hours/Mileage: 57,876

Work performrd (print)

Installed carburetor on air
compressor

Parts/supplies used (print)

A:

1-carburetor

B:

1- gasket

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Jared Willingham

Total Hours spent on Repair:

1

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 7/21/2023

Serial: 7722

Make: ford

location: R/C

Model: f-350

Hours/Mileage: 57,876

Work performrd (print)

washed and cleaned interior of
truck

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Jared Willingham

Total Hours spent on Repair: 2

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 6/2/2023 Serial: 7722
Make: Ford location: R/C
Model: F-3350 Hours/Mileage: 56,956

Work performrd (print)
Did service replaced air lines
to air compressor an dnw ball
valuefittings

Parts/supplies used (print)

A: 1-wa10679 air filter

B: 1-fl2124s oil filter

C: 3- 1 gallon engine oil

D: 1- 4107 cab-n-air filter

E:

F:

Repaired Completed By (Mechanic-Print)
Jared willingham

Total Hours spent on Repair: 3 1/2

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 10/6/2022

Serial: 7722

Make: Ford

location: R/C

Model: F-350

Hours/Mileage: 50,267

Work performrd (print)

Replaced rear brakes

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Justin Garoufalias

Total Hours spent on Repair: 3

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 9/14/2022

Serial: 7722

Make: ford

location: R/C

Model: f-350

Hours/Mileage: 50,267

Work performrd (print)

Installed new brake pad's
on front and rear, washed
truck

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)
Justin Garoufalias

Total Hours spent on Repair: 5

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 8/24/2022

Serial: 7722

Make: Ford

location: R/C

Model: f-350

Hours/Mileage: 51,266

Work performrd (print)

washed truck and cleaned inside

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Justin Garoufalias

Total Hours spent on Repair: 3

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 7/29/2022

Serial: 7722

Make: Ford

location: R/C

Model: F-350

Hours/Mileage: 50,166

Work performrd (print)

Did service on engine and
inspected truck

Parts/supplies used (print)

A: 1- FA1927 air Filter

B: 1-FL20513 Oil filter

C: 3 1/2 1 gallon engine oil

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Robert Willingham

Total Hours spent on Repair: 3

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 6/7/2022

Serial: 7722

Make: Ford

location: R/C

Model: F-350

Hours/Mileage: 44,250

Work performrd (print)

pressured washed and cleaned
inside of truck and cleaned up
shop

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Justin Garoufalias

Total Hours spent on Repair: 5

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 12/6/2021

Serial: 7722

Make: Ford

location: R/C

Model: F-350

Hours/Mileage: 43,850

Work performrd (print)
cleaned truck and shop

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)
Justin Garoufalias

Total Hours spent on Repair: 3

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 11/23/2021 Serial: 7722
Make: ford location: R/C
Model: f-350 Hours/Mileage: 43,850

Work performrd (print)
did service on truck fixed cables
on air compressor went and got
paint for keith, cleaned shop

Parts/supplies used (print)

A: 1- wa10679 air filter

B: 1- wf10458 fuel filter

C: 1- 57151 oil filter

D: 3- 1 gallon engine oil

E: 1- 1 quart engine oil

F: 2- battery cables
 2- copper lug's

Repaired Completed By (Mechanic-Print)
Justin Garoufalias

Total Hours spent on Repair: 8

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 8/18/2021

Serial: 7722

Make: Ford

location: R/C

Model: F-350

Hours/Mileage:

Work performrd (print)

Replaced cab filter

Parts/supplies used (print)

A: 1-Wp10266 cabin filter

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Justin Garoufalias

Total Hours spent on Repair: 1

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 7/28/2021

Serial: 7722

Make: Ford

location: R/C

Model: F-350

Hours/Mileage: 38,000

Work performrd (print)
washed and cleaned truck

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)
Justin Garoufalias

Total Hours spent on Repair: 1

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 7/7/2021 Serial: 7722
Make: ford location: R/C
Model: f-350 Hours/Mileage:

Work performrd (print)
Cleaned out back of truck installed seat
cover's and cleaned shop

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)
Justin Garoufalias

Total Hours spent on Repair: 6

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 6/30/2021

Serial: 7722

Make: Ford

location: R/C

Model: f-350

Hours/Mileage:

Work performrd (print)

Cleaned and washed truck out then
swapped tool's fron unit 7719 to unit
7722

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Justin Garoufalias,Danyel

Total Hours spent on Repair: 8

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 5/7/2021 Serial: 7722
Make: Ford location: R/C
Model: f-350 Hours/Mileage: 32,479

Work performrd (print)

Cleaned truck and washed and straightened
tool's and checked on pump's for service

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)
Rex Willinghm

Total Hours spent on Repair: 6

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 8/19/2020 Serial: 7722
Make: Ford location: R/C
Model: F-350 Hours/Mileage: 13,308
Work Performed (print)
Changed the Oil ,Oil Filter and Air Filter

Parts/supplies used (print)

A: 1- Wa10679 Air Filter

B: 1- 57151 Oil Filter

C: 3-! Gallon Rotella 15w40 motoroil

D: 1-Quart Rotella 15w40 motor oil

E:

F:

Repaired Completed By (Mechanic-Print)
Rex Willingham

Total Hours spent on Repair: 3

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Mechanic Equipment Repair Report

Date began: 7 / 3 / 19

Serial # 1FD8X3HTAJec27722

Make: ford

Location: Shop

Model: F350

Hours/Mileage: 4200

Work Performed (Print):

Worked on the Air compressor Belt Break installed
New belt Realigning

Parts/Supplies used (Print):

- A. _____
- B. _____
- C. _____
- D. _____
- E. _____
- F. _____
- G. _____
- H. _____

Repaired Completed By (Mechanic - Print):

Rex Willingham

Date completed: 7 / 3 / 19

Total hours spent on Repairs: 3 hr

In Service (Y/N) Y

Repairs complete (Y/N): Y

If No -

Explain: _____



Mechanic Equipment Repair Report

Date began: 1 / 25 / 19Serial # 1FD8X3HT05eca772aMake: ~~1088~~ FordLocation: ShopModel: F350Hours/Mileage: 3876**Work Performed (Print):**changed the oil and filter changed all fuel filters Air filters**Parts/Supplies used (Print):**

- A. _____
- B. _____
- C. _____
- D. _____
- E. _____
- F. _____
- G. _____
- H. _____

Repaired Completed By (Mechanic - Print):Rex WillinghamDate completed: 1/25/19Total hours spent on Repairs: 3 HrIn Service (Y/N) YRepairs complete (Y/N): Y

If No –

Explain: _____

Mechanic Equipment Repair Report

Date began: 10/26/18Serial # 7722Make: FORDLocation: Vidor shopModel: F350Hours/Mileage: 2646

Work Performed (Print):

Received metal to build a vise mount for service truck.
Took measurements. Cut mounting plate & smoothed out the edges.
Cut 2" square tubing too length. Cut a double 45° angle in 2" tubing.
Welded out & set a 90° angle @ base of mount. Mounted vise on mount &
cut holes. Ordered & received nuts & bolts.

Parts/Supplies used (Print):

A. (4) 9/16" x 2" bolts
B. (4) 1" nuts
C. (4) 1" flat washer

D. _____
E. _____
F. _____
G. _____
H. _____

Repaired Completed By (Mechanic - Print):

Hoyt Date completed: 10/26/18

Total hours spent on Repairs: 5.0In Service (Y/N) YRepairs complete (Y/N): Y

If No -

Explain: _____

