

**KILLAM:** 5907 51st Ave Killam, AB T0B 2L0 Phone: 780-385-3993 PROVOST: P.O. Box 299 3403 57 Ave Provost, AB T0B 3S0 Phone: 780-753-2278 WAINWRIGHT: 1601 - 23 Street Wainwright, AB T9W 1L2 Phone: 780-842-2171

CI-:	<b>T</b>		_
Ship	10:		

Invoice To:

. AB X0X 0X0

Branch					
KILLAM		*REPRI	NT*		
Date	Time				Page
01/22/25	22:	20:27			
Account No Phone No		o Inv No		lo	
Ship Via		Purchase C	Order		
Tax ID No					
			Sales	perso	n
				218	

#### **SERVICE INVOICE**

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS

C015691 X9 1100 COMBINE MY 1E 1H0X911XJP0825129 08/01/24

X9 1100 268 07/31/26 1250 X

GST# 895703353

SEGMENT# 1 C 248 NA 07/30/24 08/28/24

BRI INSPECTION

**CORRECTION:** 

began inspection

ran up

pulled off, parked in row

ADDITIONAL DESCRIPTION:

\*\*\*UNIT HAS BECOME THE PARTS DONOR MACHINE - INSPECTION

REPAIRS WILL BE HELD OFF FOR NOW.

**TY6341** GREASE 11.34 11.34 1 14M7299 M12 FLANGE NUT 4.06 4.06 5.70 19M7803 M8 X 70MM FLANG 1 5.70 PARTS 21.10 LABOR 2595.00 16001000 SEGMENT TOTAL ==> 2616.10

SEGMENT# 2 C 248 NA

12/31/24 01/07/25

CONTROL SYSTEM

CORRECTION: 2025-01-07

- -updated all software from service advisor.
- -cleared codes.
- -chaffer controller is not reading will have to trouble shoot.
- -created DTAC case 3161269 asking what software i may be missing to get chaffer controller working.
- -updated Gen 4 software over the internet.

CONTINUED ON PAGE 02

2.50 HRS

Signature:		
Sidnati iro:		



KILLAM: 5907 51st Ave Killam, AB T0B 2L0 Phone: 780-385-3993

PROVOST P.O. Box 299 3403 57 Ave Provost, AB T0B 3S0 Phone: 780-753-2278

WAINWRIGHT: 1601 - 23 Street Wainwright, AB T9W 1L2 Phone: 780-842-2171

Ship To:

Invoice To:

X0X 0X0 . AB

Branch					
KILLAM					
Date	Time				Page
01/22/25	22:	20:27	(B)		02
Account No	Phone No	,		Inv N	No
Ship Via		Purchase Order			
Tax ID No					
			Sale	sperso	n
				218	

#### SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS

C015691 X9 1100 COMBINE MY 1E 1H0X911XJP0825129 08/01/24

X9 1100 07/31/26 1250 X 268

-verified power and ground on CFDE

-DTAC reported back saying the HADC and HADE and CPMC need to be pushed.

-pushed all 3 payloads and the code cleared.

ADDITIONAL DESCRIPTION:

\*UPDATE 7 NEW PAYLOADS & CLEAR STORED CODES - UPDATE GEN 4 (2.5)

12/31/24

437.50 LABOR

16001000 SEGMENT TOTAL ==> 437.50

12/31/24

SEGMENT# 3 C 248 NA

FEEDER HOUSE AREA

**CORRECTION:** 

2025-01-08

-changed one large coupler that was leaking.

-changed prodrive filter.

- -found leak under feeder house it was a solenoid valve that was not tightened.
- -cleaned area and tightened valve checked for leaks and found it no longer leaked.

ADDITIONAL DESCRIPTION:

- \*CHANGE PRO DRIVE FILTER (.5) Done JL
- \*REPLACE MULTICOUPLER TOP LEFT LARGE COUPLER (LEAKING) (1)

\*RESEAL SOLONOID ON BOTTOM SIDE OF FEEDER HOUSE LEAKING

(??) Done JL

AXE73035 Hydr. Quick Cou 378.92 378.92

Hydr. Quick Coupler Socket

EF4663 RECYC FEE LONG 1.00 1.00

RE577250 1 144.07 144.07 TRANS FILTER

CONTINUED ON PAGE 03

1.50 HRS



**KILLAM:** 5907 51st Ave Killam, AB T0B 2L0 Phone: 780-385-3993 PROVOST: P.O. Box 299 3403 57 Ave Provost, AB T0B 3S0 Phone: 780-753-2278 **WAINWRIGHT:** 1601 - 23 Street Wainwright, AB T9W 1L2 Phone: 780-842-2171

Ship To:

Invoice To:			
	AB	xox	0X0

n .				
Branch				
KILLAM				
Date	Time			Page
01/22/25	2			
Account No	Phone No	ı	Inv	No
Ship Via		Purchase C	rder	
Tax ID No				
			Salespers	on
			218	3

## **SERVICE INVOICE**

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS

C015691 X9 1100 COMBINE MY 1E 1H0X911XJP0825129 08/01/24

X9 1100 268 07/31/26 1250 X

Hydraulic Filter

RE577612 Filter Element

PARTS 520.11

3.88-

LABOR 262.50

13.50 HRS

16001000 SEGMENT TOTAL==> 782.61

SEGMENT# 4 C 248 NA 12/31/24 12/31/24

LEFT HAND SIDE

CORRECTION:

JANUARY 7/2025

- \*CHOPPER TWO SPEED GEAR CASE CHANGE SIGHT GLASS TO PLUG -
- TOP UP OIL (1) --- [DONE] >> +18L HyGard
- \*CLEAN CAMERA & CHANGE DESSICANT (.5) --- [DONE]
- \*TAILING ELEVATOR CHAIN ADJUST TENSION (.75) --- [DONE]
- \*CHANGE HYDROSTATIC RETURN FILTER (.5) --- [DONE]
- \*CHANGE MAIN HYDRAULIC RESERVOIR FILTER (.5) --- [DONE]
- \*CHANGE MAIN ENGINE GEAR CASE FILTER (.5) --- [DONE]
- \*CHANGE HYDRAULIC CHARGE FILTER (.5) --- [DONE]
- \*REPLACE MISSING SHAFT SEAL AND BRACKET

(HXE172920) (.5) --- [DONE]

2025-01-14

- -diagnosed rear signals on unit.
- -both lights had diodes out replaced both lights with new
- lights and they were working good.
- -calibrated chaffer and sieve.
- -replaced #3 small wire concave with good concave.
- -reinstalled  ${\ensuremath{\mathtt{Z}}}\xspace$ -bar and levelled concaves and performed calibration.

ADDITIONAL DESCRIPTION:

\*REINSTALL, LEVEL & ZERO CONCAVES (5) Done JL

CONTINUED ON PAGE 04



**KILLAM:** 5907 51st Ave Killam, AB T0B 2L0 Phone: 780-385-3993 PROVOST: P.O. Box 299 3403 57 Ave Provost, AB T0B 3S0 Phone: 780-753-2278 WAINWRIGHT: 1601 - 23 Street Wainwright, AB T9W 1L2 Phone: 780-842-2171

Ship	То	

Invoice To:	
-------------	--

. AB X0X 0X0

Branch					
KILLAM					
Date	Time				Page
01/22/25	22:	20:27	(B)		04
Account No	,	Inv No			
Ship Via		Purchase Order			
Tax ID No					
		•	Sale	sperso	n
				218	

## **SERVICE INVOICE**

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS

C015691 X9 1100 COMBINE MY 1E 1H0X911XJP0825129 08/01/24

X9 1100 268 07/31/26 1250 X

- \*REPLACE #3 SMALL WIRE CONCAVE "WITH A GOOD USED ONE" (BROKEN BAR)
- \*REINSTALL & CALIBRATE CHAFFER & SEIVE (1) Done JL
- \*CHOPPER TWO SPEED GEAR CASE CHANGE SIGHT GLASS TO PLUG TOP UP OIL (1)
- \*DIAGNOSE AND ADVISE FRONT & BACK REAR SIGNALS (2) Done JL
- \*CLEAN CAMERA & CHANGE DESSICANT (.5)
- \*TAILING ELEVATOR CHAIN ADJUST TENSION (.75)
- \*CHANGE HYDROSTATIC RETURN FILTER (.5)
- \*CHANGE MAIN HYDRAULIC RESERVOIR FILTER (.5)
- \*CHANGE MAIN ENGINE GEAR CASE FILTER (.5)
- \*CHANGE HYDRAULIC CHARGE FILTER (.5)
- \*REPLACE MISSING SHAFT SEAL (HXE171189) AND BRACKET (HXE172920) (.5)
- \*CHANGE DESSICANT AND CLEAN CAMERAS (.5)

***(FYI) -#6 ]	HAS ONE BENT BAR***			
***(FYI) - BO'	TH STRAW SPREADER GEAR BOXS OUTPUT SIDE	SEALS		
(DE32519) LEA	KING (WARRANTY) ***			
AXE103407	Hydraulic Filte	1	135.87	135.87
	Hydraulic Filter			
AXE20532	Clip/SAFETY	1	19.86	19.86
	Track Chain W/O Shoes			
AXE73797	HYDRA FILTER	1	150.15	150.15
	Hydraulic Filter			
AXE73798	HYDRAULIC FILTE	1	184.83	184.83
	Hydraulic Filter			
EF4663	RECYC FEE LONG	5	1.00	5.00
HXE171189	Seal	1 N	70.13	70.13
HXE172920	Bracket	1 N	21.57	21.57
		CONTI	NUED ON PAG	E 05

N: 4		
Signature:		



**KILLAM:** 5907 51st Ave Killam, AB T0B 2L0 Phone: 780-385-3993 PROVOST:
P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

WAINWRIGHT: 1601 - 23 Street Wainwright, AB T9W 1L2 Phone: 780-842-2171

Ship	To:	
-		

Invoice To:

. AB X0X 0X0

Branch					
KILLAM					
Date	Time				Page
01/22/25	22:	20:27	(B)		05
Account No	Phone No			Inv N	lo
Ship Via		Purchase	Order		
Tax ID No					
			Sales	sperso	n
				218	

## **SERVICE INVOICE**

STK#/FLEET#		HRS PIN/EIN	WARRA	ANTY DATE	HRS
C015691	X9 1100 COMBINE MY	1E 1H0X911XJP08	25129	08/01/24	
	X9 1100	268		07/31/26	1250 X
KXE10744		Desiccant	1 S	314.53	314.53
RE577250		Hydraulic Filte	1	141.03	141.03
	Hydraulic Filt	er			
RE577612		Filter Element	1	175.89	175.89
RE592939		Lamp	2	86.62	173.24
R39112		FITTING	1	13.93	13.93
TY22539		HS16 CLAMP	3	1.60	4.80
				PARTS	1410.83
				LABOR	2362.50
	16001000		SEGMENT	TOTAL==>	3773.33

SEGMENT# 5 C 248

RIGHT HAND SIDE

12/31/24 12/31/24

7.50 HRS

# CORRECTION:

2025-01-14

- -removed and cleaned sediment bowl.
- -replaced desicant cartridge.
- -adjusted clean grain elevator tension.

2025-01-15

- -installed Z-bar and levelled and calibrated concaves.
- -replaced service lights on gull wings.
- -tensioned all belts.

#### ADDITIONAL DESCRIPTION:

- \*GULL WING SERVICE LIGHT OUT (1) Done JL
- \*CLEAN GRAIN ELEVATOR CHAIN ADJUST TENSION (.5) Done JL
- \*CLEAN WATER SEPERATOR (.5) Done JL
- \*CHANGE DESSICANT CLEAN CAMERAS (.5) Done BZ
- \*REINSTALL CONCAVES & ZBAR LEVEL & ZERO (5)

\*\*\*(FYI) - BATTERIES TESTED GOOD\*\*\*

CONTINUED ON PAGE 06

N: 4		
Signature:		



**KILLAM:** 5907 51st Ave Killam, AB T0B 2L0 Phone: 780-385-3993 PROVOST:
P.O. Box 299
3403 57 Ave
Provost, AB T0B 3S0
Phone: 780-753-2278

WAINWRIGHT: 1601 - 23 Street Wainwright, AB T9W 1L2 Phone: 780-842-2171

Ship	To:	
-		

Invoice To:

. AB X0X 0X0

Branch					
KILLAM					
Date	Time				Page
01/22/25	22:	20:27	(B)		06
Account No	Phone No			Inv N	10
Ship Via		Purchase	Order		,
Tax ID No					
			Sales	sperso	n
				218	

## **SERVICE INVOICE**

STK#/FLEET#		HRS PIN/EIN	WARRA	NTY DATE	HRS
C015691	X9 1100 COMBINE MY	1E 1H0X911XJP(	0825129	08/01/24	
	X9 1100	268		07/31/26	1250 X
EF4663		RECYC FEE LONG	1	1.00	1.00
KXE10744		Desiccant	1 S	314.53	314.53
R63679		RIVET	2	3.09	6.18
TA20308		Lamp	2 M	43.05	86.10
TY22062		HY-Gard 10L	1	83.11	83.11
14M7275		M12 NUT GR.10	1	1.15	1.15
14M7299		M12 FLANGE NUT	1	4.06	4.06
14M7360		M5 NYLON LOCK	4	1.07	4.28
19M7373		M5 X 20MM HEX	4	1.15	4.60
24H1283		WASHER	4	.46	1.84
				PARTS	506.85
				LABOR	1312.50
	16001000		SEGMENT '	TOTAL==>	1819.35

SEGMENT# 6 C 248 NA

MT :

\*\*\*\*\*\*\*\*\*\*\*

12/31/24 12/31/24

ENGINE COMPARTMENT

JANUARY 7/2025

**CORRECTION:** 

JANUARI //2025

- \*REPLACE DRAIN PLUG ON RADIATOR (1) --- [DONE]
- \*COOLANT TOP UP (.5) --- [DONE] + 3L CoolGard-II
- \*CHANGE OUTER ENGINE AIR FILTER AND CLEAN HOUSING (.5) --- [DONE]
- \*CHANGE ENGINE OIL & FILTER (1) --- [DONE] +54L of Plus50
- \*TOP UP ENGINE GEAR CASE OIL --- [DONE] approx. 10L HyGard
- \*CHANGE FUEL TANK BREATHER (.5) --- [DONE]
- \*CHANGE FUEL FILTERS (1) --- [DONE]
- \*CHANGE TRANSMISSION BREATHER (.5) --- {DONE}

2025-01-15

-topped main engine gear case added a jug of DEF to unit.

ADDITIONAL DESCRIPTION:

CONTINUED ON PAGE 07

5.00 HRS

N: 4		
Signature:		



KILLAM: 5907 51st Ave Killam, AB T0B 2L0 Phone: 780-385-3993

PROVOST P.O. Box 299 3403 57 Ave Provost, AB T0B 3S0 Phone: 780-753-2278

WAINWRIGHT: 1601 - 23 Street Wainwright, AB T9W 1L2 Phone: 780-842-2171

Ship T	o:	

Invoice To:			
	AB	xox	0X0

Branch					
KILLAM					
Date	Time				Page
01/22/25	22:	20:27	(B)		07
Account No	Phone No	1		Inv N	10
Ship Via		Purchase	Order		
Tax ID No					
		·	Sales	sperso	n
				218	

#### SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS C015691 X9 1100 COMBINE MY 1E 1H0X911XJP0825129 08/01/24 X9 1100 07/31/26 1250 X 268 \*REPLACE DRAIN PLUG ON RADIATOR (1) Done JL \*COOLANT - TOP UP (.5) Done BZ \*CHANGE OUTER ENGINE AIR FILTER AND CLEAN HOUSING (.5) Done BZ\*CHANGE ENGINE OIL & FILTER (1) Done BZ \*TOP UP ENGINE GEAR CASE OIL Done BZ \*CHANGE FUEL TANK BREATHER (.5) Done BZ \*CHANGE FUEL FILTERS (1) Done BZ \*CHANGE TRANSMISSION BREATHER (.5) Done BZ 147.72 295.44 AR69444 HY-GARD 18.9L 2 AT13740 8.83 DRAIN VALV 1 8.83 AXE82230 Breather 1 113.03 113.03 DZ124761 Filter Element 1 147.30 147.30 1 DZ124786 Filter Element 141.51 141.51 .50 EF4662 RECYC FEE SHORT 1 .50 EF4663 3 1.00 3.00 RECYC FEE LONG 5 EF4666 2.00 10.00 RECYC FEE OIL HXE11090 OUTER AIR FILTE 1 416.65 416.65 1 36.87 36.87 H216169 BREATHER RE572785 OIL FILTER 1 136.64 136.64 1 SWDEF025 DIESEL EXHAUST 20.99 20.99 Diesel Exhaust Fluid (DEF) 3 TY26679 15W40 18.9L 159.28 477.84 Plus-50 II Oil 15W40 CJ4/SN PARTS 1808.60 875.00 LABOR 16001000 SEGMENT TOTAL ==> 2683.60 SEGMENT# 7 C 248 NA 12/31/24 12/31/24

CAB SECTION

.50 HRS CONTINUED ON PAGE 08

Signature:	



KILLAM: 5907 51st Ave Killam, AB T0B 2L0 Phone: 780-385-3993

PROVOST P.O. Box 299 3403 57 Ave Provost, AB T0B 3S0 Phone: 780-753-2278

WAINWRIGHT: 1601 - 23 Street Wainwright, AB T9W 1L2 Phone: 780-842-2171

Ship	To:	
-		

Invoice To:

X0X 0X0 . AB

- I					
Branch					
KILLAM					
Date	Time				Page
01/22/25	22:	20:27	(B)		08
Account No	Phone No	ı		Inv N	10
Ship Via		Purchase	Order		
Tax ID No					
			Sales	sperso	n
				218	

## SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS C015691 X9 1100 COMBINE MY 1E 1H0X911XJP0825129 08/01/24 X9 1100 268 07/31/26 1250 X \*CHANGE CAB AIR FILTERS (.5) \*TOP UP WASHER FLUID \*\*\*(FYI) - TOP MIRROR LHS MISSING (THIS IS ON ORDER ON ANOTHER W/O) \*\*\* AXE70605 35.31 35.31 AIR FILTER 1 TA32591 Air Filter 1 109.84 109.84 145.15 PARTS LABOR 87.50 16001000 232.65 SEGMENT TOTAL ==> SEGMENT# 8 C 248 NA 12/31/24 01/16/25 BP15 HEADER SN#825224 1.50 HRS **CORRECTION:** 2025-01-16 -adjusted auger height and adjusted rear stripper.

- -adjusted tire pressures.
- -adjusted air bags.

# ADDITIONAL DESCRIPTION:

- \*ADJUST FEED AUGER HEIGHT & FINGER TIMING (1)
- \*ADJUST TIRE PRESSURES (.5)

SEGMENT TOTAL ==>

16001000 262.50

SEGMENT# 9 C 248 NA 12/31/24 01/15/25

2.00 HRS

LABOR

RUN AND CHECK CORRECTION:

2025-01-15

- -took unit out of shop and ran up 20 minutes at each speed.
- -brought unit int shop and reinstalled shields.

CONTINUED ON PAGE 09

SERVICE AUTHORIZATION & TERMS: I authorize the above work to be performed and approve the use of any necessary materials. I understand that Battle River Implements and its employees may operate the equipment for testing, inspection, or delivery at my risk. I agree to pay in full before the equipment is released from your possession. Battle River Implements is not responsible for loss or damage due to theft or fire while the machine is in our care for storage, sale, repair, or field testing. Equipment left for more than 30 days after the completion date may be subject to storage fees.

N: 4		
Signature:		

262.50



**KILLAM:** 5907 51st Ave Killam, AB T0B 2L0 Phone: 780-385-3993 PROVOST: P.O. Box 299 3403 57 Ave Provost, AB T0B 3S0 Phone: 780-753-2278 **WAINWRIGHT:** 1601 - 23 Street Wainwright, AB T9W 1L2 Phone: 780-842-2171

Ship	To:		

Invoice To:

. AB X0X 0X0

Branch					
KILLAM					
Date	Time				Page
01/22/25	22:	20:27	(B)		09
Account No	Phone No	ı		Inv N	lo .
Ship Via		Purchase	Order		<u> </u>
Tax ID No					
			Sales	sperso	n
				218	

## **SERVICE INVOICE**

STK#/FLEET#		HRS PIN/EIN	WARR.	ANTY DATE	HRS	
C015691	X9 1100 COMBINE MY	1E 1H0X911XJP	0825129	08/01/24		
	X9 1100	268		07/31/26	1250 X	
-checked a	nd adjusted fluid le	vels.				
-took unit	and crate out of she	op.				
ADDITIONAL	DESCRIPTION:					
RUN AND CH	ECK					
A15147		SPRING LOC	2	3.20	6.40	
	Spring Locking	Pin				
HXE157294		Plate	1	22.55	22.55	
HXE167838		Knob	1	11.54	11.54	
24H1305		3/8 FLATWASHER	2	.47	.94	
				PARTS	41.43	
				LABOR	350.00	
	16001000		SEGMENT	TOTAL==>	391.43	

PARTS 4454.07
SERV ACCESORIES 100.00 INTERNAL TOTAL 13099.07

Signature:		