

03939766

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba G03-3

Vehicle Standards and Inspections
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5G7
1-204-985-9920

Manitoba DECAL

Date Inspection Started: 07 DAY, 07 MO, 25 YR.
Date Inspection Completed: 18 DAY, 07 MO, 25 YR.
Inspection Expiry Date: 31 DAY, 07 MO, 26 YR.

Station Number: A5343
Station Name: Allscape LTD
Mechanic Number: M0394
Mechanic Signature: [Signature]
Station Phone Number: 204 275 2444
Vehicle Owner: Allscape LTD
Address: Box 575 LA SALLE MB
City: LA SALLE Province: MB Postal Code: R0G-1B0 Phone: 204 261 1800

Pass/Safe Vehicle Fail/Unsafe Vehicle Fail/Hazardous
Licence Number: CJW 0166 Prov. MB NSC # MB 9452533 Odometer Reading: 89 361 Odom. Type: km mi
Vehicle Identification Number: 1FDY686F0WVA05357 Make: Ford Model: Dump Year: 98 Unit #: 02
 Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Section 1 - Power Train: Defects (if any) 2E - Muffler clamp loose
Section 2 Suspension: Defects (if any)
Section 3 - Brake Systems: 3H (3A) Defects (if any) 2G - Air leak 16C - Clevis Pin missing Cotter Pin
Section 4 - Steering: Defects (if any)
Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
Section 6 - Lamps: Defects (if any)
Section 7 - Electrical System: Defects (if any)
Section 8 - Body: Defects (if any) 13B - Windshield Broken
Section 9 - Tire & Wheel: Defects (if any)

Brake Inspection Type: A (B) C D E
Table with columns: Axle, Lining (L, R), Drum/Rotor (L, R), Stroke (L, R).
Row 1: 1, 2/16, 4/16, 16.539, 16.541, 1 3/8, 1 3/8
Row 2: 2, 4/16, 4/16, 16.544, 16.543, 2 1/4, 2 1/4
Row 3: 3, 4/16, 4/16, 16.540, 16.547, 2 1/2, 2 1/2
Row 4: 4
Row 5: 5
Final Measurement

32nd Tread Depth 95V Air Pressure
Table with columns: Axle, L, R, Corrected L, Corrected R, Initial L, Initial R, Corrected L, Corrected R.
Row 1: 1, 18, 15, , , 105, 105, ,
Row 2: 2, 12, 13, 12, 12, 100, 100, 100, 100
Row 3: 3, 8, 8, 13, 7, 100, 100, 100, 100
Row 4: 4
Row 5: 5

Section 10 - Coupling Devices: Defects (if any) 13C - Pintle Hitch Worn Out

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

PRESENT THIS COPY WHEN REGISTERING VEHICLE