

04080361

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba 607-6

Vehicle Safety Box 4504 Regent Post Office Winnipeg, MB, R2C 5C7 1-204-985-0920

Manitoba DECAL

Date Inspection Started: 26 03 26
 Date Inspection Completed: 27 03 26
 Inspection Expiry Date: 31 03 27

Station Number: A11231
 Station Name: MARION TRUCKING LTD WPG
 City: WPG
 Station Phone Number: 204-237-3171

Mechanic Number: M1510514
 Mechanic Signature: [Signature]
 Station Phone Number: 204-237-3171

Vehicle Owner: MARION TRUCKING LTD
 Address: 578 McTAVISH ST WPG
 City: WPG
 Province: MB
 Postal Code: R2J0E6
 Phone: 237-3171

Pass/Safe Vehicle
 Fail/Unsafe Vehicle
 Fail/Hazardous

Licence Number: 1MOT
 Prov.:
 NSC #:
 Odometer Reading: 317810
 Odom. Type: km ml

Vehicle Identification Number: 1F1MH1CY1B59C1HBP718162
 Make: Freightliner
 Model: M2
 Year: 12
 Unit #:

Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ^{CLWR} 23587 KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																																																										
X		Section 1 - Power Train: Defects (if any)																																																																																																										
X		Section 2 Suspension: Defects (if any)																																																																																																										
X		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type Brake Inspection Type: A B C D E Circle appropriate letter for Internal Brake Component Inspection																																																																																																										
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">mm Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">cm Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>17</td> <td>16</td> <td></td> <td></td> <td>3 1/2</td> <td>3 1/2</td> </tr> <tr> <td>2</td> <td>16</td> <td>15</td> <td></td> <td></td> <td>4</td> <td>4</td> </tr> <tr> <td>3</td> <td>16</td> <td>10</td> <td></td> <td></td> <td>4</td> <td>4</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	mm Lining		Drum/Rotor		cm Stroke		L	R	L	R	L	R	1	17	16			3 1/2	3 1/2	2	16	15			4	4	3	16	10			4	4	4							5																																																																
Axle	mm Lining			Drum/Rotor		cm Stroke																																																																																																						
	L	R	L	R	L	R																																																																																																						
1	17	16			3 1/2	3 1/2																																																																																																						
2	16	15			4	4																																																																																																						
3	16	10			4	4																																																																																																						
4																																																																																																												
5																																																																																																												
X		Section 4 - Steering: Defects (if any)																																																																																																										
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																																																										
X		Section 6 - Lamps: Defects (if any)																																																																																																										
X		Section 7 - Electrical System: Defects (if any)																																																																																																										
X		Section 8 - Body: Defects (if any)																																																																																																										
X	X	Section 9 - Tire & Wheel: Defects (if any) 4A CORRECTED TIRES PSI																																																																																																										
		<table border="1"> <thead> <tr> <th rowspan="3">Axle</th> <th colspan="6">mm Tread Depth</th> <th colspan="6">PSI Air Pressure</th> </tr> <tr> <th colspan="3">Initial</th> <th colspan="3">Corrected</th> <th colspan="3">Initial</th> <th colspan="3">Corrected</th> </tr> <tr> <th>L</th> <th>R</th> <th></th> <th>L</th> <th>R</th> <th></th> <th>L</th> <th>R</th> <th></th> <th>L</th> <th>R</th> <th></th> </tr> </thead> <tbody> <tr> <td>1</td> <td>19</td> <td></td> <td>20</td> <td>19</td> <td></td> <td>20</td> <td>100</td> <td></td> <td>110</td> <td>110</td> <td></td> <td>110</td> </tr> <tr> <td>2</td> <td>10</td> <td>10</td> <td>9</td> <td>11</td> <td>10</td> <td>10</td> <td>95</td> <td>95</td> <td>85</td> <td>90</td> <td>110</td> <td>110</td> <td>110</td> </tr> <tr> <td>3</td> <td>10</td> <td>10</td> <td>10</td> <td>11</td> <td>10</td> <td>10</td> <td>100</td> <td>100</td> <td>95</td> <td>95</td> <td>110</td> <td>110</td> <td>110</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	mm Tread Depth						PSI Air Pressure						Initial			Corrected			Initial			Corrected			L	R		L	R		L	R		L	R		1	19		20	19		20	100		110	110		110	2	10	10	9	11	10	10	95	95	85	90	110	110	110	3	10	10	10	11	10	10	100	100	95	95	110	110	110	4														5													
Axle	mm Tread Depth						PSI Air Pressure																																																																																																					
	Initial			Corrected			Initial			Corrected																																																																																																		
	L	R		L	R		L	R		L	R																																																																																																	
1	19		20	19		20	100		110	110		110																																																																																																
2	10	10	9	11	10	10	95	95	85	90	110	110	110																																																																																															
3	10	10	10	11	10	10	100	100	95	95	110	110	110																																																																																															
4																																																																																																												
5																																																																																																												
X		Section 10 - Coupling Devices: Defects (if any)																																																																																																										

- THIS INSPECTION IS NOT A WARRANTY -
 This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: Brake Inspection Done 24/02/25 # A793340

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
 Signature