

Date Inspection Started: 10/02/26
 Station Number: A112311
 Station Name: Marion Trucking LTD WPG
 City: WPG
 Date Inspection Completed: 10/02/26
 Mechanic Number: M10255
 Mechanic Signature: [Signature]
 Station Phone Number: 204-237-3171
 Inspection Expiry Date: 2/8/02/27
 Vehicle Owner: Marion Trucking LTD
 Address: 578 McLaughlin ST WPG MB
 Postal Code: R2J 2E6
 Phone: 204-237-3171

Pass/Safe Vehicle License Number: NOT
 Fail/Unsafe Vehicle Vehicle Identification Number: 1FVHEHC481EHFM59110
 Confirmed legible Vehicle Identification Number on vehicle
 Odometer Reading: 581,704
 Make: Freightliner
 Model: M2
 Year: 14
 Unit #: []

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED
 Truck ^{aywr} 254101 KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark 'X' under 'R' when item Rejected 'XX' under 'R' when item Hazardous 'X' under 'P' when item Corrected or No Defects found in Section																																																																						
X		Section 1 - Power Train: Defects (if any)																																																																						
X		Section 2 Suspension: Defects (if any)																																																																						
X		Section 3 - Brake Systems: 3H (3A) Brake Inspection Type: (A) B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																						
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">mm Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">cm Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>16</td> <td>16</td> <td>16.502</td> <td>16.508</td> <td>3 1/2</td> <td>3 1/2</td> </tr> <tr> <td>2</td> <td>18</td> <td>18</td> <td>16.510</td> <td>16.507</td> <td>4</td> <td>4</td> </tr> <tr> <td>3</td> <td>16</td> <td>16</td> <td>16.545</td> <td>16.513</td> <td>4</td> <td>4</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	mm Lining		Drum/Rotor		cm Stroke		L	R	L	R	L	R	1	16	16	16.502	16.508	3 1/2	3 1/2	2	18	18	16.510	16.507	4	4	3	16	16	16.545	16.513	4	4	4							5																												
Axle	mm Lining			Drum/Rotor		cm Stroke																																																																		
	L	R	L	R	L	R																																																																		
1	16	16	16.502	16.508	3 1/2	3 1/2																																																																		
2	18	18	16.510	16.507	4	4																																																																		
3	16	16	16.545	16.513	4	4																																																																		
4																																																																								
5																																																																								
X		Section 4 - Steering: Defects (if any)																																																																						
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																						
X	X	Section 6 - Lamps: Defects (if any) 1C Tail Lamps B/S 1K back up Lamp R/S																																																																						
X		Section 7 - Electrical System: Defects (if any)																																																																						
X		Section 8 - Body: Defects (if any)																																																																						
X		Section 9 - Tire & Wheel: Defects (if any)																																																																						
		<table border="1"> <thead> <tr> <th rowspan="3">Axle</th> <th colspan="4">mm Tread Depth</th> <th colspan="4">PSI Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>10</td> <td>12</td> <td>10</td> <td>12</td> <td>110</td> <td>110</td> <td>110</td> <td>110</td> </tr> <tr> <td>2</td> <td>7</td> <td>8</td> <td>8</td> <td>11</td> <td>7</td> <td>8</td> <td>8</td> <td>11</td> </tr> <tr> <td>3</td> <td>8</td> <td>10</td> <td>8</td> <td>9</td> <td>8</td> <td>10</td> <td>8</td> <td>9</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	mm Tread Depth				PSI Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	10	12	10	12	110	110	110	110	2	7	8	8	11	7	8	8	11	3	8	10	8	9	8	10	8	9	4									5								
Axle	mm Tread Depth				PSI Air Pressure																																																																			
	Initial			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1	10	12	10	12	110	110	110	110																																																																
2	7	8	8	11	7	8	8	11																																																																
3	8	10	8	9	8	10	8	9																																																																
4																																																																								
5																																																																								
X		Section 10 - Coupling Devices: Defects (if any)																																																																						

- THIS INSPECTION IS NOT A WARRANTY -
 This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.
 Vehicle received without repairs by: _____ Date: _____
 Signature: _____