

04010283

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba

C001405

Date Inspection Started 23 09 25
DAY MO. YR.

Date Inspection Completed 03 10 25
DAY MO. YR.

Inspection Expiry Date 31 10 26
DAY MO. YR.

Station Number A4104 Station Name Cando Rail/Terminals B
City
Mechanic Number M0765 Mechanic Signature Dan Talford
Station Phone Number 204-726-4545

Vehicle Owner Cando Rail/Terminals
Unit C410 Vic Ave Brandon M.B. R7B-047 204-725-2627
Address City Province Postal Code Phone

☐ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☒ Fail/Hazardous

Licence Number CER792

Prov. M.B.

NSC # 9094071

Odometer Reading 242,587

Odom. Type ☒ km ☐ mi

Vehicle Identification Number

1H7MHAAL07H468250

Make Inter

Model 4700

Year 07

Unit # 100-67

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

☒ Truck ^{GVWR} 33000 KGS ☐ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X	X	Section 1 - Power Train: Defects (if any) #4 Drive Shaft "A" Vertical/Horizontal Movement Detected
X	XX	Section 2 Suspension: Defects (if any) #4 Spring "A" Cracked #7 Shock Absorber "C" 1st & 2nd Level
X	X	Section 3 - Brake Systems: 3H 3A #15 Drum Brake System Components "B" Brake Shoe Lining Cracked Wheel Speed Sensor Inoperative
X		Section 4 - Steering: Defects (if any)
X	X	Section 5 - Instruments & Auxiliary Equipment: Defects (if any) #7 Wind Shield Washer Pump Inoperative
X	X	Section 6 - Lamps: Defects (if any) #1 Required Lamps "H" Side Marker Lamp Inoperative #4 Instrument Panel Lamp Inoperative
X		Section 7 - Electrical System: Defects (if any)
X	X	Section 8 - Body: Defects (if any) #19 Seat "A" Condition Loose Covering material
X	X	Section 9 - Tire & Wheel: Defects (if any) #6 Wheel Bearings "B" Condition Roughness Detected

Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	18mm	20mm	420mm	420mm	30mm	30mm
2	20mm	20mm	420mm	420mm	30mm	30mm
3						
4						
5						
Final Measurement						

	Tread Depth				RST	Air Pressure			
	Initial		Corrected			Initial		Corrected	
Axle	L	R	L	R	L	R	L	R	
1		11mm 12mm				92 90		110 110	
2	17mm 16mm	12mm 11mm	30mm 30mm		92 94	100 88	110 110	110 110	
3									
4									
5									

Section 10 - Coupling Devices: Defects (if any)

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not