

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost	
<b>Unit No: Z1375 - 2020 ELGIN ESS-1967-HD2</b>											
10-Dec-2020	1	0	0	476386	03-013-022	Replace Glad Hands (Service/Emergency)	17-Dec-2020 11:27:33	BTRLR	C	DON	7.82
10-Dec-2020	1	0	0	476386	03-078-009	Replace Mud Flaps and Hanger Brackets	17-Dec-2020 12:17:40	BTRLR	C	DON	51.95
10-Dec-2020	1	0	0	476386	06-100-DOT	Inspect DOT Federal Inspection	17-Dec-2020 14:30:07	BTRLR	P	DON	25.19
10-Dec-2020	1	0	0	476386	06-100-PMA	Inspect A PMI	17-Dec-2020 14:51:32	BTRLR	P	DON	60.68
10-Dec-2020	1	0	0	476386	13-094	Assemble Lines, Tubes, Hoses & Fittings - Bulk	16-Mar-2021 09:56:26	BDDRIL	Q	DON	1.48
10-Dec-2020	1	0	0	476386	14-053-005	Install Markings - Vehicle - Decals	16-Dec-2020 17:00:01	BDECAL	C	DON	225.43
10-Dec-2020	1	0	0	476386	14-053-013	Install Permit Holder	17-Dec-2020 13:27:22	BTRLR	C	DON	18.94
10-Dec-2020	1	0	0	476386	14-053-101	Install License Plate	17-Dec-2020 17:32:24	BTRLR	C	DON	71.36
10-Dec-2020	1	0	0	476386	14-063-003	Install Transceiver - GPS Tracker	17-Dec-2020 14:07:42	BTRLR	Q	DON	343.47
10-Dec-2020	1	0	0	476386	24-018-005	Repair Bearings - General	17-Dec-2020 17:01:53	BTRLR	C	DON	152.69
04-Jun-2021	1	118	10	510808	02-071	Clean Body	09-Jun-2021 12:15:06	BWASH	N	DON	325.06
04-Jun-2021	1	118	10	510808	06-100-PMA	Inspect A PMI	30-Jul-2021 16:20:32	SCHED	P	DON	0.00
04-Jun-2021	1	118	10	510808	06-712	Inspect Centrifuge	26-Jul-2021 12:45:52	BDDRIL	N	DON	617.95
04-Jun-2021	1	118	10	510808	18-712	Test Centrifuge	22-Jul-2021 17:04:47	BDDRIL	N	DON	309.94
04-Jun-2021	1	118	10	510808	38-100-PMA	Service A PMI	30-Jul-2021 16:20:19	BDDRIL	P	DON	30.18
16-Mar-2022	1	57	27	575009	03-034-010	Replace Socket - Trailer Light Cord	17-Mar-2022 07:50:39	BTRLR	I	DON	35.97
16-Mar-2022	1	57	27	575009	03-079-009	Replace Tape - Reflective, Conspicuity	17-Mar-2022 09:15:36	BTRLR	I	DON	246.84
16-Mar-2022	1	57	27	575009	06-100-DOT	Inspect DOT Federal Inspection	17-Mar-2022 09:14:15	BTRLR	P	DON	60.24
16-Mar-2022	1	57	27	575009	06-100-PMA	Inspect A PMI	17-Mar-2022 09:12:15	BTRLR	P	DON	105.89
16-Mar-2022	1	57	27	575009	24-013-022	Repair Glad Hands (Service/Emergency)	17-Mar-2022 07:24:02	BTRLR	I	DON	33.45
07-Apr-2022	1	59	28	580417	24-049	Repair Electronic Management System	17-May-2022 12:16:37	BDDRIL	O	DON	1,792.56
07-Apr-2022	1	59	28	580417	24-712-005	Repair Plows / Internal Components	17-May-2022 12:16:42	BDDRIL	I	DON	2,504.16
10-Aug-2022	1	67	35	608620	03-047-001	Replace Engine Filter Kits	10-Aug-2022 12:44:34	BDDRIL	O	DON	92.79
14-Sep-2022	0	69	37	616221	03-712-005	Replace Plows / Internal Components	14-Sep-2022 08:35:40	BDDRIL	O	DON	1,314.69
16-Nov-2022	1	73	41	633043	24-712	Repair Centrifuge	16-Nov-2022 13:46:38	BDDRIL	O	DON	6,151.89
12-Jan-2023	1	77	44	644749	18-712	Test Centrifuge	12-Jan-2023 16:13:59	BDDRIL	E	DON	2,094.94
19-Sep-2023	1	95	58	706488	06-100-DOT	Inspect DOT Federal Inspection		BDDRIL	P	CAN	0.00
19-Sep-2023	1	95	58	706488	06-100-PMA	Inspect A PMI	25-Sep-2023 10:36:31	BDDRIL	P	DON	9.86
19-Sep-2023	1	95	58	706488	06-712	Inspect Centrifuge	25-Sep-2023 10:36:16	BDDRIL	N	DON	143.90

# Unit Job History

Michels Corporation

Report Printed: 04-Feb-2026 10:44:11 By User: VRIES

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: Z1375 - 2020 ELGIN ESS-1967-HD2</b>										
19-Sep-2023 1	95	58	706488	18-712	Test Centrifuge	29-Sep-2023 14:02:34	BDDRIL	N	DON	417.04
19-Sep-2023 1	95	58	706488	24-097-001	Repair Centrifugal Pump - Product Discharge	25-Sep-2023 10:38:14	BDDRIL	I	DON	461.35
19-Sep-2023 1	95	58	706488	24-712-003	Repair Plumbing	22-Sep-2023 14:01:11	BDDRIL	I	DON	599.02
19-Sep-2023 1	95	58	706488	24-712-006	Repair Frame / Chassis	21-Sep-2023 08:40:51	BDDRIL	I	DON	229.69
19-Sep-2023 1	95	58	706488	38-100-PMA	Service A PMI	21-Sep-2023 16:50:01	BDDRIL	P	DON	443.39
21-Nov-2023 1	99	61	722134	01-013-017	Adjust Slack Adjuster	27-Nov-2023 11:54:05	BDDRIL	I	DON	83.52
21-Nov-2023 1	99	61	722134	03-018-012	Replace Cap - Hub	27-Nov-2023 09:39:22	BDDRIL	I	DON	118.86
21-Nov-2023 1	99	61	722134	06-100-DOT	Inspect DOT Federal Inspection	27-Nov-2023 14:32:09	BDDRIL	P	DON	61.43
21-Nov-2023 1	99	61	722134	06-100-PMA	Inspect A PMI	27-Nov-2023 12:58:08	BDDRIL	P	DON	95.18
21-Nov-2023 1	99	61	722134	19-034-022	Wire/Rewire Harness - Main	27-Nov-2023 07:46:53	BDDRIL	I	DON	591.33
25-Feb-2025 1	123	82	818876	03-063-003	Replace Transceiver - GPS Tracker	25-Feb-2025 15:55:32	ELEC06	Q	DON	412.69
02-Feb-2026 1	123	82	897333	24-034-004	Repair Clearance & Marker Lamps	02-Feb-2026 16:19:52	LOMMAR	N	DON	17.12
02-Feb-2026 1	123	82	897333	OS-100-DOT	Out-Service DOT Federal Inspection	02-Feb-2026 17:00:02	LOMMAR	N	DON	68.30

Unit No: Z1375

Count: 42

20,428.23