

03974251

PERIODIC MANDATORY VEHICLE  
INSPECTION CERTIFICATE

Manitoba



JO2-1

Vehicle Standards and Ins  
Box 45064 Regent Postal C  
Winnipeg, MB, R2C 5C7  
1-204-985-0920

Manitoba



A966814

Date Inspection Started DAY: 08 MO: 04 YR: 25	Station Number A161049	Station Name Thompson Bus & Freight Ltd.	City Winnipeg
Date Inspection Completed DAY: 09 MO: 14 YR: 25	Mechanic Number M1451315	Mechanic Signature A. J. A. J.	Station Phone Number 204-985-5512
Inspection Expiry Date DAY: 31 MO: 10 YR: 25	Vehicle Owner Thompson Bus & Freight Ltd.		
Address		City	Province
Postal Code		Phone	
<input checked="" type="checkbox"/> Pass/Safe Vehicle <input type="checkbox"/> Fail/Unsafe Vehicle <input type="checkbox"/> Fail/Hazardous	Licence Number A161049	Prov. MB	NSC # 113195007
Vehicle Identification Number 2A01133490011028902		Make Ford	Model F43-45
Confirmed legible Vehicle Identification Number on vehicle		Year 2001	Unit # T00000
Odometer Reading 90,584		Odom. Type km	

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☒ GVWR ☒ KGS ☐ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☒ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																							
X		Section 1 - Power Train: Defects (if any)																																																																							
	X	Section 2 Suspension: Defects (if any) <i>Reinforce Brakes</i>																																																																							
X		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type																																																																							
		Brake Inspection Type: A B C <input checked="" type="radio"/> D E Circle appropriate Letter for Internal Brake Component Inspection																																																																							
		<table border="1"><thead><tr><th rowspan="2">Axle</th><th colspan="2">Lining</th><th colspan="2">Drum/Rotor</th><th colspan="2">Stroke</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>14.0</td><td>14.0</td><td>40.2</td><td>40.1</td><td></td><td></td></tr><tr><td>2</td><td>15.0</td><td>15.1</td><td>40.2</td><td>40.2</td><td></td><td></td></tr><tr><td>3</td><td>15.0</td><td>15.0</td><td>40.3</td><td>40.3</td><td></td><td></td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td colspan="7">Final Measurement</td></tr></tbody></table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	14.0	14.0	40.2	40.1			2	15.0	15.1	40.2	40.2			3	15.0	15.0	40.3	40.3			4							5							Final Measurement																						
Axle	Lining			Drum/Rotor		Stroke																																																																			
	L	R	L	R	L	R																																																																			
1	14.0	14.0	40.2	40.1																																																																					
2	15.0	15.1	40.2	40.2																																																																					
3	15.0	15.0	40.3	40.3																																																																					
4																																																																									
5																																																																									
Final Measurement																																																																									
X		Section 4 - Steering: Defects (if any)																																																																							
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																							
X		Section 6 - Lamps: Defects (if any)																																																																							
X		Section 7 - Electrical System: Defects (if any)																																																																							
X		Section 8 - Body: Defects (if any)																																																																							
X	X	Section 9 - Tire & Wheel: Defects (if any) <i>Tire and wheels</i>																																																																							
		<table border="1"><thead><tr><th rowspan="2">Axle</th><th colspan="4">Tread Depth</th><th colspan="4">Air Pressure</th></tr><tr><th colspan="2">Initial</th><th colspan="2">Corrected</th><th colspan="2">Initial</th><th colspan="2">Corrected</th></tr><tr><th></th><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>14.4</td><td>9.6</td><td></td><td></td><td>100</td><td>100</td><td></td><td></td></tr><tr><td>2</td><td>12.8</td><td>12.5</td><td>12.1</td><td>12.9</td><td>100</td><td>100</td><td>100</td><td>100</td></tr><tr><td>3</td><td>12.0</td><td>12.0</td><td></td><td></td><td>100</td><td>100</td><td></td><td></td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></tbody></table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	14.4	9.6			100	100			2	12.8	12.5	12.1	12.9	100	100	100	100	3	12.0	12.0			100	100			4									5								
Axle	Tread Depth				Air Pressure																																																																				
	Initial		Corrected		Initial		Corrected																																																																		
	L	R	L	R	L	R	L	R																																																																	
1	14.4	9.6			100	100																																																																			
2	12.8	12.5	12.1	12.9	100	100	100	100																																																																	
3	12.0	12.0			100	100																																																																			
4																																																																									
5																																																																									
		Section 10 - Coupling Devices: Defects (if any)																																																																							

THIS INSPECTION IS NOT A WARRANTY -  
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: \_\_\_\_\_ Signature

Date: \_\_\_\_\_

FVS0022-01-(R-09/15)

Ce document peut être obtenu en français sur demande.

COPY IN CAB - PLEASE ENSURE CERTIFICATE IS SIGNED - NOT FOR REGISTRATION