

04063351

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Centre
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba

C048446

Date Inspection Started DAY: 23 MO: 02 YR: 26	Station Number A2019	Station Name R Lewandowski Farms	City Sandy Beach		
Date Inspection Completed DAY: 24 MO: 02 YR: 26	Mechanic Number M9415	Mechanic Signature <i>[Signature]</i>	Station Phone Number 204-585-2120		
Inspection Expiry Date DAY: 28 MO: 02 YR: 27	Vehicle Owner Charene M Lewandowski				
Address		City	Province	Postal Code	Phone
☒ Pass/Safe Vehicle ☒ Fail/Unsafe Vehicle ☐ Fail/Hazardous	Licence Number TE4081	Prov. MB	NSC #	Odometer Reading	Odom. Type ☐ km ☐ mi
Vehicle Identification Number 2DIEGBSA2681024161		Make Dodge	Model Gran	Year 08	Unit #
☒ Confirmed legible Vehicle Identification Number on vehicle					

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GVWR KGS Truck Tractor Trailer ☒ Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																																					
☒		Section 1 - Power Train: Defects (if any)																																																																																					
☒		Section 2 Suspension: Defects (if any)																																																																																					
☒	☒	Section 3 - Brake Systems: 3H (3A) 3A(20-a) axle Defects (if any) Circle Brake Type 2 LR abs sensor 3A(15-B) axle 2 L lining worn 3A(15-D) axle 2 L drum worn 3A(16-a) axle 2 L ABS Cam condition																																																																																					
		Brake Inspection Type: (A) B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																																					
		<table><thead><tr><th rowspan="2">Axle</th><th colspan="2">mm Lining</th><th colspan="2">Drum/Rotor</th><th colspan="2">Stroke</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>17</td><td>17</td><td>16.540</td><td>16.566</td><td>1.5</td><td>1.5</td></tr><tr><td>2</td><td>new</td><td>16</td><td>new</td><td>16.553</td><td>1.5</td><td>1.5</td></tr><tr><td>3</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td colspan="7">Final Measurement</td></tr></tbody></table>	Axle	mm Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	17	17	16.540	16.566	1.5	1.5	2	new	16	new	16.553	1.5	1.5	3							4							5							Final Measurement																																				
Axle	mm Lining			Drum/Rotor		Stroke																																																																																	
	L	R	L	R	L	R																																																																																	
1	17	17	16.540	16.566	1.5	1.5																																																																																	
2	new	16	new	16.553	1.5	1.5																																																																																	
3																																																																																							
4																																																																																							
5																																																																																							
Final Measurement																																																																																							
☒		Section 4 - Steering: Defects (if any)																																																																																					
☒		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																																					
☒	☒	Section 6 - Lamps: Defects (if any) 6(1-D) left rear brake light (3/6 LED working)																																																																																					
☒		Section 7 - Electrical System: Defects (if any)																																																																																					
☒		Section 8 - Body: Defects (if any)																																																																																					
☒		Section 9 - Tire & Wheel: Defects (if any)																																																																																					
		<table><thead><tr><th rowspan="3">Axle</th><th colspan="4">mm Tread Depth</th><th colspan="4">Air Pressure</th></tr><tr><th colspan="2">Initial</th><th colspan="2">Corrected</th><th colspan="2">Initial</th><th colspan="2">Corrected</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>15</td><td>15</td><td>10</td><td>10</td><td>90</td><td>105</td><td>105</td><td>105</td><td>105</td><td></td><td></td></tr><tr><td>2</td><td>7</td><td>6</td><td>12</td><td>12</td><td>105</td><td>105</td><td>90</td><td>105</td><td></td><td></td><td>105</td></tr><tr><td>3</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></tbody></table>	Axle	mm Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	15	15	10	10	90	105	105	105	105			2	7	6	12	12	105	105	90	105			105	3												4												5											
Axle	mm Tread Depth				Air Pressure																																																																																		
	Initial			Corrected		Initial		Corrected																																																																															
	L	R	L	R	L	R	L	R																																																																															
1	15	15	10	10	90	105	105	105	105																																																																														
2	7	6	12	12	105	105	90	105			105																																																																												
3																																																																																							
4																																																																																							
5																																																																																							
☒		Section 10 - Coupling Devices: Defects (if any)																																																																																					

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature Date:

[illegible]