

03977296

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba



Job-3

Vehicle Standards and Inspection
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
204-985-0920

Manitoba

A986775

Date Inspection Started	15	09	25
	DAY	MO.	YR.
Date Inspection Completed	16	09	25
	DAY	MO.	YR.
Inspection Expiry Date	30	09	26
	DAY	MO.	YR.

Station Number	A5673	Station Name	TURK ENTERPRISES LTD	City	204-697-1678
Mechanic Number	M9403	Mechanic Signature	[Signature]	Station Phone Number	
Vehicle Owner	TURK ENTERPRISES LTD				
Address	64 AVIATION BLVD	City	St. Andrews MB	Province	RIA 3N5
				Postal Code	2046971678
				Phone	

☒ Pass/Safe Vehicle	Licence Number	TH8049	Prov.	MB	NSC #		Odometer Reading		Odom. Type	☐ km ☐ mi	
☒ Fail/Unsafe Vehicle	Vehicle Identification Number	1J1V532B06L914109		Make	Mercedes	Model	RA4F4	Year	2016	Unit #	1468
☐ Fail/Hazardous	☒ Confirmed legible Vehicle Identification Number on vehicle										

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																						
☒		Section 1 - Power Train: Defects (if any)																																																																						
☒	☒	Section 2 Suspension: Defects (if any) 2.6.9 FRONT axle Both sides shocks are worn out																																																																						
☒		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type																																																																						
		Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																						
		<table><thead><tr><th rowspan="2">Axle</th><th colspan="2">inch Lining</th><th colspan="2">Drum/Rotor</th><th colspan="2">Stroke</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>9/16</td><td>9/16</td><td></td><td></td><td>1 1/4</td><td>1 1/4</td></tr><tr><td>2</td><td>8/16</td><td>11/16</td><td></td><td></td><td>1 1/4</td><td>1 1/4</td></tr><tr><td>3</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td colspan="7">Final Measurement</td></tr></tbody></table>	Axle	inch Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	9/16	9/16			1 1/4	1 1/4	2	8/16	11/16			1 1/4	1 1/4	3							4							5							Final Measurement																					
Axle	inch Lining			Drum/Rotor		Stroke																																																																		
	L	R	L	R	L	R																																																																		
1	9/16	9/16			1 1/4	1 1/4																																																																		
2	8/16	11/16			1 1/4	1 1/4																																																																		
3																																																																								
4																																																																								
5																																																																								
Final Measurement																																																																								
		Section 4 - Steering: Defects (if any)																																																																						
		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																						
		Section 6 - Lamps: Defects (if any)																																																																						
		Section 7 - Electrical System: Defects (if any)																																																																						
		Section 8 - Body: Defects (if any)																																																																						
		Section 9 - Tire & Wheel: Defects (if any)																																																																						
		<table><thead><tr><th rowspan="3">Axle</th><th colspan="4">Tread Depth</th><th colspan="4">Air Pressure</th></tr><tr><th colspan="2">Initial</th><th colspan="2">Corrected</th><th colspan="2">Initial</th><th colspan="2">Corrected</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>2</td><td>13</td><td>13</td><td>18</td><td>20</td><td>100</td><td>100</td><td>100</td><td>100</td></tr><tr><td>3</td><td>13</td><td>16</td><td>13</td><td>17</td><td>100</td><td>100</td><td>100</td><td>100</td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></tbody></table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1									2	13	13	18	20	100	100	100	100	3	13	16	13	17	100	100	100	100	4									5								
Axle	Tread Depth				Air Pressure																																																																			
	Initial			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1																																																																								
2	13	13	18	20	100	100	100	100																																																																
3	13	16	13	17	100	100	100	100																																																																
4																																																																								
5																																																																								
		Section 10 - Coupling Devices: Defects (if any)																																																																						

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date:

1. The first part of the report is a general statement of the purpose of the study. This is followed by a brief review of the literature on the subject. The next section is a description of the methods used in the study. This is followed by a presentation of the results of the study. The final section is a discussion of the results and their implications.