



JPRO® DIAGNOSTIC REPORT

Connection Date: January 05, 2026 11:15 AM

Print Date: January 05, 2026 11:15 AM

VIN	1FVHC5DX2CHBF3776
Vehicle Make	Freightliner
Model	M2 112
Series	
Model Year	2012

Vehicle Components

Component	Description	Serial Number	Software Version	Network
Engine	Cummins 8.9L ISL (NG)	73315632	04934710 00003763 012220194004 25934822 B6 BAG	J1939 (High)/J1587 (Low)
Transmission	Allison 3000/4000 4th Gen	BK1869A971870048	W11_A59_0B381 4H00VTQ0021 0, W11 A59 0B 381	J1939 (High)/15765 (CAN)
Brakes	WABCO E Basic(12V) 4S/4M	608420	E208	J1939 (High)/J1587 (Low)
Instrument Cluster	Freightliner ICU3-M2	N/A	U.r.3.2.3	J1939 (High)/J1587 (Low)
Chassis Module	Freightliner CHM_L	N/A	U.r.2.A0.04.10	J1939 (High)
Bulkhead Module	Freightliner BHM_L	238755	U.r.2.A0.07.10	J1939 (High)/J1587 (Low)



JPRO® DIAGNOSTIC REPORT

Connection Date: January 05, 2026 11:15 AM

Print Date: January 05, 2026 11:15 AM

Vehicle Key Data Points

Description	Parameter Value
Avg Fuel Econ	5.80 mpg
Battery Potential	14.10 volts
Total Idle Hrs	959.50 hrs
Idle Shutdown	10.00 min
Road Speed Limit	65.00 mph
PTO Status	Inactive
Red Stop Lamp	Off
Protect Lamp	Off
Engine Speed	1046 rpm
Exhaust System High Temperature Lamp Command	Not Available
ABS Control Status, Trailer	Not Available
Engine Odometer	112,319.80 mi
Coolant	Normal

Description	Parameter Value
Idle Fuel Used	939.40 gal
DPF Soot Level	Not Available
DPF Derate	Not Available
Total Engine Run Time	12,134.50 hrs
Cruise Spd Limit	65.00 mph
Malfunction Indicator Lamp	Off
Amber Warning Lamp	Off
Parking Brake Switch	On
DPF Lamp Command	Not Available
ABS Control Status	On
Odometer	112,319.80 mi
Instrument Cluster Odometer	Not Available

Vehicle Issues



No Active Issues Found

Faults

Status	Component	Description	Lookup Code	FMI	Count