

MECHANIC EQUIPMENT REPAIR REPORT

DATE: 08/06/2026 Serial# 3323
Make: John Deere Location: R/C
Model: 6,155 Hours/Mileage: 5,027

Work Performed (print)

Removed and cleaned sunroof seal and
installed back on

Parts/supplies used

- A.
- B.
- C.
- D.
- E.
- F.
- G.
- H.

Repaired Completed By (mechanic-Print):
Robert Willingham

Toatal hours spent on Repairs: 2

In Service(Y/N) yes

Repairs Complete (Y/N) yes

If No -
Explain:

MECHANIC EQUIPMENT REPAIR REPORT

DATE: 04-29-2026 Serial# 3323
Make: John deere Location: R/C
Model: 6155m Hours/Mileage: 4,831

Work Performed (print)

Door not staying open removed and installed
gas door cylinder

Parts/supplies used

- A.
- B. 1-AL228352 gas cykinder
- C.
- D.
- E.
- F.
- G.
- H.

Repaired Completed By (mechanic-Print):
Robert Willingham

Toatal hours spent on Repairs: (

In Service(Y/N) yes

Repairs Complete (Y/N) yes

If No -
Explain:

MECHANIC EQUIPMENT REPAIR REPORT

DATE: 04-17-2026 Serial# 3323
Make: John Deere Location: R/C
Model: 6155m Hours/Mileage: 4,745

Work Performed (print)

Flat tire tried to air up had to call
Iron tire for repair

Parts/supplies used

- A.
- B.
- C.
- D.
- E.
- F.
- G.
- H.

Repaired Completed By (mechanic-Print):
Robert Willingham

Toatal hours spent on Repairs: {

In Service(Y/N) yes

Repairs Complete (Y/N) yes

If No -
Explain:

MECHANIC EQUIPMENT REPAIR REPORT

DATE: 04/07/2026 Serial# 3323
Make: John Deere Location: R/C
Model: 6155m Hours/Mileage: 4,712

Work Performed (print)

Removed and replaced Hyd hose due to hitch on front of
box blade breaking cleaned and ground off smooth and welded
back on and connected to tractor and filled with Hyd oil

Parts/supplies used

- A.
- B. 1- Hyd hose from Gulf Coast Screw
- C.
- D. 1-5 gallon Hyd oil from spidle oil
- E.
- F.
- G.
- H.

Repaired Completed By (mechanic-Print):
Robert Willingham

Toatal hours spent on Repairs: 5 1/2

In Service(Y/N) yes

Repairs Complete (Y/N) yes

If No -
Explain:

MECHANIC EQUIPMENT REPAIR REPORT

DATE: 04/03/2026 Serial# 3323
Make: john deere Location: R/C
Model: 6155m Hours/Mileage: 4,700

Work Performed (print)

Did 500 hour service
inspected machine found door strut blown
ordered parts

Parts/supplies used

- A. 1-AL215053 air filrer
- B. 1-DZ115392 fuel filter
- C. 1-DZ128543 fuel water/sep filter
- D. 1-RE539279 oil filter
- E. 2-AL22552 A/C filter
- F. 2-L152026 cab-n-air filter
- G. 6-Rotella T-4 1 gallon engine oil
- H.

Repaired Completed By (mechanic-Print):
Robert,Danyel Willingham

Toatal hours spent on Repairs: 3

In Service(Y/N) yes

Repairs Complete (Y/N) yes

If No -
Explain:

MECHANIC EQUIPMENT REPAIR REPORT

DATE: 3-18-2026 Serial# 3323
Make: John Deere Location: R/C
Model: 6155m Hours/Mileage: 4,658

Work Performed (print)

Flat tire on box blade removed and installed
spare tire

Parts/supplies used

- A. 1- spare tire
- B.
- C.
- D.
- E.
- F.
- G.
- H.

Repaired Completed By (mechanic-Print):
Robert Willingham

Toatal hours spent on Repairs: 1

In Service(Y/N) yes

Repairs Complete (Y/N) yes

If No -
Explain:

MECHANIC EQUIPMENT REPAIR REPORT

DATE: 3-17-2026 Serial# 3323
Make: John deere Location: R/C
Model: 6155 m Hours/Mileage: 4,652

Work Performed (print)

pin fell out of box blade installed
back in

Parts/supplies used

- A.
- B.
- C.
- D.
- E.
- F.
- G.
- H.

Repaired Completed By (mechanic-Print):
Robert Willingham

Toatal hours spent on Repairs: 1

In Service(Y/N) yes

Repairs Complete (Y/N) yes

If No -
Explain:

MECHANIC EQUIPMENT REPAIR REPORT

DATE: 12-22-2025 Serial# 3323
Make: John Deere Location: R/C
Model: 6155m Hours/Mileage: 4,364

Work Performed (print)

Rebuilt hub

Parts/supplies used

- A. 1-a-8 bearing
- B. 1-a-16 bearing
- C. 1-204500 seal
- D.
- E.
- F.
- G.
- H.

Repaired Completed By (mechanic-Print):
Robert Willingham

Toatal hours spent on Repairs: 2

In Service(Y/N) yes

Repairs Complete (Y/N) yes

If No -
Explain:

MECHANIC EQUIPMENT REPAIR REPORT

DATE: 10-20-2025 Serial# 3323
Make: John Deere Location: R/C
Model: 6155 Hours/Mileage: 4,064

Work Performed (print)

Tried to jump start battery would not
charge removed and installed new battery

Parts/supplies used

- A.
- B. 1-TY26782b battery
- C.
- D.
- E.
- F.
- G.
- H.

Repaired Completed By (mechanic-Print):
Robert Willingham

Toatal hours spent on Repairs: 2 1/2

In Service(Y/N) yes

Repairs Complete (Y/N) yes

If No -
Explain:

MECHANIC EQUIPMENT REPAIR REPORT

DATE: 10-15-2025 Serial# 3323
Make: John Deere Location: R/C
Model: 6155M Hours/Mileage: 4,043

Work Performed (print)

Removed Box blade from unit 6015 and
installed on 3323, aired up low tire and
fixed cup holder

Parts/supplies used

- A.
- B.
- C.
- D.
- E.
- F.
- G.
- H.

Repaired Completed By (mechanic-Print):
Robert Willingham

Toatal hours spent on Repairs: 3

In Service(Y/N) yes

Repairs Complete (Y/N) yes

If No -
Explain: