04116262

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba C099214

Date Inspection Started	14 DAY	09 MO.	26 YR.
Date Inspection Completed	15 DAY	09 MO.	26
Inspection Expiry Date	30 DAY	09 MO.	27 YR.

Station Number: A612107 Station Name: Anderson Mechanical Beau City
Mechanic Number: M8844 Mechanic Signature
(204) 461-3695 Station Phone Number

Vehicle Owner: Aterra Aggregates LTD
Address City Province Postal Code Phone

[X] Pass/Safe Vehicle
[X] Fail/Unsafe Vehicle
[ ] Fail/Hazardous

Licence Number: CGU1184 Prov. MB NSC #: MB079375B Odometer Reading: 993449 Odom. Type [X] km [ ] mi

Vehicle Identification Number: 1M1AW07Y6EM014158 Make: Mack Model: CX613 Year: 2014 Unit #: 24

[X] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

___Truck GVWR KGS X Truck Tractor ___Trailer ___Semi-Trailer ___Bus ___School Bus ___Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

P X / R X — **Section 1 - Power Train:** Defects (if any) 3xA Check engine light ON

P X / R — **Section 2 Suspension:** Defects (if any)

P X / R X — **Section 3 - Brake Systems:** 3H (3A)

Defects (if any) (Circle Brake Type) 13xA Glad Hand Seals torn.

Brake Inspection Type: A B (C) D E — Circle appropriate Letter for Internal Brake Component Inspection

	Lining		Drum/Rotor		Stroke	
Axle	L	R	L	R	L	R
1	3/4	3/4			1.25	1.25
2	1/2	1/2			1.25	1.25
3	1/2	1/2			1.25	1.25
4						
5						
	Final Measurement					

P X / R — **Section 4 - Steering:** Defects (if any)

P X / R — **Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)

P X / R — **Section 6 - Lamps:** Defects (if any)

P X / R — **Section 7 - Electrical System:** Defects (if any)

P X / R X — **Section 8 - Body:** Defects (if any) 1xB left hood latch Broken.

P X / R — **Section 9 - Tire & Wheel:** Defects (if any)

	Tread Depth 1/32nd Initial				Tread Depth Corrected				Air Pressure PSI Initial				Air Pressure Corrected			
Axle	L		R		L		R		L		R		L		R	
1		14	15							100	100					
2	10	9	10	10					100	100	100	100				
3	13	13	13	13					100	100	100	100				
4																
5																

P X / R — **Section 10 - Coupling Devices:** Defects (if any)

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature Date: _____

Ce document peut être obtenu en français sur demand