

K06-1

**GARAGE REPAIR ORDER**  
**BON DE RÉPARATION DE GARAGE**

2019 Midland XL3000 End Dump

040993

MATERIALS/MATÉRIEL			
QTY. QTE	PART NO. N° DE PIÈCE	DESCRIPTION	PRICE PRIX
5	372-7097	Wheel Seal	
4		TIRES	
2		Tires 2 <sup>nd</sup> Axle Drive	Dec/04/22
1		1" Hydraulic Hose 60"	Dec/04/22

NAME NOM		DATE	
ADDRESS ADRESSE			
MAKE MARQUE <b>MIDLAND</b>	MODEL MODÈLE <b>END DUMP</b>	YEAR ANNÉE <b>2019</b>	TAX REG. NO. N° DE TAXE <b># 95</b>
SERIAL NO. N° DE SÉRIE	MOTOR NO. N° DE MOTEUR	PROMISED PROMIS LE	A.M. P.M.
ODOMETER ODOMÈTRE	LICENCE NO. N° D'IMMATRICULATION	TERMS CONDITIONS	PHONE WHEN READY TÉL. UNE FOIS PRÊT <input type="checkbox"/> YES/OUI <input type="checkbox"/> NO/NON
WRITTEN BY PRÉPARÉ PAR	RES. PHONE TÉL. DOM.	BUS. PHONE TÉL. BJR	

LABOUR MAIN D'ŒUVRE	AMOUNT MONTANT
LUBRICATION LUBRIFICATION <input type="checkbox"/>	
CHANGE OIL CHANG. D'HUILE <input type="checkbox"/>	
CHANGE LUB / CHANG. DE LUBRIF. DIFF. <input type="checkbox"/> TRANS. <input type="checkbox"/>	
REPLACE OIL FILTER REMPLACER FILTRE À HUILE <input type="checkbox"/>	
CLEAN AIR FILTER NETT. FILTRE À AIR <input type="checkbox"/>	
REPACK FRONT WHEELS GRAISSAGE DES ROUES AVANT <input type="checkbox"/>	
ADJUST BRAKES RÉGLAGE DES FREINS <input type="checkbox"/>	
ROTATE TIRES PERMUTATION DES PNEUS <input type="checkbox"/>	
WASH LAVAGE <input type="checkbox"/> POLISH CIRAGE <input type="checkbox"/>	
TUNE MOTOR MISE AU POINT DU MOTEUR <input type="checkbox"/>	

OPÉRATION N° / NO.	INSTRUCTIONS
Jan/2021	oil added to Driveside front & rear axle
FEB/11/21	INSTALL VIBRATOR
Mar. 18/21	Install wheel seals on front axle each side mid axle right side, rear axle each side HITCH PIN 1 3/32"
JULY 05	REPLACED 4 TIRES ON MIDDLE AXEL 2022
JAN 7 2023	know tires middle axle changed to 500lb5
Feb/22	repair lights backend (wiring)
Nov 30/23	clean Tower rings & set ABS sensors closer

Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.

Nous ne pourrons être tenus responsables des pertes ou des dommages causés aux véhicules ou aux articles laissés dans le véhicule en cas d'incendie, de vol ou de toute autre cause indépendante de notre volonté.

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.

Par la présente, j'autorise les réparations ci-dessus indiquées ainsi que l'achat du matériel nécessaire. De plus, je vous donne la permission ainsi qu'à un de vos employés de conduire le véhicule décrit dans la présente dans les rues, sur les autoroutes ou ailleurs, dans le but d'en faire l'essai ou l'inspection. Par la présente, un privilège de construction exprès est accordé en ce qui a trait au véhicule décrit ci-dessus afin de garantir le coût des réparations.

GAS, OIL & GREASE ESSENCE, HUILE ET GRAISSE		TOTAL LABOUR TOTAL DE LA MAIN-D'ŒUVRE
QTY. QTE	PRICE PRIX	TOTAL PARTS TOTAL DES PIÈCES
LITERS GAS LITRES D'ESSENCE		TOTAL ACCESSORIES TOTAL DES ACCESSOIRES
LITERS OIL LITRES D'HUILE		TOTAL SUBCONTRACT TOTAL SOUS-TRAIT
GREASE GRAISSE		TOTAL GAS-OIL-GREASE TOTAL ESSENCE-HUILE-GRAISSE
		TVH/HST TPS/GST
		PST/TPV
	<b>TOTAL</b>	<b>TOTAL</b>

QTY. QTE	PART NO. N° DE PIÈCE	ACCESSORIES / ACCESSOIRES	PRICE PRIX
TOTAL PARTS TOTAL DES PIÈCES			
TOTAL ACCESSORIES TOTAL DES ACCESSOIRES			

AUTHORIZED BY / AUTORISÉ PAR

STAPES STC-48115

**AJ MECHANICAL LTD.**  
 Box 83  
 SWIFT CURRENT, SASK. S9H 3V5  
 Phone: 306-778-6879 Fax: 306-741-9755

**INVOICE**

**12913**

803142157

**INVOICE**

Printed Date: 04/28/2023 Work Completed: 04/28/2023

2019 Midland - End Dump -

Lic #

Odometer In : 0

Unit # : 95

VIN # : 2MFB2R5D1 KR009022

Part Description	Qty	Sale	Ext	Labor Description	Hours	Ext	
TRAILER SAFETY	1.00	0.00	n/c	LABOUR:	8.00	840.00	
3/8 TO 1/4 Brass Male Connector	1.00	2.78	2.78	WORK REQUESTED: DO TRAILER SAFETY			
Shock Absorber	6.00	86.52	519.12				
Auto Slack Adjuster - 1-1/2 28spl 5.5 trailer	1.00	161.94	161.94	WORK PERFORMED: Did safety. R&R all 6 shocks. Replaced slack adjuster on RH 3rd axle, slack adjuster was seized on s-cam, had to heat it up to get off. Replace plastic inserts on adjustment pin all 5 other slack adjusters. Greased and checked axle hub oil levels. All lights OK.			
Tee 3/8-1/4 end tube to male pipe centre tube	1.00	7.68	7.68				
1/4 MPT Plug Hex Head	1.00	1.75	1.75				
3/4-16 nut gr8	2.00	2.08	4.16				
Lock washer 3/4 gr8	2.00	0.78	1.56				
Automatic Slack Adjuster Bushing	5.00	6.24	31.20				
Airbag	1.00	225.84	225.84				
Shop Supplies			42.00				

**Taxes**

Gst	91.90
Pst	110.28

ENTERED MAY 16 2023

[ Payments - ]

**2% INTEREST CHARGE AFTER 30 DAYS**

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle described for testing and/or inspection. Express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. Save all Parts, NOT RESPONSIBLE FOR LOSS OR DAMAGE TO TRUCKS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

Labor:	840.00
Parts:	998.03
Sub:	1,838.03
Tax:	202.18
Total:	\$2,040.21
Bal Due:	\$2,040.21

Vehicle Received: 4/28/2023

Customer Number: 853

Signature \_\_\_\_\_ Date \_\_\_\_\_

Email Address: [ajmechanical@sasktel.net](mailto:ajmechanical@sasktel.net)

**AJ MECHANICAL LTD.**  
 Box 83  
 SWIFT CURRENT, SASK. S9H 3V5  
 Phone: 308-778-6879 Fax: 306-741-9755

**INVOICE**

**13215**

803142157

**INVOICE**

Printed Date: 08/28/2023 Work Completed: 08/28/2023

2019 Midland - End Dump -

Lic #

Odometer In : 0

Unit # : 95

VIN # : 2MFB2R5D1 KR009022

Part Description	Qty	Sale	Ext	Labor Description	Hours	Ext
Shop Supplies			22.50	LABOUR:	3.00	450.00

**WORK REQUESTED:**

GO THROUGH TRAILER.

**WORK PERFORMED:**

Greased trailer and filled hubs.

Found left middle axle wheel seal leaking, pulled tires, hub and cleaned wheel bearings.

Brakes didn't get wet, re-installed hub and set bearing end play.

Installed tires and torqued to 500 ft lbs.

Set and checked all brakes.

Repaired broken wire at right side signal/ marker light and left bottom tail light.

PARTS ARE ON TRUCK WORK ORDER #13188

**Taxes**

Gst	23.63
Pst	28.35

RECEIVED SEP 21 2023

[ Payments - ]

**2% INTEREST CHARGE AFTER 30 DAYS**

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle described for testing and/or inspection. Express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. Save all Parts, NOT RESPONSIBLE FOR LOSS OR DAMAGE TO TRUCKS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

Labor:	450.00
Parts:	22.50
Sub:	472.50
Tax:	51.98
Total:	\$524.48
Bal Due:	\$524.48

Vehicle Received: 8/28/2023

Customer Number : 653

Signature \_\_\_\_\_ Date \_\_\_\_\_

Email Address: [ajmechanical@sasktel.net](mailto:ajmechanical@sasktel.net)

**AJ MECHANICAL LTD.**  
 Box 83  
 SWIFT CURRENT, SASK. S9H 3V5  
 Phone: 306-778-6879 Fax: 306-741-9755

**INVOICE**  
**13828**

803142157

**INVOICE**

Printed Date: 05/30/2024 Work Completed: 05/30/2024

2019 Midland - End Dump -

Lic # :

Odometer In : 0

Unit # : 95

VIN # : 2MFB2R5D1 KR009022

Part Description	Qty	Sale	Ext	Labor Description	Hours	Ext
TRAILER SAFETY	1.00	200.00	200.00	<b>LABOUR:</b>  <b>WORK REQUESTED:</b> DO TRAILER SAFETY  <b>WORK PERFORMED:</b> Did trailer safety. Replaced RH front and rear corner clearance lights. Greased trailer. Installed new air bag on LM axle. Clipped slack adjuster bushing back in.	1.50	240.00
Light LED 2.5" red	1.00	14.91	14.91			
2.5" LED Marker Light - Amber	1.00	34.35	34.35			
Airbag	1.00	273.47	273.47			
1/4 MPT Plug Hex Head	1.00	1.14	1.14			
Tee 3/8-1/4 end tube to male pipe centre tube	1.00	7.68	7.68			
3/4-16 nut gr8	2.00	2.00	4.00			
Flat washer 3/4	2.00	0.60	1.20			
Lock washer 3/4 gr8	2.00	0.78	1.56			
Shop Supplies			12.00			

Taxes	
Gst	39.52
Pst	47.42

[ Payments - ]

**2% INTEREST CHARGE AFTER 30 DAYS**

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle described for testing and/or inspection. Express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. Save all Parts, NOT RESPONSIBLE FOR LOSS OR DAMAGE TO TRUCKS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

Labor:	240.00
Parts:	550.31
<b>Sub:</b>	<b>790.31</b>
<b>Tax:</b>	<b>86.94</b>
<b>Total:</b>	<b>\$877.25</b>
<b>Bal Due:</b>	<b>\$877.25</b>

Vehicle Received: 5/30/2024

Customer Number : 653

Signature \_\_\_\_\_ Date \_\_\_\_\_

Email Address: ajmechanical@sasktel.net

# GARAGE REPAIR ORDER BON DE RÉPARATION DE GARAGE

114004

MATERIALS/MATÉRIEL			
QTY. QTE	PART NO. N° DE PIÈCE	DESCRIPTION	PRICE PRIX
2	4707 ap	brake shoes	
2-		drums	
1-	4w10211	slack adjuster (Haldex)	
1	8091	air bag	
1	110170	relay valve	
1	6204 2RS	Bearing	

NAME NOM		DATE	
ADDRESS ADRESSE			
MAKE MARQUE	MODEL MODÈLE	YEAR ANNÉE	TAX REG. NO. N° DE TAXE
Midland	Exidderp	2019	#95
SERIAL NO. N° DE SÉRIE	MOTOR NO. N° DE MOTEUR	PROMISED PROMIS LE	A.M. P.M.
ODOMETER ODOMÈTRE	LICENCE NO. N° D'IMMATRICULATION	TERMS CONDITIONS	PHONE WHEN READY TÉL. UNE FOIS PRÊT
WRITTEN BY PRÉPARE PAR	RES. PHONE TÉL. DOM.	BUS PHONE TÉL. BUR.	

LABOUR MAIN-D'ŒUVRE	AMOUNT MONTANT
LUBRICATION LUBRIFICATION <input type="checkbox"/>	
CHANGE OIL CHANG. D'HUILE <input type="checkbox"/>	
CHANGE LUB. / CHANG. DE LUBRIF. DIFF. <input type="checkbox"/> TRANS. <input type="checkbox"/>	
REPLACE OIL FILTER PEMPLACER FILTRE À HUILE <input type="checkbox"/>	
CLEAN AIR FILTER NETT. FILTRE À AIR <input type="checkbox"/>	
REPACK FRONT WHEELS GRAISSAGE DES ROUES AVANT <input type="checkbox"/>	
ADJUST BRAKES RÉGLAGE DES FREINS <input type="checkbox"/>	
ROTATE TIRES PERMUTATION DES PNEUS <input type="checkbox"/>	
WASH LAVAGE <input type="checkbox"/>	POLISH CIRAGE <input type="checkbox"/>
TUNE MOTOR MISE AU POINT DU MOTEUR <input type="checkbox"/>	

OPÉRATION N° / NO.	INSTRUCTIONS
Feb 28/24	repair wiring for LH rear lower marker light & RH middle signal light
Mar 26/24	change brake shoes & drum both sides on axle #3, change LH axle #1 slack adjuster
July 15/24	change axle #1 LH air bag & 3 marker lights & relay valve above axle #1
April 8/25	replace <del>Rear</del> axle LH air bag
April 30/25	Fix Tapp crank handle (bearing)

QTY. QTE	PART NO. N° DE PIÈCE	ACCESSORIES / ACCESSOIRES	PRICE PRIX
TOTAL PARTS TOTAL DES PIÈCES			
TOTAL ACCESSORIES TOTAL DES ACCESSOIRES			

Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.

Nous ne pouvons être tenus responsables des pertes ou des dommages causés aux véhicules ou aux articles laissés dans le véhicule en cas d'incendie, de vol ou de toute autre cause indépendante de notre volonté.

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car or truck herein described on streets, highways, or elsewhere for the purpose of testing and/or inspecting. An express mechanic's lien is hereby acknowledged on the above car or truck to secure the amount of repairs thereto.

Par la présente, j'autorise les réparations ci-dessus indiquées ainsi que l'achat du matériel nécessaire. De plus, je vous donne la permission ainsi qu'à un de vos employés de conduire le véhicule décrit dans la présente dans les rues, sur les autoroutes ou ailleurs, dans le but d'en faire l'essai ou l'inspection. Par la présente, un privilège de construction exprès est accordé en ce qui a trait au véhicule décrit ci-dessus afin de garantir le coût des réparations.

GAS, OIL & GREASE ESSENCE, HUILE ET GRAISSE		TOTAL LABOUR TOTAL DE LA MAIN-D'ŒUVRE
QTY. QTE	PRICE PRIX	TOTAL PARTS TOTAL DES PIÈCES
LITERS GAS LITRES D'ESSENCE		TOTAL ACCESSORIES TOTAL DES ACCESSOIRES
LITERS OIL LITRES D'HUILE		TOTAL SUBCONTRACT TOTAL SOUS-TRAIT
GREASE GRAISSE		TOTAL GAS-OIL-GREASE TOTAL ESSENCE-HUILE-GRAISSE
		TVH/HST TPS/GST
		PST/TPV
TOTAL		TOTAL

AUTHORIZED BY / AUTORISÉ PAR

STAPLES STC4811B

