

American Tank Solutions, LLC
7744 Beauxart Garden Rd
Nederland, Texas, 77627
855-547-2855



Wash Ticket #: 136085

Check in Date: 05/18/2026 12:05 p.m.

Delivered By:

Payment: Account

PO #: None

KL09-85 10/20
HA019432

Tank Container Cleanliness Certificate

Customer Information:

HPC Industrial Port Arthur/Clean Harbors
16019 Sabine Consolidated Rd
Beaumont, TX, 77705, USA
Customer No.: 608

Contact Information

Office:
Cell:

Unit Information

Unit Type: Vac Truck
Tractor ID:
Unit #: 55035

Manifest/BOL#: 26554

Compartments: 1

Generator:

Unit Compartment Summary

Compartment #	Last Contained Material	Gallons	HAZ / NH
1	Hazardous Wastewater Stream	0	Haz
Total Gallons:		0	

Unit Services Summary

Item #	Service Item	Quantity	Units
10133	Vac Truck Clean	1.0	Each
10141	Energy and EIS Recovery Fee	1.0	Each

Service Initiated:
Service Completed
Comments:

Waste Heel:
Product Heel:

Gallons Containers

A thorough visual examination has been carried out and the interior of the tank, valves and fitting are free of contamination, corrosion, previous cargo, odor and pitting. The tanks are clean and dry.

Remarks:

THE REPORT IS BASED SOLELY UPON A VISUAL EXAMINATION OF THE TANK AND THE EXAMINATION OF DOCUMENTATION PROVIDED BY OTHERS. THE SURVEYOR ACCEPTS NO LIABILITY FOR ANY CONDITIONS THAT ARE NOT APPARENT DURING A NORMAL VISUAL INSPECTION OR THAT MAY BE THE RESULT OF INACCURATE INFORMATION PROVIDED IN DOCUMENTS UPON WHICH THE SURVEYOR MUST RELY. * SUBJECT ONLY TO CLEANLINESS OF THE TANK INTERIOR, VALVES AND FITTINGS

Approval:

Approval Signature/Date