

# Experian AutoCheck Report

Report run: 04/27/2026 12:42:16 EDT

## 2016 Kia Sedona LX

Mini-Van 4D (3.3L V6 DI Gasoline)

VIN:	KNDMB5C19G6098692
Class:	Van - Mini
Country of Assembly:	South Korea
Vehicle Age:	10 year(s)
Estimated In Service:	11/24/2015
Last Reported Odometer:	164,851 (04/02/2026)

Owners - 3



Vehicle Usage  
Lease, Rental



## AutoCheck Score

Similar vehicles usually range between 78 and 88

### Vehicle History at a Glance

<p>State Title Brand</p> <p><b>CLEAN</b></p>	<p>Auction Brand / Issues</p> <p><b>NO ISSUE</b></p>	<p>Accident / Damage</p> <p><b>MODERATE</b></p>
<p>Open Recall Check</p> <p><b>NO OPEN RECALLS</b></p>	<p>Insurance Loss / Transfer</p> <p><b>NO ISSUE</b></p>	<p>Odometer Check</p> <p>Last reported odometer: 164,851 (04/02/2026)</p> <p><b>NO ISSUE</b></p>
<p>Certified Pre-Owned</p> <p><b>NO CPO INFO AVAILABLE</b></p>	<p>Service / Repair</p> <p><b>NO ISSUE</b></p>	<p>Additional History</p> <p>Lien Reported, Repossessed</p> <p><b>EVENTS REPORTED</b></p>





This vehicle is eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. [Terms & Conditions](#)


[Learn More](#)

### Accident & Damage







Airbag Deployed



Structural Damage



Overturned



Moderate

Damage Date	Damage Type	Severity
11/24/2021	Collision	Moderate

Accident or damage event(s) have been reported for this vehicle to Experian AutoCheck. An inspection may provide added confidence in the vehicle's condition before purchase.

## Recommended Maintenance

### OEM Recommended Maintenance Schedule

Based on your vehicle's last reported mileage, these are the most recent and upcoming recommended maintenance intervals from your vehicle's manufacturer.

### OEM Recommended Services



#### 150000 Mile Service

- Check if Fuel Additive is required (Only necessary if TOP TIER Detergent Gasoline is not available. Add'l cost if needed)
- Inspect air conditioner refrigerant (if equipped)
- Inspect battery condition

## Odometer Check




### Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.




**State Title Odometer Check**

No issues reported



**Auction Odometer Check**

No issues reported



**Odometer Calculation Check**

No issues reported

## Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.  
 Vehicle: 2016 Kia Sedona LX (KNDMB5C19G6098692) Report Run Date: 04/27/2026 12:42:16 EDT

2015

### Owner 1

Location: OH

Owned From: 11/2015

Usage: Lease, Rental

Event Date	Location	Odometer	Data Source	Details
11/24/2015	NORTH OLMSTED, OH	50	Motor Vehicle Dept.	Title(Title #:4703088432) (Leased Vehicle) Rental

Event Date	Location	Odometer	Data Source	Details
12/10/2015	NORTH OLMSTED, OH		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
05/27/2016	NORTH OLMSTED, OH		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
06/07/2017	NORTH OLMSTED, OH		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
09/08/2017	NORTH OLMSTED, OH	12,680	Motor Vehicle Dept.	Title(Title #:4703380716) (Leased Vehicle)

2017

### Owner 2

<span>Location: OH</span> <span>Owned From: 09/2017</span> <span>Usage: Personal</span>				
Event Date	Location	Odometer	Data Source	Details
09/11/2017	CLEVELAND, OH	12,689	Motor Vehicle Dept.	Title(Title #:1811843946) (Lien Reported)
09/15/2017	CLEVELAND, OH		Motor Vehicle Dept.	Registration Event/Renewal
01/10/2018	CLEVELAND, OH		Motor Vehicle Dept.	Registration Event/Renewal
01/06/2020	OH	20,000	Independent Emission Source	Passed Emission Inspection
01/10/2020	CLEVELAND, OH		Motor Vehicle Dept.	Registration Event/Renewal
01/07/2021	CLEVELAND, OH		Motor Vehicle Dept.	Registration Event/Renewal
11/24/2021	BROOK PARK, OH		State Agency	Right Rear Impact with Another Vehicle(Case #:20214264206) Vehicle Damage Reported as Disabling Accident Reported(Report #:21-120008) Vehicle Was Towed
01/04/2022	OH	27,000	Independent Emission Source	Passed Emission Inspection
01/05/2022	CLEVELAND, OH		Motor Vehicle Dept.	Registration Event/Renewal
07/24/2023	BRUNSWICK, OH	32,817 †	Dealer Listing	Vehicle Listed for Sale
07/25/2023	BRUNSWICK, OH	32,772	Motor Vehicle Dept.	Title(Title #:5203619457)
07/29/2023	BRUNSWICK, OH	32,817	Dealer Listing	Vehicle Listed for Sale

2023

### Owner 3

<span>Location: OH</span> <span>Owned From: 08/2023</span> <span>Usage: Personal</span>				
Event Date	Location	Odometer	Data Source	Details
08/24/2023	SAINT MARYS, OH	32,817	Motor Vehicle Dept.	Title(Title #:5203634322) (Lien Reported)
09/14/2023	SAINT MARYS, OH		Motor Vehicle Dept.	Registration Event/Renewal
11/18/2025	OH	164,831	Auto Auction	Reported at Auto Auction
12/09/2025	OH		Motor Vehicle Dept.	Title(Title #:2518993895) (Lien Reported) Repossessed
12/15/2025	OH	164,831	Auto Auction	Auction Announced as Repossessed

Event Date	Location	Odometer	Data Source	Details
12/17/2025			Manufacturer	<p>Manufacturer Service Bulletin Mfr. Recall CS2312 Customer Satisfaction Campaign: CS2312 THEFT DET IGNITION CYL PROTECTOR LOCATE YOUR NEAREST AUTHORIZED <b>KIA DEALER</b> TO SCHEDULE REPAIR. Status: Remedy Unknown</p> <p>Manufacturer Service Bulletin Mfr. Recall CS2312 Customer Satisfaction Campaign: CS2312 THEFT DET IGNITION CYL PROTECTOR LOCATE YOUR NEAREST AUTHORIZED <b>KIA DEALER</b> TO SCHEDULE REPAIR. Status: Remedy Unknown</p> <p>Manufacturer Service Bulletin Mfr. Recall CS2312 Customer Satisfaction Campaign: CS2312 THEFT DET IGNITION CYL PROTECTOR LOCATE YOUR NEAREST AUTHORIZED <b>KIA DEALER</b> TO SCHEDULE REPAIR. Status: Remedy Unknown</p>
04/02/2026	OH	164,851	Auto Auction	Reported at Auto Auction

† This odometer reading is inconsistent with the odometer history. This could be due to a typographical, clerical, or rounding error and does not necessarily represent an odometer rollback by itself. If we receive additional odometer history that corroborates an odometer rollback, this display may change and that may impact other aspects of this report and the vehicle's qualifications.

#### AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at [www.autocheck.com/terms](http://www.autocheck.com/terms) or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

#### Buyback Protection Terms and Conditions

This vehicle (KNDMB5C19G6098692) qualifies for [AutoCheck Buyback Protection](#). If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at [www.autocheck.com/bbpterm](http://www.autocheck.com/bbpterm) or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

#### About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

#### Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.