Alberta
CV8668281
Expires Last Day of Month Shown
1 2 4 5 6 7 8 9 10 11 12
Year Year
2024 2029
2025 2030
2026 2031
2032
2028 2033

Alberta Government

CV8668281

800870000008668281

CERTIFICATE NUMBER

# Commercial Vehicle Inspection Certificate
## Traffic Safety Act

## PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

| | | | |
|---|---|---|---|
| **Vehicle Type:** | Trailer | **Seating Capacity:** | |
| **GVW:** | kg | **Brake Type:** | Air |
| **Owner Name:** | Bar HH Horte Ventures Ltd | | |
| **Address:** | 19566 Township Road 492 | | |
| **City:** | Camrose County | **Province:** AB | **Postal Code:** T0B2M1 |
| **Telephone Number:** | (403) 358-4474 | | |
| **Vehicle Identification Number:** | 1W14453A8E2264057 | | |
| **Make:** | Wilson | **Model:** | DWH550C |
| **Year:** | 2014 | **Unit Number:** | |
| **Odometer:** | KM | **Licence Plate Number:** 5SN794 | **Province:** AB |

**IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE**

## PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traff Safety Act for a Commercial Vehicle.

| | |
|---|---|
| **Inspection Facility Name:** | **Facility Number:** |
| Maximum Mechanical Repair (Camrose) Ltd. | 13294 |
| **Inspection Technician Name:** | **Technician Number:** |
| Bradley George | C0040 |
| **Inspection Technician Signature:** | |
| **Inspection Date:** | 2026/03/24 |

# COMMERCIAL VEHICLE RECORD OF INSPECTION
# TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

**ion**

**e for which this Record of Inspection is issued has PASSED (Certificate #8668281) the inspection and I certify it has bee**
**ce with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.**

| Date of Inspection | Technician Number | Facility Number | Signature |
|---|---|---|---|
| 2026/03/24 | C0040 | 13294 | |

**er Acknowledgment**

**stand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle s Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of al inspection and only the failed items noted on this ROI are required to be re-inspected. If the is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection e conducted.**

| Date (Year/Mo | |
|---|---|
| 2026/03 | |
| Customer Si | |

| bice To | Ship To |
|---|---|
| HH HORTE VENTURES LTD. | YEAR;2014<br>MAKE;WILSON<br>SN;1W14453A8E2264057<br>ODO;<br>LIC; |

| .O. No. | Terms | Ship |
|---|---|---|
| | | 3/25/2026 |

| Quantity | Item | Description | Price Each | Amount |
|---|---|---|---|---|
| 1 | LABOUR | DURING INSPECTION, FOUND D/S MIDWAY MARKER LAMP AND REAR MIDDLE UPPER I.D. LAMP OUT. CHECKED FOR POWER AT BOTH. REPLACED REAR LIGHT AND REPLACED LIGHT AND ADAPTOR ON MIDWAY LIGHT. ALL LIGHTS GOOD NOW. | 161.50 | 161.50 |
| 5 | S28501575 | DUSTSHIELD CLAMP (REMOVED DUSTSHIELDS TO MEASURE BRAKES INSTEAD OF WHEEL PULL) | 13.88 | 69.40 |
| 1 | SHOP SUPPLIES | SHOP SUPPLIES | 47.95 | 47.95 |

**Sales Tax Summary**

| | |
|---|---|
| GST@5.0% | 76.53 |
| Total Tax | 76.53 |

**Total** $1,607.17

GST/HST No. 869625913

| | |
|---|---|
| 3/25/2026 | 7411 |

| Invoice To | Ship To |
|---|---|
| NEAR THE HORTE VENTURES LTD. | YEAR;2014<br>MAKE;WILSON<br>SN;1W14453A8E2264057<br>ODO;<br>LIC; |

| P.O. No. | Terms | Ship |
|---|---|---|
| | | 3/25/2026 |

| Quantity | Item | Description | Price Each | Amount |
|---|---|---|---|---|
| 1 | TAT | TRI AXLE TRAILER INSPECTION | 275.00 | 275.00 |
| 1 | 52247922 | CLEARENCE LAMP | 36.42 | 36.42 |
| 1 | 52247922 | CLEARENCE LAMP | 36.42 | 36.42 |
| 1 | 52266242 | HARNESS | 9.15 | 9.15 |
| 1 | PHL12012 | GLADHAND RUBBER | 2.92 | 2.92 |
| 1 | 1643B-100 | WHEEL HUB COVER | 19.12 | 19.12 |
| 1 | RM-T03 | 46300 TRAILER WHEEL SEAL | 64.59 | 64.59 |
| 3 | NKM4707Q23 | NEW Q PLUS SHOES | 94.43 | 283.29 |
| 3.25 | LABOUR | DURING INSPECTION, FOUND #1 AXLE D/S, #2 AXLE PASS/SIDE AND #3 AXLE PASS/SIDE BRAKE LININGS HAD RUST JACKING BETWEEN LININGS AND STEEL WEBBING. ALSO FOUND #1 AXLE D/S WHEEL HUB LEVEL EMPTY. SEAL WAS LEAKING. REMOVED WHEELS AS NEEDED. REMOVED AND INSPECTED DRUMS. STILL GOOD FOR REUSES. REPLACED LININGS AS NEEDED. REMOVED WHEEL HUB FROM #1 AXLE D/S. DISASSEMBLED AND CLEANED HUB. CLEANED AND INSPECTED WHEEL BRGS. ASSEMBLED AND REINSTALLED HUB WITH NEW WHEELS SEAL AND OIL HUB COVER. FILLED HUB WITH OIL. REINSTALLED DRUMS AND WHEELS. TORQUED WHEELS TO 450 FT.LBS. AIRED UP TRAILER AND ADJUSTED ALL BRAKES. REPLACED TOR GLADHAND RUBBER. | 161.50 | 524.88 |

**Sales Tax Summary**

**Total**

GST/HST No. 869625913