



Distributor: WPI

Branch:

Technician Name: 10096 - Matthew Warrington

Inspection Date: 7/22/2025 4:24:44 PM CDT

SMR: 3602.9

Job Number: 519137

Model Number: D65EX-18

Serial: 92347

Equipment Number: 195022

Customer Name: [REDACTED]

Deficiencies			
CAB INTERIOR			
WIPER FUNCTION AND BLADE CONDITION	Poor		
Missing			
Note: left door wiper missing blade			

Inspection Results			
SAFETY AND GENERAL WALK AROUND			
FRAME,CAR BODY,ROPS,MOUNTING BOLTS	Good	GRAB BARS AND STEPS	Good
BOOM, ARM, PUSH ARMS	Good	TAKE OIL SAMPLES OF ALL COMPARTMENTS	True
GET CONDITION	Good	ENSURE NO ONE IS UNDER OR AROUND MACHINE	True
CYLINDERS	Good	SHEET METAL	Good
ANY OTHER EXTERIOR BREAKAGE/DAMAGE	No	GLASS AND MIRRORS	Good
MACHINE SERIAL NUMBER PLATE	92347	FENDER/ BUMPERS	Good
INSPECTION TYPE	REPAIR INSPECTION		

PRE START-UP			
HYDRAULIC OIL LEVEL	Low	ENGINE OIL LEVEL	Acceptable (in range)
FINAL DRIVE/ DIFFERENTIAL / Tandem Case OIL LEVELS	Acceptable (in range)	TRANSMISSION/ PT OIL LEVEL	Low
COOLANT LEVEL	Acceptable (in range)		

CAB INTERIOR			
DOORS: LATCHES, STRIKERS, HOLD-BACKS	Good	MONITOR PANEL SCREEN	Good
AC/HEATER OPERATION AND LOUVERS	Good	REAR CAMERA FUNCTIONALITY	Good
HORN AND BACK UP/TRAVEL ALARM	Good	CAB LIGHTS, BULBS, FUSES, AND SWITCHES (FUNCTION/MISSING)	Good
RECORD SMR FROM MONITOR PANEL	3602.9	SEAT OPERATION AND SAFETY BELT	Good
SIMS CARD ACTIVATED	YES	FIRE EXTINGUISHER	Not Available /
IS THIS A PM SERVICE	No	WIPER FUNCTION AND BLADE CONDITION	Poor
VERIFIED KOMTRAX IS WORKING	Good	WINDOWS: LATCHES and GLASS	Good

START MACHINE			
PARKING BRAKE	Good	LEVER CONTROL ACTION AND ACCUMULATOR	Good
BRAKE ACCUMULATOR/PEDAL OPERATION	Good	RIPPER OR WORK EQUIPMENT	Good
HEAD LAMPS	Good	BUCKET / BLADE / ATTACHMENT	Good

UNDERCARRIAGE / TIRES (GENERAL)			
ROLLERS & ROLLER GUARDS	Good	IDLER AND TRACK ASSEMBLY	Good

SPROCKETS	Good		
POWER TRAIN			
TRANSMISSION, TRANSMISSION COOLER, AND T/C	Good	HOSES	Good
FINAL DRIVES OR DIFFERENTIALS	Good	BELTS	Good
HYDRAULIC COOLER FINS	Good	ENGINE	Good
RADIATOR FINS AND RADIATOR CAP	Good	KVGT (TURBO)	Good
FAN MOTOR AND FAN BLADE	Good	DOSER PIPING	Good
BATTERY ELECTROLYTE LEVEL	Good	EGR ASSEMBLY	Good
FUEL TANK CAP	Good	DPF ASSEMBLY AND HEAT SHIELDING	Good
AIR FILTER	Good	SCR SYSTEM & AdBlue/DEF TANK	Good
FINAL DRIVE OILS CHANGED	No		

Signature

4 Corner Images



4 CORNERS PICTURES (FRONT LEFT)



4 CORNERS PICTURES (REAR LEFT)





4 CORNERS PICTURES (FRONT RIGHT)




4 CORNERS PICTURES (REAR RIGHT)

Images



ATTACHMENT PICTURES (OPTIONAL)	ATTACHMENT PICTURES (REQUIRED)
	
MACHINE SERIAL NUMBER PLATE (PHOTO)	PHOTO OF SMR ON MONITOR PANEL SCREEN

Deficiency Images	
	
CAB INTERIOR - WIPER FUNCTION AND BLADE CONDITION	