

04048214

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE



Vehicle Standards and Inspection
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba
C027694

Date Inspection Started: 24 02 26
 Date Inspection Completed: 05 03 26
 Inspection Expiry Date: 31 03 27

Station Number: A12914 Station Name: TR-S Truckshop Carmen
 Mechanic Number: M8893 Mechanic Signature: [Signature] Station Phone Number: (204) 745-3260
 Vehicle Owner: Blooming Prairie Colony Farms
 Address: Box 24 Homewood MB R0G0Y0 Postal Code: (204) 750-4531 Phone:

Pass/Safe Vehicle Fail/Unsafe Vehicle Fail/Hazardous
 Licence Number: [] [] [] [] [] [] [] [] [] [] Prov. [] NSC # [] Odometer Reading: [] Odom. Type: km mi
 Vehicle Identification Number: 1W1FKA6B7S1B0211692 Make: Nissan Model: Step Deck Year: 1998 Unit #: []
 Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus
 List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																							
X		Section 1 - Power Train: Defects (if any)																																																																							
X		Section 2 Suspension: Defects (if any)																																																																							
X		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type																																																																							
		Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																							
		<table border="1"> <thead> <tr> <th rowspan="2">MM</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>15.00</td> <td>15.10</td> <td>420.20</td> <td>420.05</td> <td>50</td> <td>45</td> </tr> <tr> <td>2</td> <td>10.10</td> <td>10.20</td> <td>420.37</td> <td>420.45</td> <td>30</td> <td>30</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>	MM	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	15.00	15.10	420.20	420.05	50	45	2	10.10	10.20	420.37	420.45	30	30	3							4							5							Final Measurement																						
MM	Lining			Drum/Rotor		Stroke																																																																			
	L	R	L	R	L	R																																																																			
1	15.00	15.10	420.20	420.05	50	45																																																																			
2	10.10	10.20	420.37	420.45	30	30																																																																			
3																																																																									
4																																																																									
5																																																																									
Final Measurement																																																																									
X		Section 4 - Steering: Defects (if any)																																																																							
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																							
X		Section 6 - Lamps: Defects (if any)																																																																							
X		Section 7 - Electrical System: Defects (if any)																																																																							
X		Section 8 - Body: Defects (if any)																																																																							
X		Section 9 - Tire & Wheel: Defects (if any)																																																																							
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th></th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>11</td> <td>10</td> <td>11</td> <td>11</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>2</td> <td>11</td> <td>11</td> <td>11</td> <td>9</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	11	10	11	11	100	100	100	100	2	11	11	11	9	100	100	100	100	3									4									5								
Axle	Tread Depth				Air Pressure																																																																				
	Initial		Corrected		Initial		Corrected																																																																		
	L	R	L	R	L	R	L	R																																																																	
1	11	10	11	11	100	100	100	100																																																																	
2	11	11	11	9	100	100	100	100																																																																	
3																																																																									
4																																																																									
5																																																																									
X		Section 10 - Coupling Devices: Defects (if any)																																																																							

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.
Vehicle received without repairs by: _____ Signature _____ Date: _____

FVS0022-01-(R-09/15)

PRESENT THIS COPY WHEN REGISTERING VEHICLE

Ce document peut être obtenu en français sur demande.