

Experian AutoCheck Report


Report run: 05/13/2026 14:31:21 EDT

2018 Toyota Tundra SR / SR5

Extended Cab 4D (5.7L V8 SMPI Flex Fuel)

VIN:	5TFUW5F1XJX743741
Class:	Pickup - Fullsize
Country of Assembly:	United States
Vehicle Age:	8 year(s)
Estimated In Service:	03/26/2018
Last Reported Odometer:	228,488 (10/08/2025)

One Owner
AutoCheck
Vehicle Usage
 Lease



Vehicle History at a Glance

<p>State Title Brand</p> <p>CLEAN</p>	<p>Auction Brand / Issues</p> <p>NO ISSUE</p>	<p>Accident / Damage Multiple Damage Events</p> <p>MINOR</p>
<p>Open Recall Check</p> <p>NO OPEN RECALLS</p>	<p>Insurance Loss / Transfer</p> <p>NO ISSUE</p>	<p>Odometer Check Last reported odometer: 228,488 (10/08/2025)</p> <p>NO ISSUE</p>
<p>Certified Pre-Owned</p> <p>NO CPO INFO AVAILABLE</p>	<p>Service / Repair 25 Service Record(s) Reported</p> <p>NO ISSUE</p>	<p>Additional History Lien Reported</p> <p>EVENTS REPORTED</p>




This vehicle is eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. [Terms & Conditions](#)

[Learn More](#)

Accident & Damage



Airbag Deployed



Structural Damage



Overturned



Minor

Damage Date	Damage Type	Severity
08/28/2019	Collision	Minor
07/25/2020	Collision	Unknown
11/02/2020	Collision	Unknown

Accident or damage event(s) have been reported for this vehicle to Experian AutoCheck. An inspection may provide added confidence in the vehicle's condition before purchase.

Service History

Service History Summary

Below is a summary of services that have been reported for this vehicle. Please note that not all maintenance events are reported to Experian AutoCheck.

Regular Oil Changes

- 5 oil services reported
- Last oil service reported 12/09/2020

Fluids Maintained

Information not available.

Brakes Maintained

- 2 brake pad replacements
- Brake last maintained on 12/09/2020

Tires Maintained

Information not available.

A/C & Climate Control

- 1 A/C services reported
- A/C system last serviced 09/13/2019

Other Services

- Cabin air filter replaced on 09/13/2019

OEM Recommended Services



120000 Mile Service

- Check installation of driver's floor mat
- Four Wheel Alignment
- Fuel Induction Service

Odometer Check

Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



State Title Odometer Check

No issues reported



Auction Odometer Check

No issues reported



Odometer Calculation Check

No issues reported

Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2018 Toyota Tundra SR / SR5 (5TFUW5F1XJX743741) Report Run Date: 05/13/2026 14:31:21 EDT

2018

Vehicle Prep and Other Pre-Titling Events

Preparation Date: 03/2018

Event Date	Location	Odometer	Data Source	Details
03/26/2018			Independent Source	Vehicle Manufactured and Shipped to Dealer
03/26/2018	TX		Independent Source	Vehicle Manufactured and Shipped to Dealer
09/03/2018	MC KINNEY, TX	2	Service Record	Multiple Point Vehicle Inspection Tires or Wheels Service Performed
09/06/2018			Service Record	Multiple Point Vehicle Inspection Tires or Wheels Service Performed

2018

Owner 1

Location: TX

Owned From: 11/2018

Usage: Lease

Event Date	Location	Odometer	Data Source	Details
11/15/2018	PLANO, TX		Motor Vehicle Dept.	Registration Event/Renewal
11/22/2018	PLANO, TX	11	Motor Vehicle Dept.	Title(Title #:04336743417101611) (Leased Vehicle)(Lien Reported)
12/06/2018	MC KINNEY, TX	5,083	Service Record	Fuel System Serviced
12/06/2018			Service Record	Safety Inspection Performed Multiple Point Vehicle Inspection
12/06/2018	MC KINNEY, TX		Service Record	Engine Serviced
12/06/2018			Service Record	Recommended Maintenance Performed Tires or Wheels Service Performed
02/08/2019	MC KINNEY, TX	10,730	Service Record	Multiple Point Vehicle Inspection Engine Serviced
02/08/2019			Service Record	Recommended Maintenance Performed Tires or Wheels Service Performed
03/26/2019		15,871	Service Record	Fuel System Serviced Multiple Point Vehicle Inspection Engine Serviced Recommended Maintenance Performed Suspension Serviced Tires or Wheels Service Performed
05/17/2019		21,437	Service Record	Air Filter Changed Multiple Point Vehicle Inspection
05/17/2019	MC KINNEY, TX		Service Record	Engine Serviced
05/17/2019			Service Record	Recommended Maintenance Performed Tires or Wheels Service Performed
07/24/2019	MC KINNEY, TX	25,906	Service Record	Multiple Point Vehicle Inspection Engine Serviced
07/24/2019			Service Record	Recommended Maintenance Performed Tires or Wheels Service Performed
08/28/2019	LEWISVILLE, TX		Damage Report	Accident or Damage Reported Minor Damage Reported
09/13/2019	MC KINNEY, TX	32,125	Service Record	Heat or Air Conditioning Serviced
09/13/2019			Service Record	Air Filter Changed Multiple Point Vehicle Inspection Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
12/09/2019	MC KINNEY, TX	39,613	Service Record	Multiple Point Vehicle Inspection
12/09/2019			Service Record	Brakes Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
04/16/2020	MC KINNEY, TX	51,041	Service Record	Multiple Point Vehicle Inspection
04/16/2020			Service Record	Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
06/17/2020	MC KINNEY, TX	56,633	Service Record	Multiple Point Vehicle Inspection

Event Date	Location	Odometer	Data Source	Details
06/17/2020			Service Record	Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
07/25/2020	FRISCO, TX		State Agency	Collision with Another Vehicle(Case #:17794190) Vehicle Had a Collision Accident Reported(Report #:3037294)
09/24/2020	PLANO, TX	67,087	Independent Emission Source	Passed Emission Inspection Passed Safety Inspection
11/01/2020	PLANO, TX		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
11/02/2020	PLANO, TX		Damage Report	Accident or Damage Reported Vehicle Damage Reported Left Side Damage or Repair Reported Front Damage or Repair Reported Damage or Repair to Bumper Reported Damage or Repair to Hood Reported Damage or Repair to Grille Reported Damage or Repair to Fender Reported
12/08/2020	MC KINNEY, TX	75,015	Service Record	Fuel System Serviced Multiple Point Vehicle Inspection Engine Serviced Brakes Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
12/09/2020		75,016	Service Record	Fuel System Serviced Multiple Point Vehicle Inspection Engine Serviced Brakes Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
10/29/2021	PLANO, TX	107,362	Independent Emission Source	Passed Emission Inspection Passed Safety Inspection
11/05/2021	PLANO, TX		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
06/24/2022		130,200	Service Record	Safety Inspection Performed Multiple Point Vehicle Inspection Engine Serviced Tires or Wheels Service Performed
09/27/2022	PLANO, TX	138,850	Independent Emission Source	Passed Emission Inspection Passed Safety Inspection
11/01/2022	MC KINNEY, TX		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
09/25/2023	MC KINNEY, TX	170,532	Independent Emission Source	Passed Emission Inspection Passed Safety Inspection
10/11/2023	MC KINNEY, TX		Motor Vehicle Dept.	Title(Title #:28695345207011328) (Leased Vehicle)
11/01/2023	MC KINNEY, TX		Motor Vehicle Dept.	Registration Event/Renewal
09/21/2024	MC KINNEY, TX	198,044	Independent Emission Source	Passed Emission Inspection Passed Safety Inspection
11/01/2024	MC KINNEY, TX		Motor Vehicle Dept.	Registration Event/Renewal
10/08/2025	MC KINNEY, TX	228,488	Independent Emission Source	Passed Emission Inspection Passed Safety Inspection
11/01/2025	MC KINNEY, TX		Motor Vehicle Dept.	Registration Event/Renewal

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (5TFUW5F1XJX743741) qualifies for [AutoCheck Buyback Protection](#). If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at www.autocheck.com/bbptterms or by writing to Experian: Experian Automotive C/O AutoCheckCustomer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle,

with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.