

Experian AutoCheck Report

Report run: 10/10/2026 13:10:27 EDT

2020 Ford F-250 Super Duty Lariat / XL / XLT

Extended Cab 4D (6.2L V8 SMPI Flex Fuel)


VIN:	1FT7X2A61LEC74470
Class:	Pickup - Fullsize
Country of Assembly:	United States
Vehicle Age:	6 year(s)
Estimated In Service:	05/28/2020
Last Reported Odometer:	263,675 (09/15/2026)

One Owner

AutoCheck

Vehicle Usage

Personal



Vehicle History at a Glance

State Title Brand CLEAN	Auction Brand / Issues NO ISSUE	Accident / Damage DAMAGE REPORTED
Open Recall Check 1 OPEN RECALL(S)	Insurance Loss / Transfer NO ISSUE	Odometer Check Last reported odometer: 263,675 (09/15/2026) NO ISSUE
Certified Pre-Owned NO CPO INFO AVAILABLE	Service / Repair 54 Service Record(s) Reported NO ISSUE	Additional History NO ISSUES REPORTED



This vehicle is eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. [Terms & Conditions](#)

Learn More



Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



State Title Odometer Check

No issues reported



Auction Odometer Check

No issues reported



Odometer Calculation Check

No issues reported



Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2020 Ford F-250 Super Duty Lariat / XL / XLT (1FT7X2A61LEC74470) Report Run Date: 10/10/2026 13:10:27 EDT

2020

Owner 1

Location: TXOwned From: 05/2020Usage: Personal				
Event Date	Location	Odometer	Data Source	Details
05/28/2020	DALLAS, TX		Motor Vehicle Dept.	Registration Event/Renewal
06/05/2020	DALLAS, TX	13	Motor Vehicle Dept.	Title(Title #:05752543977121835)
06/19/2020	GARLAND, TX	4,540	Service Record	Multiple Point Vehicle Inspection Engine Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
08/21/2020	GARLAND, TX	13,801	Service Record	Multiple Point Vehicle Inspection Engine Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
08/25/2020	GARLAND, TX	14,455	Service Record	Multiple Point Vehicle Inspection Tires or Wheels Service Performed
09/10/2020	GARLAND, TX	15,269	Service Record	Multiple Point Vehicle Inspection Tires or Wheels Service Performed
09/25/2020	GARLAND, TX	19,521	Service Record	Multiple Point Vehicle Inspection Engine Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
10/21/2020	GARLAND, TX	24,123	Service Record	Multiple Point Vehicle Inspection Engine Serviced Lube, Oil And/Or Filter Changed
11/06/2020			Manufacturer	Manufacturer Recall NHTSA Recall 20V575 / Mfr. Recall 20C19 Safety Compliance: REAR VIEW CAMERA IMPROPER FUNCTION LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR. Status: Remedy Available
11/09/2020	GARLAND, TX	27,099	Service Record	Cooling System Serviced Heat or Air Conditioning Serviced Air Filter Changed Multiple Point Vehicle Inspection Electrical System Serviced
12/03/2020	GARLAND, TX	29,613	Service Record	Air Filter Changed Multiple Point Vehicle Inspection Engine Serviced Lube, Oil And/Or Filter Changed
03/03/2021	GARLAND, TX	42,412	Service Record	Multiple Point Vehicle Inspection Engine Serviced Lube, Oil And/Or Filter Changed
04/06/2021	GARLAND, TX	47,353	Service Record	Cooling System Serviced Heat or Air Conditioning Serviced Air Filter Changed Multiple Point Vehicle Inspection



Event Date	Location	Odometer	Data Source	Details
05/01/2021	GARLAND, TX	50,845	Service Record	Battery Serviced or Replaced Multiple Point Vehicle Inspection Engine Serviced Brakes Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
05/11/2021	GARLAND, TX	51,967	Service Record	Multiple Point Vehicle Inspection Brakes Serviced
10/25/2021	GARLAND, TX	67,812	Service Record	Multiple Point Vehicle Inspection Engine Serviced Lube, Oil And/Or Filter Changed
12/22/2021	GARLAND, TX	72,553	Service Record	Air Filter Changed Multiple Point Vehicle Inspection Engine Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
01/31/2022	GARLAND, TX	75,297	Service Record	Tires or Wheels Service Performed
03/09/2022	GARLAND, TX	79,332	Service Record	Multiple Point Vehicle Inspection Engine Serviced Lube, Oil And/Or Filter Changed
05/03/2022	DALLAS, TX	84,148	Independent Emission Source	Passed Emission Inspection Passed Safety Inspection
05/03/2022	GARLAND, TX	84,148	Service Record	Safety Inspection Performed Emission System Serviced Multiple Point Vehicle Inspection Engine Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
05/04/2022	DALLAS, TX		Motor Vehicle Dept.	Registration Event/Renewal
07/02/2022	MESQUITE, TX		State Agency	Collision with a Parked Motor Vehicle(Case #:19005049) Vehicle Had a Collision Accident Reported(Report #:22057420)
09/28/2022	GARLAND, TX	100,402	Service Record	Multiple Point Vehicle Inspection Engine Serviced Brakes Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
10/11/2022	GARLAND, TX	101,817	Service Record	Tires or Wheels Service Performed
12/30/2022	GARLAND, TX	101,890	Service Record	Tires or Wheels Service Performed
02/06/2023	GARLAND, TX	112,886	Service Record	Multiple Point Vehicle Inspection Engine Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
02/27/2023	GARLAND, TX	114,833	Service Record	Cooling System Serviced Multiple Point Vehicle Inspection Engine Serviced Tires or Wheels Service Performed
03/27/2023	GARLAND, TX	119,055	Service Record	Multiple Point Vehicle Inspection Tires or Wheels Service Performed
04/19/2023	GARLAND, TX	121,073	Service Record	Multiple Point Vehicle Inspection Engine Serviced Lube, Oil And/Or Filter Changed
04/27/2023	DALLAS, TX	121,814	Independent Emission Source	Passed Emission Inspection Passed Safety Inspection
05/04/2023	DALLAS, TX		Motor Vehicle Dept.	Registration Event/Renewal
06/14/2023	GARLAND, TX	124,969	Service Record	Multiple Point Vehicle Inspection Engine Serviced Brakes Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
08/23/2023	GARLAND, TX	128,312	Service Record	Cooling System Serviced Heat or Air Conditioning Serviced Multiple Point Vehicle Inspection Engine Serviced Electrical System Serviced Lube, Oil And/Or Filter Changed
10/23/2023	GARLAND, TX	131,655	Service Record	Multiple Point Vehicle Inspection Engine Serviced Lube, Oil And/Or Filter Changed

Event Date	Location	Odometer	Data Source	Details
11/02/2023	GARLAND, TX	132,403	Service Record	Battery Serviced or Replaced Multiple Point Vehicle Inspection Electrical System Serviced Starting or Charging System Service Performed
01/22/2024	GARLAND, TX	138,173	Service Record	Air Filter Changed Multiple Point Vehicle Inspection Engine Serviced Brakes Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
03/19/2024	GARLAND, TX	144,279	Service Record	Cooling System Serviced Heat or Air Conditioning Serviced Multiple Point Vehicle Inspection Engine Serviced
04/11/2024	DALLAS, TX	146,606	Independent Emission Source	Passed Emission Inspection Passed Safety Inspection
05/01/2024	DALLAS, TX		Motor Vehicle Dept.	Registration Event/Renewal
05/06/2024	GARLAND, TX	149,548	Service Record	Multiple Point Vehicle Inspection Engine Serviced Drive Line Serviced Suspension Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
05/29/2024	GARLAND, TX	151,218	Service Record	Vehicle Serviced or Inspected
06/17/2024	GARLAND, TX	153,297	Service Record	Multiple Point Vehicle Inspection Engine Serviced
06/25/2024	GARLAND, TX	153,298	Service Record	Multiple Point Vehicle Inspection Tires or Wheels Service Performed
07/05/2024	GARLAND, TX	153,300	Service Record	Air Filter Changed Multiple Point Vehicle Inspection
07/11/2024	GARLAND, TX	155,701	Service Record	Heat or Air Conditioning Serviced Battery Serviced or Replaced Multiple Point Vehicle Inspection Engine Serviced Electrical System Serviced Lube, Oil And/Or Filter Changed
08/20/2024	GARLAND, TX	158,924	Service Record	Cooling System Serviced Multiple Point Vehicle Inspection Engine Serviced Lights or Signals Serviced
09/07/2024	GARLAND, TX	161,395	Service Record	Multiple Point Vehicle Inspection Engine Serviced Lube, Oil And/Or Filter Changed
10/08/2024	GARLAND, TX	166,247	Service Record	Multiple Point Vehicle Inspection Engine Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
11/06/2024	GARLAND, TX	170,607	Service Record	Vehicle Serviced or Inspected
12/16/2024	GARLAND, TX	176,035	Service Record	Air Filter Changed Multiple Point Vehicle Inspection Engine Serviced Lube, Oil And/Or Filter Changed
02/18/2025	GARLAND, TX	184,030	Service Record	Multiple Point Vehicle Inspection Tires or Wheels Service Performed
03/07/2025	GARLAND, TX	187,222	Service Record	Air Filter Changed Multiple Point Vehicle Inspection Engine Serviced Lube, Oil And/Or Filter Changed
03/11/2025	GARLAND, TX	187,778	Service Record	Multiple Point Vehicle Inspection Tires or Wheels Service Performed
05/16/2025	DALLAS, TX	192,400	Independent Emission Source	Passed Emission Inspection Passed Safety Inspection
05/22/2025	DALLAS, TX		Motor Vehicle Dept.	Registration Event/Renewal
01/06/2026	GARLAND, TX	224,117	Service Record	Air Filter Changed Multiple Point Vehicle Inspection Engine Serviced Lube, Oil And/Or Filter Changed

Event Date	Location	Odometer	Data Source	Details
01/12/2026	GARLAND, TX	224,200	Service Record	Safety Inspection Performed Battery Serviced or Replaced Multiple Point Vehicle Inspection Engine Serviced Brakes Serviced Tires or Wheels Service Performed
03/02/2026	GARLAND, TX	235,610	Service Record	Air Filter Changed Safety Inspection Performed Battery Serviced or Replaced Multiple Point Vehicle Inspection Engine Serviced Brakes Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
04/16/2026	GARLAND, TX	236,610	Service Record	Safety Inspection Performed Battery Serviced or Replaced Multiple Point Vehicle Inspection Engine Serviced Brakes Serviced Tires or Wheels Service Performed
05/01/2026	GARLAND, TX	243,224	Service Record	Air Filter Changed Safety Inspection Performed Battery Serviced or Replaced Multiple Point Vehicle Inspection Engine Serviced Brakes Serviced Drive Line Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
05/22/2026	GARLAND, TX	244,000	Service Record	Safety Inspection Performed Battery Serviced or Replaced Multiple Point Vehicle Inspection Engine Serviced Brakes Serviced Tires or Wheels Service Performed
06/20/2026	GARLAND, TX	249,986	Service Record	Air Filter Changed Safety Inspection Performed Battery Serviced or Replaced Multiple Point Vehicle Inspection Engine Serviced Brakes Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
07/24/2026	GARLAND, TX	256,277	Service Record	Air Filter Changed Safety Inspection Performed Battery Serviced or Replaced Multiple Point Vehicle Inspection Engine Serviced Brakes Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
08/27/2026	GARLAND, TX	260,637	Service Record	Air Filter Changed Safety Inspection Performed Battery Serviced or Replaced Multiple Point Vehicle Inspection Engine Serviced Brakes Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
09/15/2026	GARLAND, TX	263,675	Service Record	Air Filter Changed Safety Inspection Performed Battery Serviced or Replaced Multiple Point Vehicle Inspection Engine Serviced Brakes Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed

Unreported Event Dates

The following events have been reported to AutoCheck without a specified date.

Event Date	Location	Odometer	Data Source	Details
Unreported	TX		Independent Source	Vehicle Manufactured and Shipped to Dealer

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (1FT7X2A61LEC74470) qualifies for **AutoCheck Buyback Protection**. If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at www.autocheck.com/bbpterms or by writing to Experian: Experian Automotive C/O AutoCheckCustomer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.