

Experian AutoCheck Report


Report run: 06/16/2026 10:26:41 EDT

2023 Ram 2500 Tradesman

Crew Cab 4D (6.7L I6 CRDI Diesel)

VIN:	3C6UR5HL5PG584167
Class:	Pickup - Fullsize
Country of Assembly:	Mexico
Vehicle Age:	3 year(s)
Estimated In Service:	04/01/2023
Last Reported Odometer:	95,991 (02/27/2026)

One Owner
AutoCheck
Vehicle Usage
 Personal



Vehicle History at a Glance

<p>State Title Brand</p> <p>CLEAN</p>	<p>Auction Brand / Issues</p> <p>NO ISSUE</p>	<p>Accident / Damage No Accidents or Damage Reported</p> <p>NO ISSUE</p>
<p>Open Recall Check</p> <p>NO OPEN RECALLS</p>	<p>Insurance Loss / Transfer</p> <p>NO ISSUE</p>	<p>Odometer Check Last reported odometer: 95,991 (02/27/2026)</p> <p>NO ISSUE</p>
<p>Certified Pre-Owned</p> <p>NO CPO INFO AVAILABLE</p>	<p>Service / Repair 11 Service Record(s) Reported</p> <p>NO ISSUE</p>	<p>Additional History</p> <p>NO ISSUES REPORTED</p>




This vehicle is eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. [Terms & Conditions](#)

[Learn More](#)

Accident & Damage

Your Vehicle Checks Out There were no accidents or damage events disclosed to Experian AutoCheck for this vehicle. Since not all damage-related events are reported to Experian AutoCheck, an inspection may provide added confidence in the vehicle's condition before purchase.



Service History

Service History Summary

Below is a summary of services that have been reported for this vehicle. Please note that not all maintenance events are reported to Experian AutoCheck.

Regular Oil Changes

- 2 oil services reported
- Last oil service reported 01/08/2025

Fluids Maintained

- 1 coolant flushes
- Last fluid maintained 05/26/2025

Brakes Maintained

- 1 brake pad replacements
- Brake last maintained on 05/26/2025

Tires Maintained

Information not available.

A/C & Climate Control

- 1 A/C services reported
- A/C system last serviced 02/27/2026

Other Services

- Cabin air filter replaced on 02/27/2026
- Battery replaced on 09/09/2024

OEM Recommended Services

90000 Mile Service

- Change engine oil and engine oil filter
- Check coolant level, hoses, and clamps
- Check Diesel Exhaust Fluid (DEF) tank, refill if necessary

96000 Mile Service Not Yet Due

- Change engine oil and engine oil filter
- Inspect and replace the Evaporative system fresh air filter as necessary
- Inspect battery and clean and tighten terminals as required

Odometer Check

Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



State Title Odometer Check

No issues reported



Auction Odometer Check

No issues reported



Odometer Calculation Check

No issues reported

Detailed Vehicle History

2023

Vehicle Prep and Other Pre-Titling Events

Location: MIDLAND, TX

Preparation Date: 04/2023

Event Date	Location	Odometer	Data Source	Details
04/01/2023	MIDLAND, TX	4	Lithia All American Chrysler Jeep Dodge of 915.522.3115	Multiple Point Vehicle Inspection Promotional Service Performed
06/08/2023	TX	4	Motor Vehicle Dept.	Passed Emission Inspection Passed Safety Inspection

2023

Owner 1

Location: TX

Owned From: 06/2023












Usage: Personal

Event Date	Location	Odometer	Data Source	Details
06/20/2023	TX		Motor Vehicle Dept.	Registration Event/Renewal
06/28/2023	TX	5	Motor Vehicle Dept.	Title(Title #:01562745095082636)
08/26/2024	CORPUS CHRISTI, TX	41,853	Lithia CHRYSLER DODGE JEEP RAM OF CALALLEN 412.264.9222	Fuel System Serviced Air Filter Changed Battery Serviced or Replaced Emission System Serviced Multiple Point Vehicle Inspection Transmission Serviced Electrical System Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
09/09/2024	TX	41,853	Service Record	Fuel System Serviced Vehicle Inspected Air Filter Changed Battery Serviced or Replaced Emission System Serviced Transmission Serviced Electrical System Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
01/02/2025	CORPUS CHRISTI, TX	51,965	Lithia CHRYSLER DODGE JEEP RAM OF CALALLEN 412.264.9222	Fuel System Serviced Air Filter Changed Multiple Point Vehicle Inspection Electrical System Serviced Lights or Signals Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
01/08/2025	TX	51,965	Service Record	Fuel System Serviced Vehicle Inspected Air Filter Changed Electrical System Serviced Lights or Signals Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
02/03/2025	CORPUS CHRISTI, TX	54,485	Lithia CHRYSLER DODGE JEEP RAM OF CALALLEN 412.264.9222	Fuel System Serviced Multiple Point Vehicle Inspection Accessories Serviced or Installed Engine Serviced Engine Serviced Electrical System Serviced Lights or Signals Serviced Tires or Wheels Service Performed Body Service Performed
02/14/2025	TX	54,485	Service Record	Fuel System Serviced Vehicle Inspected Accessories Serviced or Installed Engine Serviced Engine Serviced Electrical System Serviced Lights or Signals Serviced Tires or Wheels Service Performed

Event Date	Location	Odometer	Data Source	Details
05/26/2025	BIG SPRING, TX	63,464	Service Record	Steering System Serviced Multiple Point Vehicle Inspection Engine Serviced Recommended Maintenance Performed Transmission Serviced Brakes Serviced Tires or Wheels Service Performed Vehicle Fluids Serviced
06/01/2025	TX		Motor Vehicle Dept.	Registration Event/Renewal
06/03/2025	BIG SPRING, TX	63,572	Service Record	Steering System Serviced Multiple Point Vehicle Inspection Recommended Maintenance Performed
06/17/2025	CORPUS CHRISTI, TX	73,789	Lithia CHRYSLER DODGE JEEP RAM OF CALALLEN 412.264.9222	Fuel System Serviced Air Filter Changed Multiple Point Vehicle Inspection Tires or Wheels Service Performed
02/27/2026	BIG SPRING, TX	95,991	Service Record	Cooling System Serviced Heat or Air Conditioning Serviced Air Filter Changed Multiple Point Vehicle Inspection Engine Serviced Recommended Maintenance Performed Alternator Serviced

Warranty Check

The warranty coverage shown below is an estimate using the best available in-service date, mileage readings, and warranty information. Enter the exact odometer reading below for more accurate results. Experian AutoCheck does not guarantee coverage, please verify these results and coverage details with an authorized dealership.

Coverage Type	Remaining Miles	Remaining Time	Status	Coverage Details
Basic 	-	-		36 months / 36000 miles Specified Components 1 year/12000 miles.
Battery 	-	-	-	Contact a certified dealer to verify coverage
Corrosion 	-	22 months		60 months / Unlimited miles Outer Panel Corrosion Warranty. All panels are covered for 3 years/unlimited miles.
Powertrain 	-	22 months		60 months / 100000 miles
Roadside Assistance 	-	22 months		60 months / 100000 miles
Safety Restraint 	-	82 months		120 months / Unlimited miles For vehicles sold and registered in Kansas, coverage is 10 years/ unlimited miles.

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (3C6UR5HL5PG584167) qualifies for [AutoCheck Buyback Protection](#). If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at www.autocheck.com/bbpterm or by writing to Experian: Experian Automotive C/O AutoCheckCustomer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.