



LTEK Diagnostics
 8355 Saint Andrews Avenue
 San Diego, CA 92154
 (619) 848-0459
 service@ltekdiagnostics.com
 www.LTEKdiagnostics.com

Invoice #6368

Created: 01/19/2026
 Invoiced: 01/21/2026
 Payment Term: On Receipt
 Payment Due: 01/21/2026
 Service Writer: Beto Herrera

2020 Freightliner Cascadia 126 (Red, #747)
 VIN: 1FUJHHDR5LLKN2083

Mileage: 963,479 mi

Customer Comments

CEL ON

Oil Service

PERFORMED OIL SERVICE WITH GREASE.

Description	Price	QTY	HRS	Subtotal
Labor: Engine Oil & Filter R&R w Grease			0.94	\$150.00
Part: FUEL FILTER Part #: A4700903151	\$121.94	1		\$121.94
Part: OIL FILTER W/SEALS Part #: A4711800209	\$47.12	1		\$47.12
Part: DETROIT MOTOR OIL 10W-30 Part #: MBL23512741	\$109.22	2		\$218.44
Part: 10W-30 (GALLON) Part #: MBL23512703	\$32.29	1		\$32.29
Fee: Hazardous Waste & Filter Disposal Fee				\$25.00
			Tax (7.75%):	\$32.53
			Total:	\$627.32

CEL ON

CONNECTED TO UNIT, ANALYZED FAULT CODES, AND PERFORMED FULL SYSTEM DIAGNOSTICS. AFTER DIAGNOSIS, PROCEEDED TO REPLACE DPF FILTERS ALONG WITH THE INLET NOX SENSOR AND OUTLET NOX SENSOR. COMPLETED SCR EFFICIENCY TEST TO VERIFY AFTERTREATMENT SYSTEM PERFORMANCE. ALL TESTS PASSED, FAULT CODES WERE CLEARED, AND PROPER OPERATION WAS CONFIRMED AFTER REPAIR.

REPLACE A T FITTING.

Description	HRS	Subtotal
Labor: DIAGNOSIS		\$0.00
Labor: SEAL 1 BOX LEAK & PLUG SCR EFFICIENCY	5	\$800.00
Labor: INLET NOX SENSOR INSTALLATION	2.13	\$340.00
Labor: OUTLET NOX SENSOR INSTALLATION	2.13	\$340.00
Shop Supplies (0.5%):		\$7.40
Tax (7.75%):		\$0.57
Total:		\$1,487.97

BIT/90 Day Inspection

Description	HRS	Subtotal
Labor: BIT Inspection	0.38	\$60.00
Total:		\$60.00



LTEK Diagnostics
 8355 Saint Andrews Avenue
 San Diego, CA 92154
 (619) 848-0459
 service@ltekdiagnostics.com
 www.LTEKdiagnostics.com

Invoice #6368

Created: 01/19/2026
Invoiced: 01/21/2026
Payment Term: On Receipt
Payment Due: 01/21/2026
Service Writer: Beto Herrera

By paying this invoice and/or taking delivery, I agree that payment is due on pickup and that LTEK may retain a mechanic's lien and withhold release until all charges are paid in full. LTEK's 6-month workmanship (labor) warranty applies only to labor performed at LTEK with new OEM parts purchased through LTEK; used/rebuilt or customer-supplied parts void any labor warranty and carry no parts warranty. I am responsible for my personal property; LTEK is not responsible for theft/loss of items or for natural-disaster damage or other events beyond LTEK's control (except for LTEK's gross negligence or willful misconduct). Vehicles not picked up within 30 days of completion/ready notice accrue \$25/day storage and may be processed under California lien-sale procedures (including potential sale after ~90 days with required notice).

Labor	\$1,690.00
Parts	\$419.79
Subtotal	\$2,109.79
Shop Supplies	\$7.40
EPA	\$0.00
Fees	\$25.00
Tax	\$33.11
Grand Total	\$2,175.30
Paid to Date	(\$0.00)

REMAINING BALANCE	\$2,175.30
--------------------------	-------------------

Signature _____

Messages

Sebastian Salgado

1/21/2026 3:21 PM PST

Below is a link to the estimate you requested from LTEK Diagnostics. Please review and let us know if you have any questions.

File: order-6368-repairOrder-2026-01-21_15-21-50.pdf



LTEK Diagnostics
 8355 Saint Andrews Avenue
 San Diego, CA 92154
 (619) 848-0459
 service@ltekdiagnostics.com
 www.LTEKdiagnostics.com

Invoice #6368

Created: 01/19/2026
 Invoiced: 01/21/2026
 Payment Term: On Receipt
 Payment Due: 01/21/2026
 Service Writer: Beto Herrera

2020 Freightliner Cascadia 126 (Red, #747)
 VIN: 1FUJHHDR5LLKN2083
 License Plate: RP12447
 Mileage: 963,479 mi

BIT Inspection

Inspected: 01/21/2026
 Completed: 01/21/2026

Item	Green	Yellow	Red	N/A
1 Windshield & windows: cracks, chips, obstructions / Wipers & washer system: blades condition, spray function	✓			
Note/Recommendation:				
2 Parking brake knob: labeled & functioning	✓			
Note/Recommendation:				
3 HVAC / A/C: cold, fan speeds functional	✓			
Note/Recommendation:				
4 Horns: both city & air horn operational	✓			
Note/Recommendation:				
5 Directional signals & hazards / Headlights (low/high beam) / Brake lights & reverse lights / Rear & clearance/marker lights / Reflectors: cab, mud flaps, trailer / Wiring harnesses: fraying, rubbing, corrosion / Battery condition & terminals	✓			
Note/Recommendation:				
6 Fire extinguisher: charged, accessible, tagged / Reflective triangles: 3 present, condition verified / First aid kit (optional fleet add-on)	✓			
Note/Recommendation:				
7 Glad hands & trailer hoses: leaks, cracks, chafing / Electrical pigtail: no exposed wires, secure connections	✓			
Note/Recommendation:				
8 Cab suspension: airbags, shocks, bushings	✓			
Note/Recommendation:				
9 Frame rails & crossmembers: cracks, bends	✓			



LTEK Diagnostics
 8355 Saint Andrews Avenue
 San Diego, CA 92154
 (619) 848-0459
 service@ltekdiagnostics.com
 www.LTEKdiagnostics.com

Invoice #6368

Created: 01/19/2026
 Invoiced: 01/21/2026
 Payment Term: On Receipt
 Payment Due: 01/21/2026
 Service Writer: Beto Herrera




Item	Green	Yellow	Red	N/A
Note/Recommendation:				
10	Torque arms, brackets, and bushings: wear/looseness	✓		
Note/Recommendation:				
11	Fifth wheel: secure, locking mechanism, grease condition	✓		
Note/Recommendation:				
12	All visible hardware: loose/missing bolts	✓		
Note/Recommendation:				
13	Tires: cuts, bulges, irregular wear / Lug nuts: torque check, missing/damaged	✓		
Note/Recommendation:				
14	Hubcaps & seals: leaks or cracks	✓		
Note/Recommendation:				
15	Brake pad/shoe thickness (record %)	✓		
Note/Recommendation:				
16	Air chambers: leaks, mounting secure / Air lines: rubbing, leaks, routing / Applied/Static air leaks: verify at all wheels			✓
Note/Recommendation: <i>Applied air leak on foot valve T fitting 1/4 on foot valve</i>				
17	Wheel seals: leaks	✓		
Note/Recommendation:				
18	Brake stroke length (record pushrod measurement)		✓	
Note/Recommendation: <i>Brake adjustment</i>				



LTEK Diagnostics
8355 Saint Andrews Avenue
San Diego, CA 92154
(619) 848-0459
service@ltekdiagnostics.com
www.LTEKdiagnostics.com

Invoice #6368

Created: 01/19/2026
Invoiced: 01/21/2026
Payment Term: On Receipt
Payment Due: 01/21/2026
Service Writer: Beto Herrera

Item	Green	Yellow	Red	N/A
				
19 Leaf spring packs & bushings: cracks, wear, movement	✓			
Note/Recommendation:				
20 Airbags: leaks, cuts, proper inflation	✓			
Note/Recommendation:				
21 Shocks: leaks, bushings, secure mounts	✓			
Note/Recommendation:				
22 Front tires & steering components: tie rods, drag link, play	✓			
Note/Recommendation:				
23 Engine block & surrounding area: oil, coolant, fuel leaks	✓			
Note/Recommendation: <i>Oil separator fitting leak class 1</i>				
<i>Turbo oil drain tube sweat leak</i>				
				
				



LTEK Diagnostics
8355 Saint Andrews Avenue
San Diego, CA 92154
(619) 848-0459
service@ltekdiagnostics.com
www.LTEKdiagnostics.com

Invoice #6368

Created: 01/19/2026
Invoiced: 01/21/2026
Payment Term: On Receipt
Payment Due: 01/21/2026
Service Writer: Beto Herrera

	Item	Green	Yellow	Red	N/A
24	Belts: cracks, tension, alignment	✓			
	Note/Recommendation:				
25	Pulleys & accessory drive: condition	✓			
	Note/Recommendation:				
26	A/C lines: leaks, fittings secure	✓			
	Note/Recommendation:				
27	Electrical wiring: exposed, rubbing, corrosion	✓			
	Note/Recommendation:				
28	Power steering: fluid, pump, gear box play	✓			
	Note/Recommendation:				
29	Transmission: leaks	✓			
	Note/Recommendation:				
30	Radiator mounts & brackets	✓			
	Note/Recommendation:				
31	Driveline: U-joints, carrier bearing, slip joint play	✓			
	Note/Recommendation:				
32	Brake chambers: leaks, mounting secure	✓			
	Note/Recommendation:				
33	Differential housing: leaks, play from diff ☒ driveline ☒ trans	✓			
	Note/Recommendation:				
	Totals	31	1	1	0