



Vehicle Standards and Inspection

Heavy Truck Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # P266484

Station #: 71216

Station Name: Astro Towing 1988 Ltd

Technician #: 88928

Technician Name: David Launders

Signing Officer #: 91081

Signing Officer Name: Andrew Clewes

Customer Details:

Name: Astro Towing

Address: 126 Gladstone Crescent, Saskatoon, Saskatchewan, S7P 0C7

Inspection Completed Date: 31Jul2025

Inspection Expiry Date: 31Jul2026

Vehicle Details:

VIN: 1FVACXDT9EHFJ8259


Odometer Reading: 748024 km

Year: 2014

Vehicle Make/Model: FREIGHTLINER/HEAVY VEHICLE

Plate: 056KJQ

Jurisdiction: Saskatchewan



Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Heavy Truck Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71216

Station Name: Astro Towing 1988 Ltd

Technician #: 88928

Technician Name: David Launders

Signing Officer #: 91081

Signing Officer Name: Andrew Clewes

Customer Details:

Name: Astro Towing

Address: 126 Gladstone Crescent, Saskatoon, Saskatchewan, S7P 0C7

Vehicle Details:

VIN: 1FVACXDT9EHFJ8259

Odometer Reading: 748024 km

Year: 2014

Vehicle Make/Model: FREIGHTLINER HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
		x		Sun Visor Interior (8)	DRIVERS SIDE SUN VISOR BROKEN
x				Hcm Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
		x		Windshield/Other Glass (8)	DRIVERS SIDE DOOR WINDOW WILL NOT OPEN
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Headlamp Aim (5)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
		x		Mud Flaps/Fenders (8)	BOTH FRONT FENDERS CRACKED
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Utilized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
------	----------	-----------	----------	---------	----------

x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	BRAKE HOSES RUBBING/ PASSENGER SIDE REAR BRAKE POT LOOSE
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
		x		Drive Shaft/Universal Joints (1)	BOTH STEADY BEARINGS WORN OUT
x				Exhaust/Emission System (1)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 15/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 16 mm • Cam Rotation: 51.C degrees • Brake Stroke: 1 1/2 in

Wheel2-On : Tire Tread Depth: 15/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 18 mm • Cam Rotation: 50.C degrees • Brake Stroke: 1 1/2 in

Axle 2-Pass

Wheel1 : Tire Tread Depth: 12/32 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 12/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 16 mm • Cam Rotation: 51.C degrees • Brake Stroke: 1 1/2 in

Wheel3-On : Tire Tread Depth: 5/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15 mm • Cam Rotation: 63.C degrees • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 11/32 in

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Deca # P266484

Inspection Completed Date: 31Jul2025