



Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A217536

Station #: 71459

Station Name: Funk Mechanical

Technician #: 91482

Technician Name: Kyle Bryson

Signing Officer #: 88859

Signing Officer Name: Patty Lindsay

Customer Details:

Name: Wayne Megli

Address: Box 607, Carrot River, Saskatchewan, S0E0L0

Inspection Completed Date: 28Oct2025

Inspection Expiry Date: 31Oct2026

Vehicle Details:

VIN: 2L9A15381NH003311

Hubometer Reading:

Year: 2022

Vehicle Make/Model: LORNES TRAILER/

Plate: 750 MMI

Jurisdiction: Saskatchewan

Unit: 750 MMI

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A217537

Station #: 71459

Station Name: Funk Mechanical

Technician #: 91482

Technician Name: Kyle Bryson

Signing Officer #: 88859

Signing Officer Name: Patty Lindsay

Customer Details:

Name: Wayne Megli

Address: Box 607, Carrot River, Saskatchewan, S0E0L0

Inspection Completed Date: 28Oct2025

Inspection Expiry Date: 31Oct2026

Vehicle Details:

VIN: 2L9A19282NH003312

Hubometer Reading:

Year: 2022

Vehicle Make/Model: LORNES TRAILER/

Plate: 751 MMI

Jurisdiction: Saskatchewan

Unit: 751 MMI

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.