04144565

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL
VOID WITHOUT DECAL
Manitoba
C100206

	DAY	MO.	YR.
Date Inspection Started	22	10	26
Date Inspection Completed	23	10	26
Inspection Expiry Date	31	10	27

Station Number: AB017 — Station Name: Lucky Star Wash A[illegible] — City: [illegible]

Mechanic Number: M101916 — Mechanic Signature: [signature] — Station Phone Number: 204-571-1531

Vehicle Owner: Rouisseau Transport LTD

Address: Site 145 Box 46 RR1 — City: Brandon — Province: MB — Postal Code: R7A 5Y1 — Phone:

- [ ] Pass/Safe Vehicle
- [X] Fail/Unsafe Vehicle
- [ ] Fail/Hazardous

Licence Number: 1111A1 — Prov.: MB — NSC #: MB079371[illegible] — Odometer Reading: 31473 — Odom. Type: [ ] km [X] mi

Vehicle Identification Number: 1H1080B[illegible] — Make: Trim — Model: Tanker — Year: 1979 — Unit #: A45

[X] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

____Truck GVWR ____ KGS ____Truck Tractor ____Trailer X Semi-Trailer ____Bus ____School Bus ____Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P = Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

R =

Section 1 - Power Train: Defects (if any)

Section 2 Suspension: Defects (if any)

Section 3 - Brake Systems: 3H 3A (3A) — Circle Brake Type

Defects (if any)

Brake Inspection Type: A B C D E — Circle appropriate Letter for Internal Brake Component Inspection

	Lining		Drum/Rotor		Stroke	
Axle	L	R	L	R	L	R
1	12	13	16.571	16547	1½	1½
2	10	11	16574	16544	1½	1½
3						
4		16"				
5						
	Final Measurement					

Section 4 - Steering: Defects (if any)

Section 5 - Instruments & Auxiliary Equipment: Defects (if any)

Section 6 - Lamps: Defects (if any) X-3C- Reflective tape damaged

Section 7 - Electrical System: Defects (if any)

Section 8 - Body: Defects (if any) X-2SB- Rear impact guard damaged

Section 9 - Tire & Wheel: Defects (if any)

	Tread Depth								Air Pressure							
	Initial				Corrected				Initial				Corrected			
Axle	L		R		L		R		L		R		L		R	
1	11	12	11	14					100	100	100	100				
2	11	11	14	12					100	100	100	100				
3																
4																
5			32"													

Section 10 - Coupling Devices: Defects (if any)

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

FVS0022-01-(R-06/25)

Ce document peut être obtenu en français sur demande.

COPY IN CAB - PLEASE ENSURE CERTIFICATE IS SIGNED - NOT FOR REGISTRATION