04144561

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Outl
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba C100202

Date Inspection Started: 22 DAY / 10 MO. / 26 YR.
Date Inspection Completed: 22 DAY / 10 MO. / 26 YR.
Inspection Expiry Date: 31 DAY / 10 MO. / 27 YR.

Station Number: A30117 — Station Name: Luckystar wash — City
Mechanic Number: m012120 — Mechanic Signature — Station Phone Number: 204-571-1531

Vehicle Owner: Renaissance Transport LTD
Address: Site 145 Box 46 RR1 — City: Brandon — Province: MB — Postal Code: R7A 5Y1 — Phone

- [x] Pass/Safe Vehicle
- [ ] Fail/Unsafe Vehicle
- [ ] Fail/Hazardous

Licence Number: N/A — Prov.: N/A — NSC #: N/A — Odometer Reading: N/A — Odom. Type: ☐ km ☐ mi

Vehicle Identification Number: T40804 — Make: Rotex — Model: Tanker — Year: 1979 — Unit #: A47

[x] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

____Truck GVWR KGS ____Truck Tractor ____Trailer ✓Semi-Trailer ____Bus ____School Bus ____Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
✓		**Section 1 - Power Train:** Defects (if any)
✓		**Section 2 Suspension:** Defects (if any)
✓		**Section 3 - Brake Systems:** 3H 3A (2) Defects (if any) — Circle Brake Type
✓		**Section 4 - Steering:** Defects (if any)
✓		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
✓	✓	**Section 6 - Lamps:** Defects (if any) X-1T-RHS rear clearance lamp inoperative X-3C-Rear top reflective tape reflective properties compromised
✓		**Section 7 - Electrical System:** Defects (if any)
✓		**Section 8 - Body:** Defects (if any)
✓	✓	**Section 9 - Tire & Wheel:** Defects (if any) X-5D-L2 hubcap has a leucl II oil leak
✓		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: A (B) C D E — Circle appropriate Letter for Internal Brake Component Inspection

	Lining		Drum/Rotor		Stroke	
Axle	L	R	L	R	L	R
1	8	13	16.546	16.573	1½	1½
2	11	11	16.582	16.536	1½	1½
3	16¹¹					
4						
5						
	Final Measurement					

	Tread Depth								Air Pressure							
	Initial				Corrected				Initial				Corrected			
Axle	L		R		L		R		L		R		L		R	
1	12	12	16	10					100	100	100	100				
2	12	6	6	8					100	100	100	100				
3	32¹¹															
4																
5																

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature

Ce document peut être obtenu en français sur demande.

COPY IN CAB - PLEASE ENSURE CERTIFICATE IS SIGNED - NOT FOR REGISTRATION