

A932521

Date Inspection Started DAY: 05 MO: 08 YR: 25			Station Number A141A1			Station Name Pacific Noel Services KILGOUR		
Date Inspection Completed DAY: 12 MO: 08 YR: 25			Mechanic Number M19181015			Station Phone Number 204-523-4500		
Inspection Expiry Date DAY: 31 MO: 08 YR: 26			Vehicle Owner Truck Freight International					
			Address 2200-333 Main St. WYOMING		City WYOMING		Province R3C4E2	
					Postal Code 204-956-2090		Phone	

☒ Pass/Safe Vehicle		Licence Number KLUB5B		Prov. MB		NSC # [Blank]		Odometer Reading 476,435		Odom. Type ☐ km ☒ mi	
☒ Fail/Unsafe Vehicle		Vehicle Identification Number 1F11AN1HGM06LM01BA1F6		Make Mack		Model Auburn		Year 2000		Unit # 1105	
☐ Fail/Hazardous		☒ Confirmed leasible Vehicle Identification Number on vehicle									

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

_____ Truck GVWR
214100 KGS ☒ Truck Tractor _____ Trailer _____ Semi-Trailer _____ Bus _____ School Bus _____ Coach Bus
 List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																						
X		Section 1 - Power Train: Defects (if any)																																																																						
X	X	Section 2 Suspension: Defects (if any) <i>axle 1, 3 L & R Shocks leaking - 7C</i>																																																																						
X	X	Section 3 - Brake Systems: <u>3H 3A</u> <i>4-7</i> Defects (if any) <i>Brake Lines on axle 2 & 3 - 2 defects 6 lines</i> <i>all brake lines have surface cracks with 15B</i> <i>some of large & medium 15D</i> <i>all wheels have 15B</i>																																																																						
		Brake Inspection Type: <u>A</u> B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																						
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>11/16</td> <td>11/16</td> <td>16.5</td> <td>16.5</td> <td>1.25</td> <td>1.25</td> </tr> <tr> <td>2</td> <td>10/16</td> <td>12/16</td> <td>16.5</td> <td>16.5</td> <td>1.25</td> <td>1.25</td> </tr> <tr> <td>3</td> <td>12/16</td> <td>11/16</td> <td>16.5</td> <td>16.5</td> <td>1.25</td> <td>1.25</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	11/16	11/16	16.5	16.5	1.25	1.25	2	10/16	12/16	16.5	16.5	1.25	1.25	3	12/16	11/16	16.5	16.5	1.25	1.25	4							5							Final Measurement																					
Axle	Lining			Drum/Rotor		Stroke																																																																		
	L	R	L	R	L	R																																																																		
1	11/16	11/16	16.5	16.5	1.25	1.25																																																																		
2	10/16	12/16	16.5	16.5	1.25	1.25																																																																		
3	12/16	11/16	16.5	16.5	1.25	1.25																																																																		
4																																																																								
5																																																																								
Final Measurement																																																																								
		Section 4 - Steering: Defects (if any)																																																																						
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																						
X	X	Section 6 - Lamps: Defects (if any) <i>Rear lamp not working - 1N 1/16. Brake light not working - 1F</i> <i>1/16. Brake light not working - 1F 1/16. Brake light not working - 1F</i> <i>1/16. Brake light not working - 1F 1/16. Brake light not working - 1F</i>																																																																						
X		Section 7 - Electrical System: Defects (if any)																																																																						
X		Section 8 - Body: Defects (if any) <i>Passenger Side Body Panel torn - 4A</i> <i>Driver Side Mirror - 15D</i> <i>Driver Side Mirror - Glass missing - 15C</i>																																																																						
X		Section 9 - Tire & Wheel: Defects (if any)																																																																						
		<table border="1"> <thead> <tr> <th rowspan="3">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>32</td> <td>32</td> <td></td> <td></td> <td>100</td> <td>100</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>32</td> <td>32</td> <td></td> <td></td> <td>100</td> <td>100</td> <td></td> <td></td> </tr> <tr> <td>3</td> <td>32</td> <td>32</td> <td></td> <td></td> <td>100</td> <td>100</td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	32	32			100	100			2	32	32			100	100			3	32	32			100	100			4									5								
Axle	Tread Depth				Air Pressure																																																																			
	Initial			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1	32	32			100	100																																																																		
2	32	32			100	100																																																																		
3	32	32			100	100																																																																		
4																																																																								
5																																																																								
X		Section 10 - Coupling Devices: Defects (if any)																																																																						

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature _____

Date _____

FY2022-01-R-09/15

Ce document peut être obtenu en français sur demande.

CONFIDENTIAL - THIS INFORMATION IS UNCLASSIFIED EXCEPT WHERE SHOWN OTHERWISE NOT FOR DISTRIBUTION

Scanned with
CS CamScanner