04117837

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba
C100199

Date Inspection Started: DAY 30 MO. 10 YR. 26
Date Inspection Completed: DAY 30 MO. 10 YR. 26
Inspection Expiry Date: DAY 31 MO. 10 YR. 27

Station Number: 43017 Station Name: Lucky Star Wash City: [illegible]
Mechanic Number: M10220 Mechanic Signature: [signature] Station Phone Number: 204-571-1531

Vehicle Owner: Rogasch Transport LTD
Address: Site 145 Box 46 PR1 City: Brandon Province: MB Postal Code: R7A 5Y1 Phone:

- [x] Pass/Safe Vehicle
- [x] Fail/Unsafe Vehicle
- [ ] Fail/Hazardous

Licence Number: [illegible] Prov. MB NSC # 10A Odometer Reading: 259444 Odom. Type: [ ] km [x] mi

Vehicle Identification Number: 5H0BBH[illegible] Make: Trail Model: Tanker Year: 977 Unit #: A21

- [x] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

____Truck GVWR KGS ____Truck Tractor ____Trailer X Semi-Trailer ____Bus ____School Bus ____Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
X		**Section 3 - Brake Systems:** 3H (3A) Defects (if any) Circle Brake Type
/		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X		**Section 6 - Lamps:** Defects (if any)
X		**Section 7 - Electrical System:** Defects (if any)
X		**Section 8 - Body:** Defects (if any)
X	X	**Section 9 - Tire & Wheel:** Defects (if any) 1-SO RO hubcap has level & oil leak
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: A (B) C D E Circle appropriate Letter for Internal Brake Component Inspection

	Lining		Drum/Rotor		Stroke	
Axle	L	R	L	R	L	R
1	12	11	16.57	16545	1 1/2	1 1/2
2	9	8	16536	16540	1 1/2	1 1/2
3	11	8	16547	16594	1 1/2	1 1/2
4						
5						
	Final Measurement					

	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
Axle	L	R	L	R	L	R	L	R
1	8	16				100 100		
2	15 16	12 12			100 100	100 100		
3	17 22	15 15			100 100	100 100		
4								
5		30"						

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature _____ Date: _____

FVS0022-01-(R-06/25)

Ce document peut être obtenu en français sur demande.

COPY IN CAB - PLEASE ENSURE CERTIFICATE IS SIGNED - NOT FOR REGISTRATION