

04063401

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45084 Regent Postal
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba

C048496

Date Inspection Started 07 04 26
Date Inspection Completed 10 04 26
Inspection Expiry Date 30 04 27

Station Number A12019 R Lewandowski Farms
Mechanic Number M9415
Station Name
City
Mechanic Signature
Station Phone Number 204-585-2120

Vehicle Owner Balan Grawelling
Address
City
Province
Postal Code
Phone

- ☒ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number
Prov.
NSC #
Odometer Reading
Odom. Type km mi
Vehicle Identification Number 2MFB2S14D1XR1007542
Confirmed legible Vehicle Identification Number on vehicle
Make mid Model grad Year 14 Unit #

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GVWR KGS Truck Tractor Trailer ☒ Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		Section 1 - Power Train: Defects (if any)
X	X	Section 2 Suspension: Defects (if any) 2 (7-A) axle 3L Shock
X	X	Section 3 - Brake Systems: 3H (3A) Defects (if any) Circle Brake Type 3A(15-B) axle 1, 2 + 3 linings worn 3A(15-D) all axes drums worn except axle 3R 3A(14-A) axle 2L brake chamber + axle 3R
X		Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X		Section 6 - Lamps: Defects (if any)
X		Section 7 - Electrical System: Defects (if any)
X		Section 8 - Body: Defects (if any)
X		Section 9 - Tire & Wheel: Defects (if any)
X		Section 10 - Coupling Devices: Defects (if any)

Axle	mm Tread Depth				Air Pressure							
	Initial		Corrected		Initial		Corrected					
	L	R	L	R	L	R	L	R				
1	10	11	7	10	95	95	95	95	100	100	100	100
2	6	6	6	6	85	25	100	100	100	100		
3	6	8	9	8	100	100	100	100				
4												
5												

Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	new	new	new	new	1.5	1.5
2	new	new	new	new	1.5	1.5
3	new	new	new	new	1.5	1.5
4				16.515		
5						
Final Measurement						

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date:

Ce document peut être obtenu en français sur demande.

201-282-9190
201-282-9190

Bottom Covering

07 04 30
10 04 30
20 04 30

ANF8324DXE8001243

2 (A) 0103L 2000

DATE	TIME	LOCATION	REMARKS
11/15	11:15	100/100	100/100
11/15	11:15	100/100	100/100
11/15	11:15	100/100	100/100

20(15) 0103L 2000
20(15) 0103L 2000
20(15) 0103L 2000
20(15) 0103L 2000

DATE	TIME	LOCATION	REMARKS
11/15	11:15	100/100	100/100
11/15	11:15	100/100	100/100
11/15	11:15	100/100	100/100

DATE	TIME	LOCATION	REMARKS
11/15	11:15	100/100	100/100
11/15	11:15	100/100	100/100
11/15	11:15	100/100	100/100

DECLASSIFICATION AUTHORITY