

04063408

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Safety

Box 45064 Regent Postal Centre
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba

C048503

Date Inspection Started 13 04 26 DAY MO. YR.
Date Inspection Completed 15 04 26 DAY MO. YR.
Inspection Expiry Date 30 04 27 DAY MO. YR.

Station Number A20119 Station Name R Lewandowski Farms City
Mechanic Number M94115 Mechanic Signature Station Phone Number 204-585-2120
Vehicle Owner Balan Gravelling Inc.
Address City Province Postal Code Phone

Pass/Safe Vehicle ☒ Fail/Unsafe Vehicle ☒ Fail/Hazardous ☐
Licence Number CPV13218 Prov. MB NSC # MB1305615 Odometer Reading 651405 Odom. Type ☒ km ☐ mi
Vehicle Identification Number 2HSCNA1PR167C492424 Make Inter Model 940 Year 07 Unit #
☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GVWR KGS ☒ Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P R Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

X Section 1 - Power Train: Defects (if any)

X Section 2 Suspension: Defects (if any)

X Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type

3A(15-B) axle 2L, 3L + 3R linings worn
3A(15-D) axle 2L drum cracked

Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke "	
	L	R	L	R	L	R
1	10	10	15.045	15.045	1 1/2	1 1/2
2	new	18	new	16.575	1 1/2	1 1/2
3	new	new	16.560	16.540	1 1/2	1 1/2
4						
5						
Final Measurement						

X Section 4 - Steering: Defects (if any)

X Section 5 - Instruments & Auxiliary Equipment: Defects (if any)

X Section 6 - Lamps: Defects (if any)

X Section 7 - Electrical System: Defects (if any)

X Section 8 - Body: Defects (if any)

X Section 9 - Tire & Wheel: Defects (if any)

Axle	mm Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	8	9			80	80	100	100
2	8	9	11	11				
3	10	6	6	7	90	80	90	80
4					100	100	100	100
5					90	80	70	80
					100	100	100	100

Section 10 - Coupling Devices: Defects (if any)

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date:

PRESENT THIS COPY WHEN REGISTERING VEHICLE

Ce document peut être obtenu en français sur demande.

04063408

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba
C048503

Date Inspection Started
13 04 26
DAY MO. YR.

Date Inspection Completed
15 04 26
DAY MO. YR.

Inspection Expiry Date
30 04 27
DAY MO. YR.

Station Number
A2019

Station Name
R. Lewandowski Farms

City
St. James

Mechanic Number
M94115

Mechanic Signature
[Signature]

Station Phone Number
204-585-2220

Vehicle Owner
Balan Gravelling Inc.

Address
[Blank]

City
[Blank]

Province
[Blank]

Postal Code
[Blank]

Phone
[Blank]

☒ Pass/Safe Vehicle

☒ Fail/Unsafe Vehicle

☐ Fail/Hazardous

Licence Number
CPV328

Prov.
MB

NSC #
MB1305615

Odometer Reading
651405

Odom. Type
☐ km ☐ mi

Vehicle Identification Number
2HSCNAPR67C492424

Make
International

Model
9400

Year
07

Unit #
[Blank]

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck

GVWR
[Blank]

KGS
[Blank]

☒ Truck Tractor

☐ Trailer

☐ Semi-Trailer

☐ Bus

☐ School Bus

☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																																						
X		Section 1 - Power Train: Defects (if any)																																																																																						
X		Section 2 Suspension: Defects (if any)																																																																																						
X	X	Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type 3A(15-B) axle 2L, 3L+3R linings worn 3A(15-D) axle 2L drum cracked																																																																																						
		Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																																						
		<table><thead><tr><th rowspan="2">Axle</th><th colspan="2">Lining</th><th colspan="2">Drum/Rotor</th><th colspan="2">Stroke</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>10</td><td>10</td><td>15.045</td><td>15.045</td><td>1 1/2</td><td>1 1/2</td></tr><tr><td>2</td><td>new</td><td>18</td><td>new</td><td>16.575</td><td>1 1/2</td><td>1 1/2</td></tr><tr><td>3</td><td>new</td><td>new</td><td>16.560</td><td>16.540</td><td>1 1/2</td><td>1 1/2</td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td colspan="7">Final Measurement</td></tr></tbody></table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	10	10	15.045	15.045	1 1/2	1 1/2	2	new	18	new	16.575	1 1/2	1 1/2	3	new	new	16.560	16.540	1 1/2	1 1/2	4							5							Final Measurement																																					
Axle	Lining			Drum/Rotor		Stroke																																																																																		
	L	R	L	R	L	R																																																																																		
1	10	10	15.045	15.045	1 1/2	1 1/2																																																																																		
2	new	18	new	16.575	1 1/2	1 1/2																																																																																		
3	new	new	16.560	16.540	1 1/2	1 1/2																																																																																		
4																																																																																								
5																																																																																								
Final Measurement																																																																																								
		Section 4 - Steering: Defects (if any)																																																																																						
		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																																						
		Section 6 - Lamps: Defects (if any)																																																																																						
		Section 7 - Electrical System: Defects (if any)																																																																																						
		Section 8 - Body: Defects (if any)																																																																																						
X		Section 9 - Tire & Wheel: Defects (if any)																																																																																						
		<table><thead><tr><th rowspan="3">Axle</th><th colspan="4">Tread Depth</th><th colspan="4">Air Pressure</th></tr><tr><th colspan="2">Initial</th><th colspan="2">Corrected</th><th colspan="2">Initial</th><th colspan="2">Corrected</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>8</td><td>9</td><td></td><td></td><td>80</td><td>80</td><td>100</td><td>100</td></tr><tr><td>2</td><td>8</td><td>9</td><td>11</td><td>11</td><td>90</td><td>80</td><td>90</td><td>80</td><td>100</td><td>100</td><td>100</td><td>100</td></tr><tr><td>3</td><td>10</td><td>6</td><td>6</td><td>7</td><td>90</td><td>80</td><td>70</td><td>80</td><td>100</td><td>100</td><td>100</td><td>100</td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></tbody></table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	8	9			80	80	100	100	2	8	9	11	11	90	80	90	80	100	100	100	100	3	10	6	6	7	90	80	70	80	100	100	100	100	4													5												
Axle	Tread Depth				Air Pressure																																																																																			
	Initial			Corrected		Initial		Corrected																																																																																
	L	R	L	R	L	R	L	R																																																																																
1	8	9			80	80	100	100																																																																																
2	8	9	11	11	90	80	90	80	100	100	100	100																																																																												
3	10	6	6	7	90	80	70	80	100	100	100	100																																																																												
4																																																																																								
5																																																																																								
		Section 10 - Coupling Devices: Defects (if any)																																																																																						

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature Date: