

03965286

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba



MOC

Vehicle Standards and Inspection  
Box 45084 Regent Postal Centre  
Winnipeg, MB, R2C 5C7  
204-965-0920

Manitoba

A946548

Date Inspection Started: DAY 25, MO. 11, YR. 25  
 Date Inspection Completed: DAY 25, MO. 11, YR. 25  
 Inspection Expiry Date: DAY 30, MO. 11, YR. 26

Station Number: A1111411  
 Station Name: Bell Truck Sales Ltd  
 City: \_\_\_\_\_  
 Mechanic Number: M5338  
 Mechanic Signature: \_\_\_\_\_  
 Station Phone Number: \_\_\_\_\_  
 Vehicle Owner: Shortline Moving Solutions  
 Address: 2-47 Gomez St W, WPG, MB, R2R 0G1  
 City: \_\_\_\_\_ Province: \_\_\_\_\_ Postal Code: \_\_\_\_\_ Phone: \_\_\_\_\_

Pass/Safe Vehicle  
 Fail/Unsafe Vehicle  
 Fail/Hazardous

Licence Number: \_\_\_\_\_ Prov. \_\_\_\_\_ NSC # \_\_\_\_\_  
 Odometer Reading: \_\_\_\_\_ Odom. Type:  km  mi  
 Vehicle Identification Number: 1T1A4R7S4A1108323  
 Make: Toyota Model: Camry Year: \_\_\_\_\_ Unit #: \_\_\_\_\_  
 Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck   GWRV  KGS  Truck Tractor  Trailer  Semi-Trailer  Bus  School Bus  Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																							
X		Section 1 - Power Train: Defects (if any)																																																																							
X		Section 2 Suspension: Defects (if any)																																																																							
X	X	Section 3 - Brake Systems: 3H 3A Defects (if any): 2. front hand seals worn out Circle Brake Type: _____ Brake Inspection Type: A B C D E <table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>5/8</td> <td>5/8</td> <td>16.55</td> <td>16.55</td> <td>3/4</td> <td>1/2</td> </tr> <tr> <td>2</td> <td>5/8</td> <td>5/8</td> <td>16.55</td> <td>16.55</td> <td>2/4</td> <td>1/2</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	5/8	5/8	16.55	16.55	3/4	1/2	2	5/8	5/8	16.55	16.55	2/4	1/2	3							4							5																													
Axle	Lining			Drum/Rotor		Stroke																																																																			
	L	R	L	R	L	R																																																																			
1	5/8	5/8	16.55	16.55	3/4	1/2																																																																			
2	5/8	5/8	16.55	16.55	2/4	1/2																																																																			
3																																																																									
4																																																																									
5																																																																									
X		Section 4 - Steering: Defects (if any)																																																																							
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																							
X	X	Section 6 - Lamps: Defects (if any): 1. 2. tail light dim 1. 4. 2. R/S mid turn lights missing																																																																							
X		Section 7 - Electrical System: Defects (if any)																																																																							
X	X	Section 8 - Body: Defects (if any): 7. tarp ripped damage at multiple locations																																																																							
X		Section 9 - Tire & Wheel: Defects (if any)																																																																							
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th></th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>10/10</td> <td>8/8</td> <td></td> <td></td> <td>100/100</td> <td>100/100</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>8/8</td> <td>11/11</td> <td></td> <td></td> <td>100/100</td> <td>100/100</td> <td></td> <td></td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	10/10	8/8			100/100	100/100			2	8/8	11/11			100/100	100/100			3									4									5								
Axle	Tread Depth				Air Pressure																																																																				
	Initial		Corrected		Initial		Corrected																																																																		
	L	R	L	R	L	R	L	R																																																																	
1	10/10	8/8			100/100	100/100																																																																			
2	8/8	11/11			100/100	100/100																																																																			
3																																																																									
4																																																																									
5																																																																									
X		Section 10 - Coupling Devices: Defects (if any)																																																																							

THIS INSPECTION IS NOT A WARRANTY. This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: \_\_\_\_\_ Signature \_\_\_\_\_ Date: \_\_\_\_\_