

04147622

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

mob-2

Vehicle Safety
Box 45064 Regent Postal Office
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba

C116433

Date Inspection Started 09 DAY 09 MO. 216 YR.	Station Number A 6 5 4 7	Station Name Diesel Geek Services Inc.	City Souris, MB
Date Inspection Completed 16 DAY 09 MO. 216 YR.	Mechanic Number M 9 8 9 4	Mechanic Signature <i>[Signature]</i>	Station Phone Number 204 371 6471
Inspection Expiry Date 310 DAY 09 MO. 217 YR.	Vehicle Owner X-L Transportation		
Address City Province Postal Code Phone			

☒ Pass/Safe Vehicle ☒ Fail/Unsafe Vehicle ☐ Fail/Hazardous	Licence Number CAZ358	Prov. MB	NSC # MB0998315	Odometer Reading 434 331	Odom. Type ☒ km ☐ mi
Vehicle Identification Number 1 F D A F B 1 6 F 1 Y E A 8 3 5 3 4		Make Ford	Model F350	Year '00	Unit # —
☒ Confirmed legible Vehicle Identification Number on vehicle					

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

☒ Truck ^{GVWR} 16000 KGS ☐ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
☒		Section 1 - Power Train: Defects (if any)
☒		Section 2 Suspension: Defects (if any)
☒		Section 3 - Brake Systems: <u>3H</u> 3A Defects (if any) Circle Brake Type
☒		Section 4 - Steering: Defects (if any)
☒	☒	Section 5 - Instruments & Auxiliary Equipment: Defects (if any) 1-A - Fire extinguisher empty
☒	☒	2-A - Triangle kit missing 7-B - Wipers streaking 7-D - washers n/w
☒	☒	Section 6 - Lamps: Defects (if any) 1-B - RH headlight lense broken
☒	☒	1-C - Left tail light out
☒	☒	Section 7 - Electrical System: Defects (if any) 2-A - Connections corroded
☒	☒	2-B - Battery hold-down missing
☒		Section 8 - Body: Defects (if any)
☒		Section 9 - Tire & Wheel: Defects (if any)
☒		Section 10 - Coupling Devices: Defects (if any)

Axle	Tread Depth <u>32nd</u>				Air Pressure <u>PSI</u>			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	15	15			45	45		
2	18	18	19	19	45	45	45	45
3								
4								
5								

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: _____

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Date: _____
Signature