



Vehicle History Report #: 64863797
Report Date: October 6, 2025 | 5:13 p.m. EDT
Report Status: Complete
Reference: M06-3

2012 FORD F250 SUPER DUTY

Pickup | 8 Cylinders | Gas

1FT7X2B62CEB90205

Country of Assembly: United States

Last Reported Odometer: 252,255 KM



Accident/Damage Records Found



Last Registered In:
Saskatchewan (Normal)



57 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import/Export Records Found

Questions? We're here to help.


Visit us at support.carfax.ca




This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of October 06, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

1FT7X2B62CEB90205


Vehicle History Report



Accident/Damage


 There are no police reported accidents, estimates, or claims reported on this vehicle, however, we found other damage records that are outlined below.

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
 2014 Oct 21	Ontario, Canada	
	Damage Event: Damage reported Damage to left side	



Registration

-  This vehicle has been registered in the following locations in **Canada** (listed oldest to newest):
- In the province of **Ontario** with **Normal** branding.
 - In the province of **Saskatchewan** with **Normal** branding.

We checked for: *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2012 May 23		Service Facility Mississauga, Ontario, Canada	Vehicle serviced
2012 Nov 29		Service Facility	Vehicle serviced
2013 Apr 26	15,928 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none">• Oil and filter changed
2013 Jul 22	22,444 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none">• Tire condition and pressure checked
2013 Sep 7	26,116 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none">• Oil and filter changed• Trim checked
2013 Nov 29	33,753 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none">• Tire condition and pressure checked

1FT7X2B62CEB90205

	ODOMETER	SOURCE	DETAILS
2014 Jan 22	35,277 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2014 May 5	46,170 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2014 Nov 28	60,888 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2015 May 25	74,265 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2015 Jul 13	74,266 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Lights checked
2015 Nov 6	86,406 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Brakes checked Oil and filter changed Tire condition and pressure checked
2015 Dec 8	88,915 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Electrical system checked
2016 Apr 21	100,013 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Lights checked Oil and filter changed Tire condition and pressure checked
2016 Sep 6	111,606 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Brakes checked Electrical system checked Ignition system checked Lights checked Oil and filter changed Wheel bearing(s)/hub(s) replaced
2017 Apr 12	124,108 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2017 Apr 26		Service Facility	Vehicle serviced <ul style="list-style-type: none"> Fuel system checked Lights checked
2017 Jul 17		Service Facility	Vehicle serviced <ul style="list-style-type: none"> Trailer hitch installed
2017 Aug 11		Krown Kenora Kenora, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Undercoating/rustproofing applied
2017 Aug 23	133,643 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Electrical system checked
2017 Nov 24	138,219 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Air system checked Electrical system checked Ignition system checked Oil and filter changed Steering/suspension checked Tire condition and pressure checked

1FT7X2B62CEB90205

ODOMETER		SOURCE	DETAILS
2017 Dec 6		Service Facility	Vehicle serviced <ul style="list-style-type: none"> Tire condition and pressure checked
2018 Jan 5	138,320 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Ignition system checked
2018 Jan 13		Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Tire condition and pressure checked Tire(s) replaced
2018 Mar 21	144,973 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Tire condition and pressure checked
2018 Jun 13	156,792 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2018 Nov 27	167,336 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Cooling system checked Steering/suspension checked Wheel bearing(s)/hub(s) replaced
2019 Jan 21	167,713 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Ignition system checked
2019 Feb 25		Service Facility	Vehicle serviced <ul style="list-style-type: none"> Lights checked
2019 Jun 6	177,583 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed Steering/suspension checked
2019 Oct 9	180,679 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Air system checked Oil and filter changed
2019 Nov 22	183,042 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Axles checked Body lubricated Brakes checked Front brake pads replaced Front brake rotor(s) replaced Lights checked Parking brake system checked Parking brake shoes/pads replaced Rear brake pads replaced Rear brake rotor(s) replaced Rear wheel bearing(s)/hub seal(s) replaced Steering/suspension checked Tie rod end(s) replaced Tie rod(s) replaced Wheel bearing seal replaced Wheel bearing(s)/hub(s) replaced
2020 Oct 5	199,755 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Exhaust system checked Fuel system checked Oil and filter changed Steering/suspension checked Tire condition and pressure checked
2021 Feb 19	206,355 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Battery/charging system checked Battery replaced

1FT7X2B62CEB90205

ODOMETER		SOURCE	DETAILS
			<ul style="list-style-type: none"> Cooling system checked Fuel system checked Fuel pump module replaced Fuel pump replaced Ignition system checked Leaf spring(s) adjusted Oil and filter changed Steering/suspension checked
2021 Feb 22	207,073 KM	Service Facility	Vehicle serviced
2021 Apr 6	211,350 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2021 Apr 30	212,969 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Alternator replaced Battery/charging system checked Brakes checked Electrical system checked Tire condition and pressure checked Tire(s) balanced Tire(s) replaced
2021 Aug 4	219,769 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Tire condition and pressure checked
2021 Oct 6	221,821 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Battery/charging system checked Battery replaced Ignition system checked
2021 Nov 25	222,732 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Axles checked Electrical system checked
2022 Jan 21	222,738 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Ignition system checked
2022 Jan 24		Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Battery replaced Ignition system checked
2022 Aug 3	231,153 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> A/C and heating system checked A/C refrigerant recharged Air system checked Air filter replaced Oil and filter changed
2023 Feb 3	233,680 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Axles checked Battery/charging system checked Battery replaced Brakes checked Brake caliper(s) replaced Brake rotor(s) replaced Electrical system checked Front brake caliper(s) replaced Front brake pads replaced Front brake rotor(s) replaced Ignition system checked Oil and filter changed Steering/suspension checked Tie rod end(s) replaced

1FT7X2B62CEB90205

ODOMETER		SOURCE	DETAILS
			<ul style="list-style-type: none"> Tire rod(s) replaced Tire condition and pressure checked Tire(s) balanced Tire(s) replaced
2023 Mar 15	236,680 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Electrical system checked Ignition system checked Starter replaced
2023 Mar 30	237,175 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Electrical system checked Lights checked
2023 Jun 13	237,283 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Vehicle serviced
2023 Sep 1	238,970 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Brakes checked Fuel system checked Lights checked Steering/suspension checked
2023 Sep 28	239,709 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Tire condition and pressure checked
2024 Jan 15	243,643 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Electrical system checked No-start/hard start condition checked
2024 Mar 7	245,887 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Axles checked Brakes checked Brake rotor(s) replaced Driveshaft checked Electrical system checked Lights checked Oil and filter changed Parking brake shoes/pads replaced Rear axle oil seal replaced Rear brake pads replaced Rear brake rotor(s) replaced Rear wheel bearing(s)/hub seal(s) replaced Tire condition and pressure checked Wheel bearing seal replaced Wheel bearing(s)/hub(s) replaced
2024 May 22	250,098 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none"> A/C and heating system checked Axles checked Brakes checked Rear brake pads replaced Wheel bearing(s)/hub(s) replaced
2024 Jun 6		Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> A/C refrigerant recharged Brakes checked Brake rotor(s) replaced Parking brake system checked Parking brake shoes/pads replaced Rear axle oil seal replaced Rear brake pads replaced Rear brake rotor(s) replaced Wheel bearing(s) serviced Wheel bearing(s)/hub(s) replaced

1FT7X2B62CEB90205

ODOMETER		SOURCE	DETAILS
2024 Jun 21	250,126 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">• Brakes checked• Brake cable replaced• Brake caliper(s) replaced• Brake fluid flushed/changed• Rear brake caliper(s) replaced
2024 Jun 25	250,243 KM	Kal Tire - Kenora Kenora, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">• Tire condition and pressure checked• Tire repaired
2024 Jul 17	250,372 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">• Tire condition and pressure checked• Wheel lug nuts torqued
2024 Sep 11	252,255 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none">• Tire condition and pressure checked• Wheel lug nuts torqued



Open Recalls

✔ No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact FORD or visit [Ford's website](https://www.ford.ca/support/recalls/). (https://www.ford.ca/support/recalls/)



Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2012 Apr 26		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Fleet Vehicle colour noted as white
2012 May 23		Service Facility Mississauga, Ontario, Canada	Service Record	Vehicle serviced
2012 Oct 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Fleet
2012 Nov 29		Service Facility	Service Record	Vehicle serviced
2013 Apr 26	15,928 KM	Service Facility	Service Record	Vehicle serviced
2013 Jul 22	22,444 KM	Service Facility	Service Record	Vehicle serviced
2013 Sep 7	26,116 KM	Service Facility	Service Record	Vehicle serviced

1FT7X2B62CEB90205

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2013 Oct 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Fleet
2013 Nov 29	33,753 KM	Service Facility	Service Record	Vehicle serviced
2014 Jan 22	35,277 KM	Service Facility	Service Record	Vehicle serviced
2014 May 5	46,170 KM	Service Facility	Service Record	Vehicle serviced
2014 Oct 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Fleet
2014 Oct 21		Ontario, Canada	Damage Event	Damage reported Damage to left side
2014 Nov 28	60,888 KM	Service Facility	Service Record	Vehicle serviced
2015 May 25	74,265 KM	Service Facility	Service Record	Vehicle serviced
2015 Jul 13	74,266 KM	Service Facility	Service Record	Vehicle serviced
2015 Oct 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Fleet
2015 Nov 6	86,406 KM	Service Facility	Service Record	Vehicle serviced
2015 Dec 8	88,915 KM	Service Facility	Service Record	Vehicle serviced
2016 Apr 21	100,013 KM	Service Facility	Service Record	Vehicle serviced
2016 Sep 6	111,606 KM	Service Facility	Service Record	Vehicle serviced
2016 Oct 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Fleet
2017 Apr 12	124,108 KM	Service Facility	Service Record	Vehicle serviced
2017 Apr 26		Service Facility	Service Record	Vehicle serviced
2017 Jul 17		Service Facility	Service Record	Vehicle serviced
2017 Aug 11		Krown Kenora Kenora, Ontario, Canada	Service Record	Vehicle serviced
2017 Aug 23	133,643 KM	Service Facility	Service Record	Vehicle serviced
2017 Oct 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Fleet
2017 Nov 24	138,219 KM	Service Facility	Service Record	Vehicle serviced
2017 Dec 6		Service Facility	Service Record	Vehicle serviced
2018 Jan 5	138,320 KM	Service Facility	Service Record	Vehicle serviced
2018 Jan 13		Shane's Northern Tire & Auto Inc	Service Record	Vehicle serviced

1FT7X2B62CEB90205

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
		Kenora, Ontario, Canada		
2018 Mar 21	144,973 KM	Service Facility	Service Record	Vehicle serviced
2018 Jun 13	156,792 KM	Service Facility	Service Record	Vehicle serviced
2018 Oct 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Fleet
2018 Nov 27	167,336 KM	Service Facility	Service Record	Vehicle serviced
2019 Jan 21	167,713 KM	Service Facility	Service Record	Vehicle serviced
2019 Feb 25		Service Facility	Service Record	Vehicle serviced
2019 Jun 6	177,583 KM	Service Facility	Service Record	Vehicle serviced
2019 Oct 9	180,679 KM	Service Facility	Service Record	Vehicle serviced
2019 Nov 22	183,042 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Service Record	Vehicle serviced
2020 Oct 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Fleet Vehicle colour noted as white
2020 Oct 5	199,755 KM	Service Facility	Service Record	Vehicle serviced
2021 Feb 19	206,355 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Service Record	Vehicle serviced
2021 Feb 22	207,073 KM	Service Facility	Service Record	Vehicle serviced
2021 Apr 6	211,350 KM	Service Facility	Service Record	Vehicle serviced
2021 Apr 30	212,969 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Service Record	Vehicle serviced
2021 Aug 4	219,769 KM	Service Facility	Service Record	Vehicle serviced
2021 Oct 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Fleet Vehicle colour noted as white
2021 Oct 6	221,821 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Service Record	Vehicle serviced
2021 Nov 25	222,732 KM	Service Facility	Service Record	Vehicle serviced
2022 Jan 21	222,738 KM	Service Facility	Service Record	Vehicle serviced

1FT7X2B62CEB90205

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2022 Jan 24		Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Service Record	Vehicle serviced
2022 Aug 3	231,153 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Service Record	Vehicle serviced
2022 Oct 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Fleet Vehicle colour noted as white
2023 Feb 3	233,680 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Service Record	Vehicle serviced
2023 Mar 15	236,680 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Service Record	Vehicle serviced
2023 Mar 30	237,175 KM	Service Facility	Service Record	Vehicle serviced
2023 Jun 13	237,283 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Service Record	Vehicle serviced
2023 Sep 1	238,970 KM	Service Facility	Service Record	Vehicle serviced
2023 Sep 28	239,709 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Service Record	Vehicle serviced
2023 Oct 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Fleet
2024 Jan 15	243,643 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Service Record	Vehicle serviced
2024 Mar 7	245,887 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Service Record	Vehicle serviced
2024 May 22	250,098 KM	Service Facility	Service Record	Vehicle serviced
2024 Jun 6		Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Service Record	Vehicle serviced
2024 Jun 21	250,126 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Service Record	Vehicle serviced
2024 Jun 25	250,243 KM	Kal Tire - Kenora Kenora, Ontario, Canada	Service Record	Vehicle serviced

1FT7X2B62CEB90205

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2024 Jul 17	250,372 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Service Record	Vehicle serviced
2024 Sep 11	252,255 KM	Shane's Northern Tire & Auto Inc Kenora, Ontario, Canada	Service Record	Vehicle serviced
2024 Oct 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Fleet
2025 Sep 29		Motor Vehicle Dept. Saskatchewan, Canada	Canadian Renewal	Registration Issued or Renewed



Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

