

04098217

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba No2-1

Vehicle Safety Box 45094 Regent Postal Outlet Winnipeg, MB, R2C 5C7 1-204-985-0920

Manitoba

C035633

Date Inspection Started: 16 06 26
Date Inspection Completed: 16 06 26
Inspection Expiry Date: 30 06 27

Station Number: A60120 Station Name: 218 REPAIR LTD DOM
Mechanic Number: M94614 Station Phone Number: 204-746-4715

Vehicle Owner: ALLMENDINGER FARMS
Address: Box 9 Woodmore MB R0A 2M0

Pass/Safe Vehicle, Licence Number: L4M16120, NSC #: M41306312, Odometer Reading: 895341, Make: F.L., Model: CASCO, Year: 15

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11-Part B

Table with columns P, R and rows for Section 1-9. Includes a Brake Inspection table with columns for Axle, Lining, Drum/Rotor, and Stroke.

Tread Depth and Air Pressure table with columns for Axle, Initial, Corrected, L, R.

- THIS INSPECTION IS NOT A WARRANTY - This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle.

Vehicle received without repairs by: Signature Date: