04098218 **PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE**

Manitoba NO2-1

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

DECAL Manitoba

C035634

Date Inspection Started	16 (DAY)	06 (MO.)	26 (YR.)
Date Inspection Completed	16 (DAY)	06 (MO.)	26 (YR.)
Inspection Expiry Date	30 (DAY)	06 (MO.)	27 (YR.)

Station Number: A6070 — Station Name: 218 REPAIR LTD — City: Dominion City

Mechanic Number: M9464 — Mechanic Signature: [signature] — Station Phone Number: 204-746-4715

Vehicle Owner: ALLMENDINGER FARMS
Address: BOX 9 — City: WOODMORE — Province: MB — Postal Code: R0A 2M0 — Phone:

☒ Pass/Safe Vehicle
☒ Fail/Unsafe Vehicle
☐ Fail/Hazardous

Licence Number: TE2930 — Prov.: MB — NSC #: — Odometer Reading: — Odom. Type: km / mi

Vehicle Identification Number: 1WIMCEYA21B234001 — Make: WILSON — Model: HOPPER — Year: 01 — Unit #:

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

___Truck GVWR ___ KGS ___Truck Tractor ___Trailer X Semi-Trailer ___Bus ___School Bus ___Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		**Section 1 - Power Train:** Defects (if any)
X	X	**Section 2 Suspension:** Defects (if any) 5B AXLE 2 BOTH AIR BAGS LEAKING
X	X	**Section 3 - Brake Systems:** 3H (3A) Circle Brake Type — Defects (if any): 16D AXLE 2 RIGHT SLACK ADJUSTER INOP
X		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X		**Section 6 - Lamps:** Defects (if any)
X		**Section 7 - Electrical System:** Defects (if any)
X		**Section 8 - Body:** Defects (if any)
X		**Section 9 - Tire & Wheel:** Defects (if any)
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: A (B) C D E — Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining L	Lining R	Drum/Rotor L	Drum/Rotor R	Stroke L	Stroke R
1	15.0	18.1	16.577	16.604	1.35	1.35
2	9.7	16.1	16.605	16.594	1.35	1.35
3						
4						
5						
	Final Measurement					

Axle	Tread Depth Initial L	Tread Depth Initial R	Tread Depth Corrected L	Tread Depth Corrected R	Air Pressure Initial L	Air Pressure Initial R	Air Pressure Corrected L	Air Pressure Corrected R
1	7 6	8 7			100 100	100 100		
2	7 6	7 7			100 100	100 100		
3								
4								
5								

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature — Date: _____

FVS0022-01-(R-06/25)

Ce document peut être obtenu en français sur demande.

PRESENT THIS COPY WHEN REGISTERING VEHICLE