

03869389

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba



103-1

Vehicle Standards and Inspection
Box 45064, Regent Forest Centre
Winnipeg, MB, R2C 9C7
1-204-955-0520

Manitoba



A859095

Date Inspection Started: 20 DAY, 12 MO, 24 YR

Date Inspection Completed: 02 DAY, 01 MO, 25 YR

Inspection Expiry Date: 31 DAY, 01 MO, 26 YR

Station Number: A00001 Station Name: A. Netherland Transport Ltd.

Mechanic Number: M9339 Mechanic Signature: [Signature] Station Phone Number: 204-227-2671

Vehicle Owner: ANIL Leasing Ltd.

Address: Box 40022 Leguminaire P.O. Winnipeg MB R2C 4P3 City: Winnipeg Province: MB Postal Code: R2C 4P3 Phone: [Blank]

☒ Pass/Safe Vehicle ☒ Fail/Unsafe Vehicle ☐ Fail/Hazardous

Licence Number: CIRIN232 Prov: MB NSC #: MB9000042 Odometer Reading: 533,131 Odometer Type: ☒ km ☐ mi

Vehicle Identification Number: 1X1PISDIB91X1X17IN1J1S1919 Make: Petrol Model: 379 Year: 2007 Unit #: 11

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☒ KGS ☒ X Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		Section 1 - Power Train: Defects (if any)
X		Section 2 Suspension: Defects (if any) 4c Axle 1 shock absorbers and bushings worn
X	X	Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type 16H Axle 3 R side brake stroke out of adjustment 14b Axle 2 R side spring broken inside brake chamber 15b Axle 2 L side shoes grease contaminated 15h Axle 2+3 Brake spider anchor pins worn
X		Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X		Section 6 - Lamps: Defects (if any)
X		Section 7 - Electrical System: Defects (if any)
X		Section 8 - Body: Defects (if any)
X	X	Section 9 - Tire & Wheel: Defects (if any) 5c Axle 2 R side wheel seal leaking
X		Section 10 - Coupling Devices: Defects (if any)

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	18	18			120	120		
2	12	12	10	10	105	105	105	105
3	13	13	14	14	105	105	105	105
4								
5								

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date:

FV50022-01-(R-09/15)

Ce document peut être obtenu en français sur demande.