

C027951

Date Inspection Started: DAY 19, MO. 11, YR. 25  
 Date Inspection Completed: DAY 20, MO. 11, YR. 25  
 Inspection Expiry Date: DAY 30, MO. 11, YR. 26

Station Number: [ ] Station Name: [ ] City: [ ]  
 Mechanic Number: [ ] Mechanic Signature: [ ] Station Phone Number: 325-5786

Vehicle Owner: [ ]  
 Address: [ ] City: [ ] Province: [ ] Postal Code: [ ] Phone: [ ]

Pass/Safe Vehicle  
 Fail/Unsafe Vehicle  
 Fail/Hazardous

License Number: TA3659 Prov. MB NSC # [ ] Odometer Reading: [ ] Odom. Type:  km  mi  
 Vehicle Identification Number: 2L1D1A151C371E1015911014 Make: [ ] Model: ANU Year: 15 Unit #: 307  
 Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck  GVWR [ ] KGS  Truck Tractor  Trailer  Semi-Trailer  Bus  School Bus  Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																														
X		Section 1 - Power Train: Defects (if any)																																																														
X		Section 2 Suspension: Defects (if any)																																																														
X	X	Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type 19B - AXLE 1 (LH + RH) Brake oil Spring broken 15C - AXLE 2 (LH + RH) Brake fluid Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection <table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>1 1/16</td> <td>5/8</td> <td>16.545</td> <td>16.551</td> <td>1</td> <td>1</td> </tr> <tr> <td>2</td> <td>1 1/16</td> <td>7/8</td> <td>16.546</td> <td>16.500</td> <td>1</td> <td>1</td> </tr> <tr> <td>3</td> <td>3/4</td> <td>7/8</td> <td>16.531</td> <td>16.500</td> <td>1</td> <td>1</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table> Final Measurement	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	1 1/16	5/8	16.545	16.551	1	1	2	1 1/16	7/8	16.546	16.500	1	1	3	3/4	7/8	16.531	16.500	1	1	4							5																				
Axle	Lining			Drum/Rotor		Stroke																																																										
	L	R	L	R	L	R																																																										
1	1 1/16	5/8	16.545	16.551	1	1																																																										
2	1 1/16	7/8	16.546	16.500	1	1																																																										
3	3/4	7/8	16.531	16.500	1	1																																																										
4																																																																
5																																																																
X		Section 4 - Steering: Defects (if any)																																																														
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																														
X	X	Section 6 - Lamps: Defects (if any) LH - front left marker light out																																																														
X		Section 7 - Electrical System: Defects (if any)																																																														
X		Section 8 - Body: Defects (if any)																																																														
X		Section 9 - Tire & Wheel: Defects (if any)																																																														
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>12</td> <td>12</td> <td>13</td> <td>12</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>2</td> <td>10</td> <td>9</td> <td>10</td> <td>11</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td>9</td> <td>11</td> <td>13</td> <td>14</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		1	12	12	13	12	100	100	100	100	2	10	9	10	11	100	100	100	100	3	9	11	13	14	100	100	100	100	4									5								
Axle	Tread Depth				Air Pressure																																																											
	Initial		Corrected		Initial		Corrected																																																									
1	12	12	13	12	100	100	100	100																																																								
2	10	9	10	11	100	100	100	100																																																								
3	9	11	13	14	100	100	100	100																																																								
4																																																																
5																																																																
X		Section 10 - Coupling Devices: Defects (if any)																																																														

- THIS INSPECTION IS NOT A WARRANTY -  
 This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: [ ]

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature [ ] Date: [ ]